

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20002128/T1KA3Q2**Date:** 23/06/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800007615
Claimant
Vehicle No : FBJ5956H **Insured Vehicle No :** SLW2265B
Date of Loss: 19/01/2020 Nature of Claim: TP Claim No: 1300891122SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBJ5956H**
Make & Model: HONDA CB400X, 399cc Engine No: NC47E1004451
Reg. Date: 31/07/2014 (Man. Year: 2014) Chassis No: NC471004510
Colour: Grey Odometer: 119369 km
Engine Capacity: 399 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 120/70 R17 Rear Tyre Size: 160/60 R17
Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm
Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,253.00	4,052.70	1,200.30	22.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	580.00	360.00	220.00	37.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,833.00	4,412.70	1,420.30	24.35
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	5,833.00	3,500.00	2,333.00	40.00
+ Loss of Use (4.0 x S\$35.00/day) (S\$)		140.00		
		3,640.00		

INSPECTION

Date of Assignment: 06/02/2020
Date Inspected: 07/02/2020 Inspected At: Pang Scooter Service (HQ)
BLK 1006 BUKIT MERAH LANE 2
#01-06
Singapore 159762
Estimated Period of Repair: 4.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	185.00 F	*185.00 FL
2	1		*WINDSHIELD	Cracked	285.00 F	*285.00 FL
3	1		*WINDSHIELD BRACKET	Not Necessary	185.00 F	*- FL
4	1		*TOP CLAMP	Bent	250.00 F	*250.00 FL
5	1		*STEERING CON	Not Necessary	120.00 F	*- FL
6	1		*UNDER BRACKET	Not Necessary	395.00 F	*- FL
7	1		*BRAKE DISC	Bent	285.00 F	*285.00 FL
8	1		*BRAKE LEVER	Not Necessary	50.00 F	*- FL
9	1		*RIGHT HAND FRONT FOOT REST	Cut	85.00 F	*85.00 FL
10	1		*RIGHT HAND FRONT FOOT BRACKET	Bent	185.00 F	*185.00 FL
11	1		*BRAKE PEDAL	Bent	75.00 F	*75.00 FL
12	1		*MUFFLER ASSY	Dented	980.00 F	*980.00 FL
13	1		*MUFFLER JOINT GASKET	Necessary	48.00 F	*48.00 FL
14	1		*REAR WHEEL RIM	Bent	795.00 F	*795.00 FL
15	1		*REAR BOX	Dented	485.00 F	*485.00 FL
16	1		*CRASH BAR	Bent	385.00 F	*385.00 FL
17	1		*RIGHT HAND MIRROR	Cut	95.00 F	*95.00 FL
18	1		*HANDGUARD RH (NPA)	Not Necessary	0.00 F	*- FL
19	1		*HANGUAR R/H	Cut	185.00 F	*185.00 FL
20	1		*FORK LIGHT R/H	Cracked	180.00 F	*180.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	5,253.00	4,503.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	450.30
Total Parts (\$)	5,253.00	4,052.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT	New	80.00	60.00
2	LABOUR	New	500.00	300.00
Gross Labour Cost (\$)			580.00	360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >