

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

JESRAY COACH TRANSPORT
BLK 725 JURONG WEST AVE 5 #06-124
SINGAPORE 640722

TPM
Cecilia

Contact : 83883279

ESTIMATE

Repair Code : CLM16025

Date in : 05/02/2020

Vehicle Num. : PC3702H

Model : TOYOTA HIACE COMMUTER 3.0 GL AT 2WD 4DR LWB

Chassis/Eng# : KDH2230023443/1KD2500862

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT AIR CLEANER BOX <i>Cracked.</i>	1	972.85	691 972.85
FRONT AIR CLEANER BOX HOSE <i>Deformed.</i>	1	177.25	✓ 177.25
FRONT BUMPER <i>Distorted</i>	1	498.90	✓ 498.90
FRONT BUMPER LOWER GRILLE <i>Deformed</i>	1	198.50	✓ 198.50
FRONT BUMPER REINFORCEMENT <i>Best</i>	1	418.70	✓ 418.70
FRONT BUMPER REINFORCEMENT BRACKET <i>Best</i>	1	125.10	✓ 125.10
FRONT BUMPER REINFORCEMENT SIDE BRACKET (VERTICAL) <i>Not in</i>	1	121.10	X 121.10
FRONT BUMPER SIDE RETAINER L/R <i>Not in</i>	2	139.60	129.60 279.20
FRONT BUMPER TOW HOOK COVER <i>Not in</i>	1	60.80	X 60.80
FRONT GRILLE <i>Not in</i>	1	580.30	X 580.30
FRONT GRILLE OUTER COVER (LOWER) <i>Cracked</i>	1	279.70	✓ 279.70
FRONT GRILLE OUTER COVER (TOP)	1	280.20	✓ 280.20
FRONT RH BUMPER FOGLAMP <i>cut</i>	1	289.90	✓ 289.90
FRONT RH BUMPER FOGLAMP GARNISH <i>Cracked</i>	1	80.80	✓ 80.80
FRONT RH DOOR WIRE GARNISH COVER <i>Cracked</i>	1	98.70	✓ 98.70
FRONT RH HEADLAMP (L.E.D) <i>Cracked</i>	1	1680.30	✓ 1,680.30
FRONT RH STEP GARNISH <i>to be</i>	1	289.90	✓ 289.90

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

JESRAY COACH TRANSPORT
BLK 725 JURONG WEST AVE 5 #06-124
SINGAPORE 640722

Contact : 83883279

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE

Repair Code : CLM16025

Date in : 05/02/2020

Vehicle Num. : PC3702H

Model : TOYOTA HIACE COMMUTER 3.0 GL AT 2WD 4DR LWB

Chassis/Eng# : KDH2230023443/1KD2500862

				Subtotal before discount	6,432.20
					1,608.05
Percentage discount	25%	5248.55			
		3936.41		Sub-total 1	4,824.15
FRONT BUMPER CLIPS - SET	NOV		1	80.00	30 80.00
FRONT BUMPER LOWER SPOILER	Deformed		1	920.00	700 920.00
FRONT GRILLE CLIPS - SET	NEW		1	50.00	1 50.00
FRONT RH BUMPER CHROME COVER	CRACKED		1	350.00	200 350.00
FRONT RH BUMPER FOGLAMP GARNISH CHROME	CRACKED	1030	1	200.00	80 200.00
FRONT RH HEADLAMP CLIPS - SET	NEW		1	25.00	10 25.00
FRONT RH STEP GARNISH CLIPS - SET	NEW		1	25.00	10 25.00
				Subtotal before discount	1,650.00
Percentage discount	0%				0.00
				Sub-total 2	1,650.00
				Parts-total	6,474.15

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

2,020.00

8,494.15

total: 6096.41
L/S: 4.81C 042yp.