

ASS. REC. BY:

REF:

CS/CAI2000237/14/2.

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBO 28014

Yr Regn:

08, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Itaque

c.c

2982

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

76675

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JT1H702P800146706

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: M/L/S/Rlm / STD A/Rlm or

Tyre Size:

F:

1P5R15X8

R:

BS/DUN/EXNOVA/GY/FS/LIZA/MIC/OHTSU/PIR/SUMI/

TOYO/YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

16/8/1P

D.O.I.

17/2/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

fill pass to typist

RECEIVED 27 FEB 2020

Amend report to cost plus 15% instead of 20%. Close 18/3/2020
20/3/2018 close date 28/3/20, reopen ref only.

Date/Time, File Pass to?

☐

: Prell. Report

☒

: Final Report

Date/Time, File Return to?

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

290

Transportation

S - F.S. SI

P. F. S.

Others

TOTAL

290

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

TP

Lump Sum / I.B.I. (\$

2100/-

Denise Tay (LKKAuto)

From: Motor Claims <motorclaims@sg.gaig.com>
Sent: Monday, 16 March 2020 4:15 PM
To: SUR; Reports (LKKAuto)
Subject: FW: Survey Report & Invoice of Vehicle GBD 2801Y Ref: CLMOMVC000003707
Attachments: LKKInvoice-GBD 2801Y.pdf; GA Authorised Workshop Agreement .pdf

Follow Up Flag: Follow up
Due By: Tuesday, 17 March 2020 8:30 AM
Flag Status: Flagged

Hi Elaine

For TPD, it should be costs plus 15% not 20%. Please refer Page 3 of the signed agreement with our authorized workshop.

Please revise your report and ensure workshop repair cost is amended accordingly.

Regards
Sharon
Great American

From: Elaine (LKK Auto) <report@lkkauto.com>
Sent: 28 February 2020 3:57 PM
To: Wong, Shery <shery.wong@sg.gaig.com>
Cc: Motor Claims <motorclaims@sg.gaig.com>; Ng, Sharon <sharon.ng@sg.gaig.com>; 'SUR' <sur@lkkauto.com>
Subject: [External] Survey Report & Invoice of Vehicle GBD 2801Y Ref: CLMOMVC000003707

Dear Sir / Madam,

Enclose Survey Report of GBD 2801Y.

Thank you.

Best Regards,

Elaine | Reports

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Ext.111 Fax: 6741-4108 email: report@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 Singapore 408933



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2801Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH TAILLAMP (WCP)	CUT	95.00	95.00
1	REAR RH FENDER (WCP)	BENT	590.00	590.00
	COST PLUS 20%		137.00	137.00
			822.00	822.00
	<u>LABOUR</u>			
	REMOVE & REFIX RH TAILGATE, RH SLIDING DOOR, SLIDING DOOR TRUCK, CUT, WELD & RENEW REAR RH SIDE PANEL, KNOCK & REPAIR RH SLIDING DOOR & REALIGN THE SAME.		1,200.00	900.00
	REMOVE & REFIX TOP ROOF LINING, GARNISH, ETC.		80.00	60.00
	PUTTY & RESPRAY ON REAR RH SIDE PANEL.		600.00	500.00
	TO REWRITE ADVERTISEMENT.		450.00	350.00
	RUSTPROOFING.		30.00	30.00
			2,360.00	1,840.00
	GRAND TOTAL		3,182.00	2,662.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CS/GAI20002137/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref : CS/GAI20002137/Ktf3e2	
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190			Date : 28-02-2020	
			Code : GAI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YP 9452P	Veh. Inspected	GBD 2801Y	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003707	Excess (\$)	0.00	
Assign From	SHERY WONG	Assign Date	06/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	JTFHT02P600146706	Colour	WHITE	
Odometer	76675	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15X8	BRIDGESTONE	6 mm	
L/H Front Tyre	195 R15X8	BRIDGESTONE	6 mm	
R/H Rear Tyre	195 R15X8	BRIDGESTONE	6 mm	
L/H Rear Tyre	195 R15X8	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/08/2019	Inspection Date	17/02/2020	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO CHECK WIRING.		80.00	30.00
	TOWING CHARGE.		100.00	60.00
	TO DISMANTLE & REPLACING ODC SENSOR.		100.00	50.00
	TO TRANSFER BOOTLID MECHANISM.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX REAR EXHAUST.		180.00	80.00
	TO DISMANTLE & REPLACING FRONT UNDERCARRIAGE.		380.00	150.00
	TO REFILL AIR CON GAS.	NOT NECESSARY	150.00	-
	TO RESET & REPROGRAM HEADLAMP SYSTEM.		150.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.		120.00	60.00
	TO SPRAY RUST PROOFING.		180.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF BOOTLID AND REAR EXHAUST ASSY.		2,200.00	1,200.00
	TO PUTTY & SPRAY PAINTING.		2,500.00	1,600.00
			6,240.00	3,340.00
	GRAND TOTAL		50,711.32	22,164.73

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			17,500.00
---	--	--	------------------

Report Ref No. CC6/EQ19019067/Upa3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 2801Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH TAILLAMP (WCP)	CUT	95.00	95.00
1	REAR RH FENDER (WCP)	BENT	590.00	590.00
	COST PLUS 15%		-	102.75
	COST PLUS 20%		137.00	-
			822.00	787.75
	<u>LABOUR</u>			
	REMOVE & REFIX RH TAILGATE, RH SLIDING DOOR, SLIDING DOOR TRUCK, CUT, WELD & RENEW REAR RH SIDE PANEL, KNOCK & REPAIR RH SLIDING DOOR & REALIGN THE SAME.		1,200.00	900.00
	REMOVE & REFIX TOP ROOF LINING, GARNISH, ETC.		80.00	60.00
	PUTTY & RESPRAY ON REAR RH SIDE PANEL.		600.00	500.00
	TO REWRITE ADVERTISEMENT.		450.00	350.00
	RUSTPROOFING.		30.00	30.00
			2,360.00	1,840.00
	GRAND TOTAL		3,182.00	2,627.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CS/GAI20002137/Ktf3e2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.