



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SKX2460K TOYOTA COROLLA ALTIS-1.6 (A)

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1000.00	200
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	200
3	To remove and re-fix wiring and check all electrical components	150.00	X 111
4	To provide anti-rust treatment on affected area	150.00	X 111
5	To remove, refix, and focus headlamp	150.00	X 111
Labour Total :		2250.00	
TOTAL (PARTS & LABOUR):		3392.50	

400

285

30

400

715

208

572

45-550

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rashid
Hp 90010068

2 days
C/S

10/02/2020 @ 1555

Resurvey before paint



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SKX2460K TOYOTA COROLLA ALTIS-1.6 (A)

Vehicle No.		SKX2460K TOYOTA COROLLA ALTIS-1.6 (A)		
QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)		Less 25%	380.00	/
1	Front bumper cut /		140.00	
1	Front fender innershield RH Xnn		560.00	
1	RH headlamp Xnn		220.00	
1	Fog lamp RH Xnn		150.00	
1	Fog lamp cover RH Xnn			
			1450.00	
			362.50	
			1087.50	
SPECIAL NETT ITEMS				
1	Front bumper clips ha /	30.00	/	
1	Front innershield clips Xnn	25.00		
Total Parts			1142.50	

380

257

285

30