

Individual Statement Pg. 1

13-12-19:15:20 ; KAN FOOK SING MOTOR WORKSHOP

:+65 6481 8683

2/ 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Kallang Airport Way.

I was about to enter the tunnel and I stopped when I realised I was in the wrong direction but then I decided to drive forward but I used reversed gear instead I hit onto vehicle behind me

1. I HEREBY DECLARE that

1. The reporting officer has explained the above statement & sketch plan to me

2. I fully understand and agree with the above statement

3. The information given is true and correct to best of my/our knowledge and belief.

Name: [Signature] & Company Stamp (if applicable)

DECLARATION

I/We declare the foregoing particulars are true in all respects.

X

Policyholder's Signature

Date & Time:

1558

Driver's Signature

(If driver is not the policyholder)

Date & Time: 13/12/2019


Reporting Centre Personnel's Signature

Name:


NRIC/FIN No.:

STAMP HERE (Reporting Centre)


Accident Photo



Accident Photo



Accident Photo



Accident Photo



Accident Photo




Accident Photo



13 Dec 2019 09:25:42



13 Dec 2019 09:24:56



13 Dec 2019 09:16:37



accident scene photos



accident scene photos



13 Dec 2019 09:16:27



13 Dec 2019 09:16:21




accident scene photos



accident scene photos





K A A S
kelvin automotive appraising services

6 tampines st 73, #01-03, singapore 528825
tel: 6746 2118 fax: 6746 1148
reg no: 53058468m

Claim Reference : -
Insured Vehicle No. : -
Thirty Party Veh No. : -
Officer-In-Charge : -

Our Reference : KAAS/TA/5808/5844/TP/12.19
Date : 05 January 2020

To: Favourite Car Rental Pte Ltd
c/o 25 Kaki Bukit Road 4
#01-55, Synergy @ Kaki Bukit
Singapore 417800

VEHICLE APPRAISAL REPORT

Name of Workshop : Apex Motoring
Place of inspection : 25 Kaki Bukit Road 4 #01-55, Synergy @ Kaki Bukit, Singapore 417800
Date of Assignment : 17 December 2019
Date of Accident : 13 December 2019
Date of inspection : 17 December 2019

PARTICULARS OF INSPECTED VEHICLE

Registration No.	: SMN 5844X	Chassis Frame No.	: GP7-2002487
Make / Model	: Honda Shuttle Hybrid 1.5(A)	Engine No. (Logcard)	: LEB7103295
Year of Manufacture/Reg	: 2019	Odometer Reading	: 50,927 KM
Colour	: Silver		
Class / Type	: MPV		1796 cc

CONDITION OF VEHICLE DURING SURVEY (Visual & Static Check Only)

General Condition : Excellent
Paintwork : Excellent
Market Value : -
Scrap Value : -

CONDITION OF TYRES ON VEHICLE

	<u>Make/Size</u>	<u>Thread Balance</u>
Front L	KUMHO 185 / 60 R15	8 mm
Front R	KUMHO 185 / 60 R15	8 mm
Rear L	KUMHO 185 / 60 R15	8 mm
Rear R	KUMHO 185 / 60 R15	8 mm

*The above is an estimate of the remaining life of the tyre thread in millimeters

The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this survey report in error, please contact us immediately by phone so that we can arrange for its return.



6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m

Our Reference : KAAS/TA/5808/5844/TP/12.19
 Vehicle Number : SMN 5844X

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
LIST ITEMS:-					
1	1 pc	front bumper	deformed	\$ 1,050.00	\$ 1,050.00
2	1 pc	front bumper reinforcement	buckled	\$ 420.90	\$ 420.90
3	1 pc	front bumper l/h side retainer	necessary	\$ 47.00	\$ 47.00
4	1 pc	front bumper r/h side retainer	necessary	\$ 47.00	\$ 47.00
5	1 set	front bumper clips	necessary	\$ 35.00	\$ 35.00
6	1 pc	front grille	broken	\$ 395.00	\$ 395.00
7	1 pc	front grille ctr chrome moulding	necessary	\$ 302.50	\$ 302.50
8	1 pc	front grille lwr chrome moulding	necessary	\$ 230.70	\$ 230.70
9	1 pc	front logo emblem	necessary	\$ 23.40	\$ 23.40
10	1 pc	front support top panel	buckled	\$ 637.00	\$ 637.00
11	1 pc	l/h headlamp	broken	\$ 2,250.00	\$ 2,250.00
12	1 pc	r/h headlamp	broken	\$ 2,250.00	\$ 2,250.00
13	1 pc	bonnet	buckled	\$ 560.80	\$ 560.80
14	1 pc	bonnet inner lock	shifted	\$ 112.00	realign
15	1 pc	l/h front fender	buckled	\$ 489.20	\$ 489.20
16	1 pc	r/h front fender	buckled	\$ 489.20	\$ 489.20
17	1 pc	l/h front fender " hybrid " emblem	necessary	\$ 39.70	\$ 39.70
18	1 pc	r/h front fender " hybrid " emblem	necessary	\$ 39.70	\$ 39.70
				\$ 9,419.10	\$ 9,307.10
Less 20%					\$ 1,861.42
				\$ 9,419.10	\$ 7,445.68
Sub - Total				\$ 9,419.10	\$ 7,445.68

SKC
30
x R
x R

7902.89
- 20%
6322.74



6 tampines st 73, #01-03, singapore 528825
 tel: 6746 2118 fax: 6746 1148
 reg no: 53058468m


Our Reference : KAAS/TA/5808/5844/TP/12.19
 Vehicle Number : SMN 5844X

APPRAISEMENT SCHEDULE

S/N	Qty	Descriptions	Conditions	Repairer's Estimate	Revised Amount
		B/F		\$ 9,419.10	\$ 7,445.68
		LABOUR & OTHER CHARGES:-			
1		To panel beat and renewal of all necessary damaged body parts		\$ 1,400.00	\$ 1,200.00
2		To realign headlamp focus		\$ 35.00	\$ 20.00
3		To check wiring and rewire		\$ 60.00	\$ 50.00
4		To remove and reinstall radiator and a/c condenser		\$ 160.00	\$ 120.00
5		To vacuum and refill a/c refrigerant		\$ 120.00	\$ 100.00
6		To apply anti-rust		\$ 120.00	\$ 100.00
7		To putty and spray-paint of affected areas		\$ 1,200.00	\$ 1,000.00
				\$ 3,095.00	\$ 2,590.00
		6 repair rlys		P-6322.24 L-1680 8002.24 L/S-6401.79 = 6400	800 / 30 X X 30 800 1680
Sub - Total				\$ 12,514.10	\$ 10,035.68

ASSESSMENT SUMMARY

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered **Squarely to the Front** portion of the vehicle.



The general area of damages is at the **Front portion**
(Please refer to the parts list and photographs as attached for more information)

ASSESSOR'S RECOMMENDATIONS

The estimated repair costs submitted by Messrs **Apex Motoring** is \$ 12,514.10 .
We have adjusted the cost to \$ 10,035.68 and the repairer has agreed to undertake the repairs at a **Contract Lump Sum of \$ 8,000.00** to a acceptable quality and standards.
However, we have not given authorization and instruction to the repairer to proceed with the repairs.

The repairs should be completed within a reasonable period of **7** working days.

66 photographs were taken at the time of static inspection.

This report is strictly done in a **Without Prejudice Basis**.

We are reverting the matter to you a decision.

We enclose herewith our Invoice No. **5808** for our services rendered and we thank you for engaging our services.

Conducted By :



TERRENCE HONG
Dip Engineering / DECC (SP)
Certs Automotive Technology (NP)
Cert. Crash Investigation & Reconstruction
Cert SCI (General Insurance)
AMSAAA, AM SAE-A

Approved By :



KELVIN TEO
Licensed Automotive Appraiser
Nitec in Automotive Technology
Cert. Crash Investigation & Reconstruction
Dip MS
MSAAA, AM SAE-A

NOTE : This revised estimate was from a visual inspection. Should there be any discrepancy or unseen items not listed in this survey, kindly notify the company within Seven (7) days from the date hereof. Otherwise this revised amount shall be treated as valid.



Your Ref: 19/19/19/VC05/022786

Date: 13th February 2020

Our Ref: CS1/LPC20002155/Eyf3s2

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMN 5844X
INSURED VEHICLE: YN 3998G ACCIDENT DATE: 13/12/2019**

We thank you for your instruction on 07/02/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMN 5844X from M/s Kelvin Automotive Appraising Services.
- b) Singapore Accident Statement of Vehicles SMN 5844X and YN 3998G.
- c) Colour damaged vehicle photographs of SMN 5844X.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMN 5844X
Make & Model	: Honda Shuttle Hybrid 1.5(A)
Year of Registration	: 2019
Chassis Number	: GP72002487
Engine Capacity	: 1496 cc

2. We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 5844X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DEFORMED	1,050.00	1,050.00
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	420.90	-
1	FRONT BUMPER L/H SIDE RETAINER	NECESSARY	47.00	47.00
1	FRONT BUMPER R/H SIDE RETAINER	NECESSARY	47.00	47.00
1	SET FRONT BUMPER CLIPS	NECESSARY	35.00	30.00
1	FRONT GRILLE	BROKEN	395.00	395.00
1	FRONT GRILLE CHROME MOULDING	NECESSARY	302.50	302.50
1	FRONT GRILLE LWR CHROME MOULDING	NECESSARY	230.70	230.70
1	FRONT LOGO EMBLEM	NECESSARY	23.40	23.40
1	FRONT SUPPORT TOP PANEL	BUCKLED	637.00	637.00
1	L/H HEADLAMP	BROKEN	2,250.00	2,250.00
1	R/H HEADLAMP	BROKEN	2,250.00	2,250.00
1	BONNET	BUCKLED	560.80	560.80
1	BONNET INNER LOCK	SHIFTED	112.00	-
1	L/H FRONT FENDER	TO REPAIR SEE LABOUR	489.20	-
1	R/H FRONT FENDER	TO REPAIR SEE LABOUR	489.20	-
1	L/H FRONT FENDER "HYBRID" EMBLEM	NECESSARY	39.70	39.70
1	R/H FRONT FENDER "HYBRID" EMBLEM	NECESSARY	39.70	39.70
	LESS 20% DISCOUNT		-	-1,580.56
			9,419.10	6,322.24
LABOUR				
	TO PANEL BEAT AND RENEWAL OF ALL NECESSARY DAMAGED BODY PARTS. INCLUSIVE OF THE REPAIR OF L/H FRONT FENDER AND R/H FRONT FENDER.		1,400.00	800.00
	TO REALIGN HEADLAMP FOCUS.		35.00	20.00
	TO CHECK WIRING AND REWIRE.		60.00	30.00
	TO REMOVE AND REINSTALL RADIATOR AND A/C CONDENSER.	NOT NECESSARY	160.00	-
	TO VACUUM AND REFILL A/C REFRIGERANT.	NOT NECESSARY	120.00	-
	TO APPLY ANTI-RUST.		120.00	30.00
	TO PUTTY AND SPRAY-PAINT OF AFFECTED AREAS.		1,200.00	800.00
			3,095.00	1,680.00
GRAND TOTAL			12,514.10	8,002.24

Report Ref No. CS1/LPC20002155/Eyf3s2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,400.00
---	--	--	----------

Report Ref No. CS1/LPC20002155/Eyf3s2

CHEN TSUE YEE
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.