

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: AEMD/105/009/2018/178

Date: 14th February 2020

Our Ref: CS1/SPF20002168/R1sf3s2

## M/s Automotive Engineering & MGT Division

Accident Claims Section (Singapore Police Force)
Police Logistics Base (PLB)
1 Hemmant Road
Singapore 438675

Attn: Frankie Thay

Dear Sir / Madam,

## EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLT 6955H INSURED VEHICLE: QX 290B ACCIDENT DATE: 19/11/2018

We thank you for your instruction on 07/02/2020.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLT 6955H from M/s AXA Insurance.
- b) Singapore Accident Statement of Vehicle SLT 6955H.
- c) Colour damaged vehicle photographs of SLT 6955H.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

: SLT 6955H

Make & Model

: Toyota Harrier

Year of Registration

: 2017

Chassis Number

: JTEKB3GH80J000513

**Engine Capacity** 

: 1998 cc

- We recommend that the repairs of the entire damage require about 6 (Six) working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.