

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002182/UEA3N2

Date: 20/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100479808

Claimant
Vehicle No : SMQ3734C **Insured Vehicle No :** SLF5321S

Date of Loss: 05/02/2020 Nature of Claim: TP Claim No: 6353347039SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMQ3734C		
Make & Model:	TOYOTA PRIUS PLUS, 1.8 (A)	Engine No:	2ZR0E80576
Reg. Date:	13/11/2019 (Man. Year: 2019)	Chassis No:	JTDZS3EU60J052175
Colour:	White	Odometer:	23952 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Yokohama 7 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Yokohama 7 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,995.47	4,677.55	1,317.92	21.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,460.00	1,650.00	810.00	32.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,455.47	6,327.55	2,127.92	25.17
Approved Total (Overridden) (\$\$)		5,050.00		
(\$\$)	8,455.47	5,050.00	3,405.47	40.28
+ GST 7.00/7.00% (\$\$)	591.88	353.50	238.38	40.28
Nett Amount (\$\$)	9,047.35	5,403.50	3,643.85	40.28
+ Loss of Use (7.0 x S\$80.00/day) (\$\$)		560.00		
+ Doc/Search Fee (\$\$)		31.00		
Nett Liability (\$\$)		5,994.50		

INSPECTION

Date of Assignment: 07/02/2020

Date Inspected: 07/02/2020 Inspected At:

Focus Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #02-48/50 Autobay
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Badly Dented	1,096.00 FL	*1,096.00 FL
2	1		*REAR BOOT LOCK	Dented /Shorted	495.00 FL	*495.00 FL
3	1		*REAR BOOT RUBBER	Twisted	289.20 FL	*289.20 FL
4	1		*REAR BOOT EMBLEM (HYBRID)	Necessary	65.90 FL	*65.90 FL
5	1		*REAR BOOT EMBLEM (PRIUS)	Necessary	85.90 FL	*85.90 FL
6	1		*REAR BOOT CENTRE GARNISH	Not Necessary	561.90 FL	*- FL
7	1		*REAR BOOT INNER COVER BOARD	Deformed / Torn	505.40 FL	*505.40 FL
8	2		*REAR BOOT SHOCK ABSORBER	Not Necessary	843.80 FL	*- FL
9	1		*REAR TAIL LAMP -RH	Cracked	695.90 FL	*695.90 FL
10	1		*REAR END PANEL	Dented / Bent	596.20 FL	*596.20 FL
11	1		*REAR BUMPER	Distorted	981.70 FL	*981.70 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	495.20 FL	*495.20 FL
13	1		*REAR BUMPER LOWER SPOILER	Distorted	367.40 FL	*367.40 FL
14	1		*REAR BUMPER TOP PROTECTOR	Necessary	223.65 FS	*100.00 FS
15	1		*REAR BUMPER REINFORCEMENT BRACKET O/S	Bent	109.60 FL	*109.60 FL
16	1		*SET REAR WINDSCREEN GUM	Necessary	80.00 FS	*40.00 FS
17	1		*SET REAR BUMPER SENSOR	Shorted	300.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **7,792.75** **6,123.40**
- List Item Discount on L Items 25.00/25.00% (\$\$) 1,797.28 1,445.85

Total Parts (\$\$) **5,995.47** **4,677.55**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	600.00
2	CHECK WIRING	New	60.00	20.00
3	RUST PROOFING	New	60.00	60.00
4	TO REMOVE & REFIT REAR WINDSCREEN	New	160.00	120.00
5	TO REMOVE & REPLACE BUMPER SENSOR	New	80.00	50.00
6	TO SPRAY PAINT	New	900.00	800.00
Gross Labour Cost (\$)			2,460.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >