



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2004392
INV Date 19/06/2020
Reference CC6/EQI20002184/Gpa3s2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SLV 2075M
Insured Veh. GBH 806B
Claim No.
Policy No. DMCPHQ19-002521
Accident Date 09/01/2020
Inspection Date 07/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQI20002184/Gpa3s2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 19-06-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 806B	Veh. Inspected	SLV 2075M
Policy No.	DMCPHQ19-002521	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	07/02/2020

2. Vehicle Particulars & Condition

Make & Model	BLUECAR	c.c	0
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VL4BCEB4RHT003092	Colour	WHITE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65 R15	MICHELIN	5 mm
L/H Front Tyre	175/65 R15	MICHELIN	5 mm
R/H Rear Tyre	175/65 R15	MICHELIN	5 mm
L/H Rear Tyre	175/65 R15	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	09/01/2020	Inspection Date	07/02/2020
Survey held at	INDECO ENGINEERS PTE LTD 39 DEFU LANE 12 . SINGAPORE 539139		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 2075M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BOOT LID GLASS (WCP)	SCRATCHED	937.66	937.66
4	BOOT LID GLASS SCREW @ \$2.00 (WCP)		8.00	8.00
1	BOOT LID GLASS EMBLEM (WCP)	NECESSARY	59.35	59.35
1	BOOT LID GLASS LOGO (WCP)	NECESSARY	30.41	30.41
1	REAR BUMPER ASSY (WCP)	DEFORMED	823.08	823.08
10	REAR BUMPER SCREW @ \$2.00 (WCP)	NECESSARY	20.00	20.00
1	REAR BUMPER REFLECTOR LH (WCP)	MISSING	47.92	47.92
1	REAR BUMPER REFLECTOR RH (WCP)	MISSING	47.92	47.92
1	REAR BUMPER REINFORCEMENT (WCP)	NOT NECESSARY	79.46	-
1	REAR BUMPER REINFORCEMENT BRACKET (WCP)	NOT NECESSARY	10.83	-
1	REAR BUMPER REINFORCEMENT BRACKET (WCP)	NOT NECESSARY	10.83	-
1	NUMBER PLATE LAMP LH (WCP)	NOT NECESSARY	42.00	-
1	NUMBER PLATE LAMP RH (WCP)	NOT NECESSARY	38.48	-
1	REAR RH FENDER COVER (WCP)	DEFORMED	188.00	188.00
	COST PLUS 15%		351.59	324.35
			2,695.53	2,486.69
<u>SPECIAL NETT ITEMS</u>				
1	STICKER (BLUESG) (SN)	NECESSARY	50.00	50.00
1	REAR NUMBER PLATE W/CASING (SN)	CRACKED	45.00	45.00
1	FRONT NUMBER PLATE W/CASING (SN)	CRACKED	45.00	45.00
			140.00	140.00
<u>LABOUR</u>				
	TO REPAIR, REPLACE REAR GLASS, REAR BUMPER, REFLECTOR, NUMBER PLATE, STICKERS AND AFFECTED AREA.		100.00	300.00
	TO PUTTY AND RESPRAY ON REAR BUMPER AND AFFECTED AREA.	NOT NECESSARY	300.00	-
	TO APPLY TUFF KOTE.	NOT NECESSARY	150.00	-
	TO CHECK WIRING.		100.00	30.00
			650.00	330.00



GRAND TOTAL		3,485.53	2,956.69
RECOMMENDED COST OF REPAIRS			2,956.69

Report Ref No. CC6/EQI20002184/Gpa3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 2075M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 2075M

RE-INSPECTION

