



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 1989E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER (CONSISTENT)	CRACKED	1,370.00	1,200.50
2	FRONT BUMPER RETAINER (CONSISTENT)	N/S NECESSARY	106.50	85.50
2	FRONT BUMPER BRACKET (CONSISTENT)	NO SUCH PARTS	122.60	-
1	FRONT LOWER BUMPER (CONSISTENT)	NO SUCH PARTS	437.50	-
1	FRONT REINFORCEMENT (CONSISTENT)	TO REPAIR SEE LABOUR	657.20	-
1	FRONT BUMPER GRILLE (CONSISTENT)	CRACKED	482.30	370.80
1	FRONT BUMPER GRILLE CHROME (CONSISTENT)	NECESSARY	216.50	216.50
1	FRONT BUMPER LOWER GRILLE (CONSISTENT)	SERVICEABLE	328.10	-
1	LHS FRONT BUMPER FOG LAMP COVER (CONSISTENT)	CRACKED	220.60	110.50
1	LHS HEADLAMP (CONSISTENT)	N/S CRACKED	2,756.30	1,160.50
1	LHS HEADLAMP BRACKET (CONSISTENT)	CRACKED	106.20	78.80
1	LHS FRONT FENDER (CONSISTENT)	TO REPAIR SEE LABOUR	1,172.30	-
1	LHS FRONT FENDER SHIELD (CONSISTENT)	SERVICEABLE	285.60	-
1	LHS FRONT ABSORBER (CONSISTENT)	NOT NECESSARY	685.00	-
1	LHS FRONT LOWER ARM (CONSISTENT)	NOT NECESSARY	566.50	-
1	LHS FRONT KNUCKLE HUB (CONSISTENT)	NOT NECESSARY	523.80	-
1	LHS FRONT KNUCKLE HUB BEARING (CONSISTENT)	NOT NECESSARY	310.50	-
1	WIPER TANK (CONSISTENT)	CRUMPLED	285.00	200.80
1	HORN LH (CONSISTENT)	CRACKED	120.00	98.80
	LESS 10% DISCOUNT		-	-352.27
			10,752.50	3,170.43
<u>SPECIAL NETT ITEMS</u>				
10	FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	50.00	25.00
10	LHS FRONT FENDER SHIELD CLIP (SN) (CONSISTENT)	NECESSARY	50.00	20.00
1	LHS FRONT RIM (SN) (CONSISTENT)	NOT NECESSARY	600.00	-
1	LHS FRONT TYRE (SN) (CONSISTENT)	NOT NECESSARY	300.00	-
1	SUNDRIES (SN) (CONSISTENT)	NOT NECESSARY	50.00	-
			1,050.00	45.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO REPAIR ,REPLACE & REALIGN DAMAGED AREAS.INCLUSIVE OF THE REPAIR OF FRONT REINFORCEMENT AND LHS FRONT FENDER .		900.00	450.00
	TO SPRAY PAINTING ON AFFECTED AREAS.		600.00	400.00
	TO CHECK WIRING AND LIGHTING SYSTEM.		100.00	30.00
	TO DIAGNOSE ERASE FAULT CODE MEMORIES.		150.00	60.00
	TO SUPPLY UNDER-COATING /PUTTY ON PARTS REPLACED.		80.00	30.00
	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS.	NOT NECESSARY	60.00	-
	CHECK AND RE-ADJUST WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	REMOVE AND REPLACE FRONT BUMPER SENSOR .		80.00	20.00
			2,070.00	990.00
	GRAND TOTAL		13,872.50	4,205.43
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,350.00

Report Ref No. CC4/ASM20002187/Hga3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.