Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002215/AEA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900020295

Claimant
Vehicle No: SLQ2624E

Insured Vehicle No: SMJ1087L

Date of Loss: 06/02/2020 Nature of Claim: TP Claim No: 0867704220SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ2624E

Make & Model: AUDI A4, 1.4 TFSI S TRONIC (A) Engine No: CVN039884

Reg. Date: 30/06/2017 (Man. Year: 2017) Chassis No: WAUZZZF42HA171220

Colour: Red Odometer: 37761 km

Engine Capacity: 1395 cc Market Value/New Car

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,008.00	47.52	12,960.48	99.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,952.00	2,152.00	1,800.00	45.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,960.00	2,199.52	14,760.48	87.03
+ GST 7.00/7.00% (S\$)	1,187.20	153.97	1,033.23	87.03
Nett Amount (S\$)	18,147.20	2,353.49	15,793.71	87.03
+ Loss of Use (3.0 x \$	+ Loss of Use (3.0 x S\$60.00/day) (S\$)			
Nett Liability (S\$)		2,533.49		

INSPECTION

Date of Assignment: 12/02/2020

Date Inspected: 12/02/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING Manager: Asher Sng Rong Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	2,010.00 FS	*-FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	269.00 FS	*-FS
3	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTRE	Not Necessary	198.00 FS	*-FS
4	1		*FRONT BUMPER AIR GUIDE -LH	Not Necessary	59.00 FS	*-FS
5	1		*FRONT BUMPER GRILLE -CENTRE	Not Necessary	185.00 FS	*-FS
6	1		*RADIATOR GRILLE	Not Necessary	1,084.00 FS	*-FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE -LH	Not Necessary	127.00 FS	*-FS
8	1		*FRONT BUMPER GUIDE SECTION -LH	Not Necessary	34.00 FS	*-FS
9	1		*FRONT BUMPER FOAM FILLER PIECE	Not Necessary	117.00 FS	*-FS
10	1		*FRONT BUMPER CARRIER	Not Necessary	757.00 FS	*-FS
11	1		*LOCK CARRIER BRACKET	Not Necessary	129.00 FS	*-FS
12	2		*FRONT BUMPER SUPPORT -LH/RH	Not Necessary	54.00 FS	*-FS
13	1		*HORN -LH HIGH TONE	Not Necessary	38.00 FS	*-FS
14	1		*LIFT CYLINDER -LH	Not Necessary	198.00 FS	*-FS
15	1		*HEADLIGHT CORRUGATED PIPE	Not Necessary	88.00 FS	*-FS
16	1		*LED HEADLIGHT -LH	Not Necessary	7,321.00 FS	*-FS
17	1		*FRONT NO PLATE	Not Necessary	40.00 FS	*-FS
18	1		*SUNDRIES	Necessary	300.00 FS	*47.52 FS
F=Fra	anchise	part. S=S	pcNett.	Total Parts (S\$)	13,008.00	47.52

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00					
2	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHTS ,RE-ORGANISE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	1,400.00	500.00					
3	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	2,000.00	1,100.00					
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00					
	Gross Labour Cost (S\$)		3,952.00	2,152.00					
	Report was unsubmitted durin	g this print-out.							

< END OF ESTIMATES >