

ASS. REF. BY:

REF: CS/CT1 20002228/ USF302

Special Instruction:

SURVEYOR

Marcus

ASSIGNMENT (Office)

From (Person): Cecilia Low

of

CTI

Date/Time: 10.2.2020 9.54 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 9563H

Insured:

GBK 4092

at Workshop m/s

Lin's Brother

Tel:

67411730

of

Blk 1 Baki Bukit Ave 6 #01-01 Autobay

Policy No:

DMVSVR 30836619000

Claim No:

SNM 201200663

Sum Insured:

Excess:

Make of Veh:

D.O.A. 05/02/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10.2.2020 10.59 a.m

Person Contacted:

Susan

Vehicle: IN / OUT

Date/Time

Action/Instruction (✓) Estimate

GBE 9563H - NM/CTI 20002059/114 D.O.A - 05/02/2020

GBE 4092 - CS/CTI 20002228/121473 DM - 05/02/2020

11/02/20

@ 14:00 pm checked with Susan, got estimate.

ASSIGNMENT

From: Date: Veh No: GBE9563H Yr Regn: 175/16
 Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer of CAI
 To inspect Vehicle No: GBE 9563K Make: FIAT Doble cargo mexi 1598
 at Workshop m/s 1st's su Colour: white A/C: Insured / Std / NI / NA
 of Sp. Reading 36803 T/Radio: Insured / Std / NI / NA
 Insured: GBE 2437E Eng/No:
 Policy No: C/No: ZFA26300006C0 6665
 Claims No: Gen. Cond: Good / Fair / Poor / Burnt
 Sum Insured: Excess: Steering: In order / Jammed / Leaked / Burnt or
 (Client's Record) Brake: In order / Jammed / Leaked / Burnt or
 Make of Veh: Modi: Nil / S/Rim / STD A/Rim or

N/S	O/S

Tyre Size: F: 195/60R16
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIP / SUMI /
 TOYO / YOKO or
 Front 6 Rear 6
 R/Bal. mm R/Bal. mm
 L/Bal. mm L/Bal. mm
 D.O.A. 5/12/20 D.O.I. 10/12/20
 Survey held at
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rear & R.L. &
 The O/S / Chassis frame / Body Structure affected due to collision.

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 35K
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 12 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: net 18532 Vehicle: IN / OUT

Date / Time Action / Instruction

21/12/20 17A18468 Gyr 3rd.

21/12/20 4/5 @ 15,000 confirmed with Susan.
 (\$ 22,118.80 Red - 60%)

RECEIVED 24 FEB 2020

Date/Time, File Pass to?

21/02/20

1) Typist

Date/Time, File Return to?

2)

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 12

Resurvey No. of Trip: 3

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

) \$ + RS. \$

) Photos

) Others

)

Report Format :

Lump Sum / I.B.I.: (\$ 15,000/- 45)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2020		10 Feb 2020 09:54 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N		
Vehicle Reg. No.:	GBE9563H	Date of Loss:	05/02/2020 14:00 - :59
Claim Type:	TP / SNM20D200663	Policy/Cover Note No.:	DMCVSN30836619000 (Comprehensive)
Vehicle Reg. No. (Insured):	GBK409Z	Policy No. (Claimant):	D-16083837MFCV/4
		Excess:	S\$0.00
Repairer:	Lius Brother Auto Workshop (HQ) Liu's Brother Auto Workshop, Blk 1 Kaki Bt Ave 6 #01-01 Auto Bay @ Kaki Bt Singapore 417883, 417883 Kaki Bukit - Tel: 67411730		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Company

Owner ID: 196N

Vehicle Details

Vehicle No.: GBE9563H

Vehicle to be Exported: No

Intended Deregistration Date: 11 Feb 2020

Vehicle Make: FIAT

Vehicle Model: DOBLO CARGO MAXI 1.6 MTJ AMT
GLAZE

Primary Colour: White

Manufacturing Year: 2016

Engine No.: 263A50007578651

Chassis No.: ZFA26300006C06665

Maximum Power Output: -

Open Market Value: \$19,364.00

Original Registration Date: 12 May 2016

First Registration Date: 12 May 2016

Transfer Count: 1

Actual ARF Paid: \$969.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 11 May 2026

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

PQP Paid: \$29,549.00

COE Rebate Amount: \$18,468.00

Total Rebate Amount: \$18,468.00

The information contained herein is correct as at 10 Feb 2020

OK

Miudelight V2
Massage Chair

5 Stars Review

\$1299
\$36/month



MiuDivine V3
Massage Chair

5 Stars Review

\$1999
\$56/month



EMS Ultra-Slim Foot Massager
With Massage Chair Purchase
Worth \$139
FREE



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad Advertiser Login Ways of Selling

New 5 Years Renewal COE Toyota Vios 1.5A.



2.98% P.A, 0 Down, 0 Admin,
\$458 Monthly, 2 Years Warranty
Engine And Gearbox.
GV Credit - StarAd

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars
30 years of car sale

Browse by Category

Sort by Date Posted 20 results/page

8 vehicles

Fiat Doblo

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Fiat Doblo		Any	Any	2016	Any	Any	Any	Available
	Fiat Doblo	Fiat Doblo Cargo Maxi 1.6A	\$40,388	\$6,200 /yr	17-Aug-2016	1,598 cc	-	Van	Available
		Fuel Type: Diesel							
		1 Owner Auto Diesel Van. Low Mileage And Well Maintained Original Factory Condition. \$0 Driveaway Possible. Flexible In House Loan A...							
		ABWIN Bus Pte Ltd							
		Posted: 08-Feb-2020 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat							
	Fiat Doblo	Fiat Doblo Cargo Maxi 1.6M	\$36,800	\$5,460 /yr	07-Nov-2016	1,598 cc	74,890 km	Van	Available
		Fuel Type: Diesel							
		1 Owner Only. 100% Loan Available. fully Agent Service Since Days 1. Totally Like New. 5 Year 160000km Warranty, No Gimmicks, 100%...							
		Posted: 07-Feb-2020 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat							
	Fiat Doblo	Fiat Doblo Cargo Maxi 1.6A	\$37,800	\$5,630 /yr	28-Oct-2016	1,598 cc	49,000 km	Van	Available
		Fuel Type: Diesel							
		1 Owner, 100% No Gimmicks. Smoke Free, Totally Like New Van, Spare Unit For Previous Owner. 100% Super Low Mileage Bound With...							
		Posted: 07-Feb-2020 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat							
	Fiat Doblo	Fiat Doblo Cargo Maxi 1.6A	\$40,800	\$6,390 /yr	30-Jun-2016	1,598 cc	48,600 km	Van	Available
		Fuel Type: Diesel							
		Priced To Sell! Warranty And Free Servicing Till 2021. By Agent. Accident Free. No Scratch Es, No Dents. Very Low Mileage. No Addition...							
		Posted: 31-Jan-2020 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat							
		Debut of the new Fiat Doblo Cargo							
		Making its debut at the Hanover IAA Motor Show, the new Fiat Doblo also debuts the ultra-efficient new 'EcoJet' derivative.							
		Read this article							
	Fiat Doblo	Fiat Doblo Cargo Maxi 1.6A	\$35,800	\$5,720 /yr	16-May-2016	1,598 cc	104,000 km	Van	Available
		Fuel Type: Diesel							
		Agent Unit. Maintained At Agent Till Now. Warranty Till May 2021 Or 160k Mileage. Consignment Unit. Call Now For A Viewing Appt.							
		Prem Roy Motoring							
		Posted: 28-Jan-2020 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat							
	Fiat Doblo	Fiat Doblo Cargo Maxi 1.6A	\$37,880	\$6,340 /yr	01-Feb-2016	1,598 cc	31,099 km	Van	Available
		Fuel Type: Diesel							
		3 Free Servicing And 1.5 Year Of Warranty Left! Management Car For Director Only. Seldom Used. Very Low Mileage. Comes With 2 Rea...							
		Posted: 26-Jan-2020 Tags: 2016 Fiat Doblo, 2016 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat							
		Fiat Doblo Cargo Maxi 1.6A	\$42,888	\$6,420 /yr	17-Oct-2016	1,598 cc	28,000 km	Van	Available
		Fuel Type: Diesel							
		Service And Warranty By Agent Motorviva Pte Ltd.							

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurer(s).
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/02/2020 18:17
Date Of Accident 05/02/2020 15:10
Exact Location Of Accident 4 CLEMENTI LOOP PARKING LOT
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE9563H
Insured/Policyholder
Name Of Registered Owner GOLDBELL LEASING PTE LTD
Co Reg No 1XXXXX196N
Email Address ISAACNGCL@GBL.COM.SG
Mobile Phone No (LOCAL) +65-91133724
Alternative Phone No OFFICE-64942897

Vehicle Particulars

Manufacturer FIAT
Model DOBLO CARGO MAXI-1.6 D MTJ AMT GLAZE (M)
Exact Purpose for which vehicle was being used at time of accident DELIVERY
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy YES
Policy Number D-16083837MFCV/4
Cover Note Number

Driver

Name of Driver MOHD SANDIPUTRA BIN AJISMAN
Passport No/FIN GXXXX331P
Date Of Birth 22/12/1985
Occupation OUTDOOR
Date Of Driving Pass 25/04/2018
Driving Experience 1 YEAR AND 9 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-91462692
Fax Number
Contact Number
Email Address VIMAL.K@OTIS.COM

Address	8 KALLANG AVE #07-01 APERIA TOWER
Postcode	339509
Was driver involved in the Insured's Company	NO
If No, Relationship with the Insured	OTHER - HIRER
Vehicle Registered under Driver's Own	-
Vehicle	-
	-
Insurance Cover under Driver's Own Vehicle	-
	-
	-

General Information about the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Condition	CLEAR
Road Surface	DRY

Other Information

Was any foreigner involved in this accident?	NO
Number of people involved in the accident (including own vehicle)	3
Was any foreigner involved in the Accident?	NO
Was any injured person taken to hospital by ambulance?	NO
Was any other person's property damaged?	YES
I have been contacted by unknown person(s) soliciting for insurance claims assistance.	NO
Number of people involved (including Driver)	0

Details of Police Report

Was the accident reported to the police?	NO
If Yes, Please provide Police Station	
Was notice of prosecution given?	NO
If Yes, please provide details	

Circumstances of the Accident

ON 5 FEB 2022 AT 1510HRS, I PARKED MY VEHICLE GBE9563H AT 4 CLEMENTI LOOP CAR PARK. AFTER I FINISHED MY WORK, I RETURNED BACK TO MY VEHICLE. REALISED THAT VEHICLE GBK409Z HAS COLLIDED ONTO MY VEHICLE AT REAR PORTION. BECAUSE OF THE COLLISION MY VEHICLE MOVED FORWARD AND COLLIDED ONTO THE FENCE. REAR PORTION OF MY VEHICLE C-GBK409Z ALSO COLLIDED ONTO VEHICLE GBF2437E WHICH IS PARKED ON LEFT OF MY VEHICLE. VEHICLE GBK409Z WAS PARKED AT THE SLOPE. SO THE VEHICLE MOVED OUT FROM THE SLOPE AND COLLIDED ONTO MY VEHICLE AT REAR PORTION. MY VEHICLE REAR MIRROR, UNDERCARRIAGE WERE DAMAGED. THERE WAS OIL LEAKAGE FROM BELOW MY VEHICLE. NOBODY WAS INJURED.

Attachment

Are accident details available for attachment?	YES
Was there any evidence captured by Car Camera?	NO
Was there any evidence provided?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registered under	GBK409Z
Vehicle Make/Model	TOYOTA
Details Of Policy	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MUTHUSAMY PRABU
NRIC/Passport No	GXXXX540X
Contact Number	94204951
Address	
Postcode	
Insurance Cover	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

GBF2437E

Vehicle Make/Model/Colour

FIAT DIABLO

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

GOH SER YOUNG

NRIC/Passport Number

SXXXX847A

Contact Number

97124484

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

NOTICE

to correctly the details of the accident to speed up the claims process.

Must be completed by the Policyholder and/or the Authorised Driver

provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material information may lead insurance companies to **repudiate policy liability**.

Acceptance of this Form by insurance companies is not an admission of **policy liability** on the part of the insurance company.

Reporting may be referred to the Police for investigation.

will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by parties.

By submitting this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of this report being made available aforesaid.

Under the Personal Data Protection Act (PDPA)

I acknowledge, agree and consent that:

(a) my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, store and process my personal data/personal information set out in this form and any other personal information that may be possessed by my insurer (collectively the "Personal Information") and disclose and transfer such information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Police Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) stated below;

(b) for settling, handling and/or dealing with my claims including the settlement of the claims and any necessary communications relating to the claims;

(c) for locating the accident and/or my claims;

(d) for settling out and/or dealing with my instructions or responding to any enquiries by me;

(e) for settling my claims (including the making of correspondence, statements, invoices, reports or notices to me, which might involve disclosure of certain personal data about me to bring about delivery of the same as well as on the delivery of envelopes/mail packages); and/or

(f) for settling with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").

(g) the Insurers, who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, store and/or process my Personal Information for one or more of the above Purposes; and

(h) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or their lawyers/law firms, which may be sited outside of Singapore, for one or more of the above Purposes.


(i) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, prevention and management in present and all future claims.

(j) any so collected under (d) above may be shared / disclosed:

(1) to the Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, claims, law enforcement and government agencies as reasonably required for the purposes stated; or


(2) complying with requirements under any regulations, laws or court orders.


Driver's Signature
(if driver is not the policyholder)
Date & Time 5/3/20 - 1705H


Reporting Centre Personnel's Signature
Name: Khumetay
NIC/FIN No:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 5 Feb 2020, at about 1510hrs, I was parked my vehicle GBE 9563H at 4 Clementi Loop carpark. After I finished my work I returned back to my vehicle. Realised that vehicle GBK 4092 has collided onto my vehicle at rear portion. Because of the collision my vehicle moved forward and collided onto the fence. Realised that vehicle C - GBK 4092 also collided onto vehicle GBF 2437E which is parked on left of my vehicle. Vehicle ~~GBK 4092~~ GBK 4092 was parked at the slope. So the vehicle drove out from the slope and collided onto my vehicle at rear portion. My vehicle rear mirror, undercarriage was damaged. There is a oil leakage from my wheel of my vehicle. Nobody was ~~injured~~ injured.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time: 5/2/20 - 1705H

Reporting Centre Personnel's Signature
Name: Kheng
NRIC/IN No.:

Accident Photo



Accident Photo



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBE956311200205

Estimate

Customer

Page 01 - 02

Name: China Taiping Insurance (Singapore) Pte Ltd

Date: 07-02-20

Address: Motor Claims Department

Vehicle No: GBE9563H

3 Anson Road #16-00

Model/Make: Fiat Doblo Cargo

Springleaf Tower

Singapore 079909

Maxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Tailgate <i>Body 2355.50</i>	\$ 2,395.00	
2	Tailgate Lock <i>Suc</i>	\$ 331.00	X
3	Tailgate Weatherstrip <i>171 244.60</i>	\$ 344.50	X
4	Tailgate Hinge 02 pcs (@ \$8166.30) <i>111</i>	\$ 332.60	X
6	Tailgate Inner Trim Board <i>Che 288.70</i>	\$ 384.90	X
7	Tailgate Inner Trim Board Clips 1 set <i>11</i>	\$ 164.50	X
8	Tailgate Wiper Motor <i>Che</i>	\$ 428.00	X
9	Tailgate Wiper Link <i>11</i>	\$ 165.30	X
10	Tailgate Wiper Rubber <i>11</i>	\$ 98.00	SN X
13	Tailgate Number Plate Lamp 02 pcs (@ \$51.50) <i>Che</i>	\$ 103.00	X
14	Tailgate Number Plate Outer Garnish <i>Beif</i>	\$ 154.40	X
15	Tailgate Number Plate and Base <i>Suc</i>	\$ 48.00	SN X
16	Tailgate "70 KM/H" Sticker <i>nee</i>	\$ 15.00	SN 105.2
18	Tailgate "Doblo" Emblem <i>nee 80.50</i>	\$ 118.00	X
19	Tailgate "Maxi" Emblem <i>nee 62.50</i>	\$ 86.00	X
11	Tailgate Glass <i>Shofers 680.00</i>	\$ 841.50	X
12	Tailgate Glass Sealant <i>nee</i>	\$ 80.00	SN 40 5.2
26	Tail Lamp <i>ALS Che 422.10</i>	\$ 462.70	X
27	Tail Lamp Panel <i>n</i>	\$ 989.30	X
28	Fender (Body Panel) <i>Body 2350.00</i>	\$ 2,850.00	X
29	Fender Cowling <i>ALS 70.11 166.00</i>	\$ 230.00	X
30	Rear Bumper <i>De 734.34</i>	\$ 745.00	X
31	Bumper Clips 1 set <i>nee 50.00</i>	\$ 65.00	X
32	Bumper <i>retainer nls beif 75.40</i>	\$ 155.00	X
33	Bumper Reinforcement <i>beif 520.92</i>	\$ 752.00	X
34	Bumper Reflector <i>Suc</i>	\$ 117.60	X
35	Bumper Reverse Sensor <i>Suc</i>	\$ 220.00	SN X
36	Bumper Towing Cover <i>11</i>	\$ 95.00	X
21	Floor Panel Garnish <i>11</i>	\$ 1,379.80	X
37	"Corporate" Advertisement & Artwork <i>nee</i>	\$ 150.00	- 805.2
38	Front Bumper <i>Del Torn 864.07</i>	\$ 1,245.50	X
39	Bumper Clips 1 set <i>nee 50.00</i>	\$ 60.00	X
40	Bumper Lower Garnish <i>Torn 228.60</i>	\$ 685.00	X
41	Grille <i>Torn</i>	\$ 484.70	X
42	Grille Emblem <i>11</i>	\$ 142.10	X
43	Number Plate and Base <i>Suc</i>	\$ 48.00	SN X
C/F Balance --->		\$ 14,301.10	

Link Auto Consultants hence notify

the Repairer of the following:

- * To resurvey before/after spray painting
- * To display damaged part(s) during inspection
- * Parts prices are subject to confirmation
- * Total parts warranty is on a "Without Prejudice" basis
- * No liability for corrosion(s) is allowed
- * Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized

10/2/20
2/s \$15,000
WhatsApp After 12 days.



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

Nô. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBE9563H200205

Estimate**Customer**

Name: China Taiping Insurance (Singapore) Pte Ltd

Address: Motor Claims Department

3 Anson Road #16-00

Springleaf Tower Singapore 079909

Page 02 - 02

Date: 07-02-20

Vehicle No: GBE9563H

Model/Make: Fiat Doblo Cargo

Maxi 1.6 MTJ AMT Glaze

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
----------	-----------------------	---------------------------------	------------------------------------

B/F Balance --->

44	Front Headlamp 02 pcs (@ S\$862.40) <i>holder c/o</i>	\$ 1,724.80	
45	Head Lamp Outer Garnish 02 pcs (@ S\$176.30) <i>11</i>	\$ 352.60	X
46	Engine Oil Sump <i>11</i>	\$ 1,780.00	X
47	Engine Oil Sump Lower Cover <i>11</i>	\$ 1,170.00	X
48	Engine Oil Sump Lower Cover Clips 1 set <i>11</i>	\$ 98.00	SN X
49	Engine Mounting 1 set <i>11</i>	\$ 2,148.00	X
50	Engine Lower Cover <i>For 1 385-12</i>	\$ 974.00	
51	Engine Cover 02 pcs (@ S\$235.00) <i>0150-1 102</i>	\$ 470.00	17K
52	Engine Oil 4L <i>11</i>	\$ 140.00	SN X
53	Steering Rack <i>Sub/121 2650-42</i>	\$ 3,540.00	
54	Exhaust Pipe <i>Sub/121</i>	\$ 1,195.00	
55	Exhaust Pipe Mounting 02 pcs (@ S\$35.00 SN) <i>11</i>	\$ 70.00	SN X
57	Front Rh Tyre <i>See</i>	\$ 195.00	SN X
58	Wheel Hub-Cab <i>11</i>	\$ 225.00	SN X
59	Wheel Steel Rim <i>11</i>	\$ 679.00	SN X
60	Lower Arm <i>See 455-10</i>	\$ 648.00	
61	Suspension <i>See</i>	\$ 1,044.00	X
62	Shock Absorber Mounting <i>11</i>	\$ 315.30	X
63	Knuckle Arm <i>See</i>	\$ 684.00	X
64	Knuckle Arm Bearing <i>Dange</i>	\$ 175.00	

Remove & reinstall Rear Lh Windscreen Glass to facilitate repairs

Remove and replace rear exhaust pipe system to facilitate repairs

Remove and refix rear reverse sensor

Remove & reinstall Front Windscreen Glass to facilitate repairs

To Dismantle & Replacing Undercarriage parts & components

To remove and refix Engine Labor Charge

To check and re-adjust wheel alignment

To apply Rust Proofing, reseal tuff-coating treatment on accident area

To check all wiring & electrical component for proper function

Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc

To putty & spray painting & including touch up paint on accident aff

Total Parts & Labour of estimate for damaged vehicle

\$ 37,118.80

3200

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

18750-39 P-17133-77

39720-10

102
P-15420-39
S-2130

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	06 Feb 2020		10 Feb 2020 09:54 Edit Adj Rpt	S\$15,000.00 Edit Estimates	S\$15,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	Co. Reg. No.: -								
Main Claimant:	GOLDBELL LEASING PTE LTD, Co. Reg. No.: 199001196N								
Vehicle Reg. No.:	GBE9563H	Date of Loss:	05/02/2020 14:00 - :59 [44 Months and 24 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200663	Policy/Cover Note No.:	DMCVSN30836619000 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBK409Z	Policy No. (Claimant):	D-16083837MFCV/4						
		Excess:	S\$0.00						
Repairer:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 19/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBE9563H (SNM20D200663)
[GBK409Z]

TP

GOLDBELL LEASING PTE LTD

Feb 5 2020 2:00PM

[-]

Liu's Brother Auto Engineering Workshop

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images								3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	10/02/20 15:37	General View						 Load JPG	☒	
2	10/02/20 15:37	General View						 Load JPG	☒	
3	10/02/20 15:37	General View						 Load JPG	☒	
4	10/02/20 15:37	General View						 Load JPG	☒	
5	10/02/20 15:37	General View						 Load JPG	☒	
6	10/02/20 15:37	General View						 Load JPG	☒	
7	10/02/20 15:37	General View						 Load JPG	☒	
8	10/02/20 15:37	General View						 Load JPG	☒	
9	10/02/20 15:37	General View						 Load JPG	☒	
10	10/02/20 15:37	General View						 Load JPG	☒	
11	10/02/20 15:37	General View						 Load JPG	☒	
12	10/02/20 15:37	General View						 Load JPG	☒	
13	10/02/20 15:37	General View						 Load JPG	☒	
14	10/02/20 15:37	General View						 Load JPG	☒	
15	10/02/20 15:37	General View						 Load JPG	☒	
16	10/02/20 15:37	General View						 Load JPG	☒	
17	10/02/20 15:37	General View						 Load JPG	☒	
18	10/02/20 15:37	General View						 Load JPG	☒	
19	10/02/20 15:37	General View						 Load JPG	☒	
20	10/02/20 15:37	General View						 Load JPG	☒	
21	10/02/20 15:37	General View						 Load JPG	☒	
22	10/02/20 15:37	General View						 Load JPG	☒	
23	10/02/20 15:37	General View						 Load JPG	☒	
24	10/02/20 15:37	General View						 Load JPG	☒	
25	10/02/20 15:37	General View						 Load JPG	☒	
26	10/02/20 15:37	General View						 Load JPG	☒	
27	10/02/20 15:37	General View						 Load JPG	☒	
28	10/02/20 15:37	General View						 Load JPG	☒	
29	10/02/20 15:37	General View						 Load JPG	☒	
30	10/02/20 15:37	General View						 Load JPG	☒	
31	10/02/20 15:37	General View						 Load JPG	☒	
32	10/02/20 15:37	General View						 Load JPG	☒	
33	10/02/20 15:37	General View						 Load JPG	☒	
34	10/02/20 15:37	General View						 Load JPG	☒	
35	10/02/20 15:37	General View						 Load JPG	☒	
36	10/02/20 15:37	General View						 Load JPG	☒	
37	10/02/20 15:37	General View						 Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	10/02/20 15:37	General View	 Load JPG	☒
39	10/02/20 15:37	General View	 Load JPG	☒
40	10/02/20 15:37	General View	 Load JPG	☒
41	10/02/20 15:37	General View	 Load JPG	☒
42	10/02/20 15:37	General View	 Load JPG	☒
43	10/02/20 15:37	General View	 Load JPG	☒
44	10/02/20 15:37	General View	 Load JPG	☒
45	10/02/20 15:37	General View	 Load JPG	☒
46	10/02/20 15:37	General View	 Load JPG	☒
47	10/02/20 15:37	General View	 Load JPG	☒
48	10/02/20 15:37	General View	 Load JPG	☒
49	10/02/20 15:37	General View	 Load JPG	☒
50	10/02/20 15:37	General View	 Load JPG	☒
51	10/02/20 15:37	General View	 Load JPG	☒
52	10/02/20 15:37	General View	 Load JPG	☒
53	10/02/20 15:37	General View	 Load JPG	☒
54	10/02/20 15:37	General View	 Load JPG	☒
55	10/02/20 15:37	General View	 Load JPG	☒
56	10/02/20 15:37	General View	 Load JPG	☒
57	10/02/20 15:37	General View	 Load JPG	☒
58	10/02/20 15:37	General View	 Load JPG	☒
59	10/02/20 15:37	General View	 Load JPG	☒
60	10/02/20 15:37	General View	 Load JPG	☒
61	10/02/20 15:37	General View	 Load JPG	☒
62	10/02/20 15:37	General View	 Load JPG	☒
63	10/02/20 15:37	General View	 Load JPG	☒
64	10/02/20 15:37	General View	 Load JPG	☒
65	10/02/20 15:37	General View	 Load JPG	☒
66	10/02/20 15:37	General View	 Load JPG	☒
67	10/02/20 15:37	General View	 Load JPG	☒
68	10/02/20 15:37	General View	 Load JPG	☒
69	10/02/20 15:37	General View	 Load JPG	☒
70	10/02/20 15:37	General View	 Load JPG	☒
71	10/02/20 15:37	General View	 Load JPG	☒
72	10/02/20 15:37	General View	 Load JPG	☒
73	10/02/20 15:37	General View	 Load JPG	☒
74	10/02/20 15:37	General View	 Load JPG	☒
75	10/02/20 15:37	General View	 Load JPG	☒
76	10/02/20 15:37	General View	 Load JPG	☒
77	10/02/20 15:37	General View	 Load JPG	☒
78	10/02/20 15:37	General View	 Load JPG	☒
79	10/02/20 15:37	General View	 Load JPG	☒
80	10/02/20 15:37	General View	 Load JPG	☒
81	10/02/20 15:37	General View	 Load JPG	☒
82	10/02/20 15:37	General View	 Load JPG	☒
83	10/02/20 15:37	General View	 Load JPG	☒
84	10/02/20 15:37	General View	 Load JPG	☒
85	10/02/20 15:37	General View	 Load JPG	☒
86	10/02/20 15:37	General View	 Load JPG	☒
87	10/02/20 15:37	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	10/02/20 15:37	General View	 Load JPG	☒
89	10/02/20 15:37	General View	 Load JPG	☒
90	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
91	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
92	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
93	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
94	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
95	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
96	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
97	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
98	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
99	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
100	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
101	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
102	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
103	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
104	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
105	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
106	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
107	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
108	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
109	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
110	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
111	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
112	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
113	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
114	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
115	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
116	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
117	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
118	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
119	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
120	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
121	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
122	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
123	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
124	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
125	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
126	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
127	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
128	14/02/20 17:26	Reinspection Photo	 Load JPG	☒
129	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
130	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
131	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
132	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
133	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
134	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
135	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
136	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
137	20/02/20 18:10	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
139	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
140	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
141	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
142	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
143	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
144	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
145	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
146	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
147	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
148	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
149	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
150	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
151	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
152	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
153	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
154	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
155	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
156	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
157	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
158	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
159	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
160	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
161	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
162	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
163	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
164	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
165	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
166	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
167	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
168	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
169	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
170	20/02/20 18:10	Reinspection Photo	 Load JPG	☒
171	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
172	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
173	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
174	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
175	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
176	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
177	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
178	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
179	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
180	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
181	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
182	20/02/20 18:11	Reinspection Photo	 Load JPG	☒
183	20/02/20 18:11	After Repair Photo	 Load JPG	☒
184	20/02/20 18:11	After Repair Photo	 Load JPG	☒
185	20/02/20 18:11	After Repair Photo	 Load JPG	☒
186	20/02/20 18:11	After Repair Photo	 Load JPG	☒
187	20/02/20 18:11	After Repair Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	20/02/20 18:11	After Repair Photo	 Load JPG	☒
189	20/02/20 18:11	After Repair Photo	 Load JPG	☒
190	20/02/20 18:11	After Repair Photo	 Load JPG	☒
191	20/02/20 18:11	After Repair Photo	 Load JPG	☒
192	20/02/20 18:11	After Repair Photo	 Load JPG	☒

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Aspectus Consultancy Pte Ltd (Aspectus)	Thumbnail	Print
1	05/02/20 19:25	Accident Statement	 Load HTM	

Photos/Images			3 per page	☒
No	Finalized On	Aspectus Consultancy Pte Ltd (Aspectus)	Thumbnail	Print
1	05/02/20 18:55	Accident Photo	 Load JPG	☒
2	05/02/20 18:55	Accident Photo	 Load JPG	☒
3	05/02/20 18:55	Accident Photo	 Load JPG	☒
4	05/02/20 18:55	Accident Photo	 Load JPG	☒
5	05/02/20 18:55	Accident Photo	 Load JPG	☒
6	05/02/20 18:55	Accident Photo	 Load JPG	☒
7	05/02/20 18:55	Accident Photo	 Load JPG	☒
8	05/02/20 18:55	Accident Photo	 Load JPG	☒
9	05/02/20 18:55	Accident Photo	 Load JPG	☒
10	05/02/20 18:55	Accident Photo	 Load JPG	☒
11	05/02/20 18:55	Accident Photo	 Load JPG	☒
12	05/02/20 18:55	Accident Photo	 Load JPG	☒
13	05/02/20 18:55	Accident Photo	 Load JPG	☒
14	05/02/20 18:55	Accident Photo	 Load JPG	☒
15	05/02/20 18:55	Accident Photo	 Load JPG	☒
16	05/02/20 18:55	Accident Photo	 Load JPG	☒
17	05/02/20 18:55	Accident Photo	 Load JPG	☒
18	05/02/20 18:55	Accident Photo	 Load JPG	☒
19	05/02/20 18:55	Accident Photo	 Load JPG	☒
20	05/02/20 18:55	Accident Photo	 Load JPG	☒
21	05/02/20 18:55	Accident Photo	 Load JPG	☒
22	05/02/20 18:55	Accident Photo	 Load JPG	☒
23	05/02/20 18:55	Accident Photo	 Load JPG	☒
24	05/02/20 18:55	Accident Photo	 Load JPG	☒
25	05/02/20 18:55	Accident Photo	 Load JPG	☒
26	05/02/20 18:55	Accident Photo	 Load JPG	☒
27	05/02/20 18:55	Accident Photo	 Load JPG	☒
28	05/02/20 18:55	Accident Photo	 Load JPG	☒
29	05/02/20 18:55	Accident Photo	 Load JPG	☒
30	05/02/20 18:55	Accident Photo	 Load JPG	☒
31	05/02/20 18:55	Accident Photo	 Load JPG	☒
32	05/02/20 19:20	Identification Card	 Load JPG	☒
33	05/02/20 19:20	Identification Card	 Load JPG	☒
34	05/02/20 19:20	Driving License	 Load JPG	☒
35	05/02/20 19:20	Driving License	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Aspectus Consultancy Pte Ltd (Aspectus)	Thumbnail	Print
Documentation			1 per page	☒
No	Finalized On	Aspectus Consultancy Pte Ltd (Aspectus)	Thumbnail	Print
1	05/02/20 18:45	Sketch Plan	 Load JPG	☒
2	05/02/20 18:45	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002228/USF3E2

Date: 27/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30836619000
Claimant Vehicle No :	GBE9563H	Insured Vehicle No :	GBK409Z
Date of Loss:	05/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200663

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE9563H		
Make & Model:	FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M)	Engine No:	263A50007578651
Reg. Date:	12/05/2016 (Man. Year: 2016)	Chassis No:	ZFA26300006C06665
Colour:	White	Odometer:	36803 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16	Rear Tyre Size:	195/60 R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,594.10	15,550.39	19,043.71	55.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,190.00	3,200.00	1,990.00	38.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	39,784.10	18,750.39	21,033.71	52.87
Approved Total (Overridden) (\$\$)		15,000.00		
(S\$)	39,784.10	15,000.00	24,784.10	62.30
+ GST 7.00/7.00% (S\$)	2,784.89	1,050.00	1,734.89	62.30
Nett Amount (\$\$)	42,568.99	16,050.00	26,518.99	62.30

INSPECTION

Date of Assignment:	10/02/2020	
Date Inspected:	10/02/2020 Inspected At:	Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO

BAY @ KAKI BUKIT
Singapore 417883

Estimated Period of Repair: 12.0 days

Adjuster: MARCUS CHUA

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Feb 2020)
Parts:	213	FIAT DOBLO CARGO MAXI 1.6 D MTJ AMT GLAZE (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE9563H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR LH TAILGATE	Badly Dented	2,395.00 F	*2,355.50 FL
2	1		*REAR LH TAILGATE LOCK	Serviceable	331.00 F	*- FL
3	1		*REAR LH TAILGATE WEATHERSTRIP	Twisted	344.50 F	*244.60 FL
4	2		*REAR LH TAILGATE HINGE	Not Necessary	332.60 F	*- FL
5	1		*REAR LH TAILGATE INNER TRIM BOARD	Cracked	384.90 F	*288.70 FL
6	1		*SET REAR LH TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	164.50 F	*- FL
7	1		*REAR LH TAILGATE WIPER MOTOR	Cracked	428.00 F	*428.00 FL
8	1		*REAR LH TAILGATE WIPER LINK	Not Necessary	165.30 F	*- FL
9	1		*REAR LH TAILGATE WIPER RUBBER	Not Necessary	98.00 FS	*- FS
10	2		*REAR LH TAILGATE NUMBER PLATE LAMP	Cracked	103.00 F	*103.00 FL
11	1		*REAR LH TAILGATE NUMBER PLATE OUTER GARNISH	Bent	154.40 F	*154.40 FL
12	1		*REAR LH TAILGATE NUMBER PLATE AND BASE	Serviceable	48.00 FS	*- FS
13	1		*REAR LH TAILGATE 70 KM/H STICKER	Necessary	15.00 FS	*10.00 FS
14	1		*REAR LH TAILGATE DOBLO EMBLEM	Necessary	118.00 F	*80.50 FL
15	1		*REAR LH TAILGATE MAXI EMBLEM	Necessary	86.00 F	*62.50 FL
16	1		*REAR LH TAILGATE GLASS	Shattered	841.50 F	*680.00 FL
17	1		*REAR LH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
18	1		*REAR LH TAIL LAMP N/S	Cracked	462.70 F	*422.10 FL
19	1		*REAR LH TAIL LAMP PANEL	Repair	989.30 F	*- FL
20	1		*REAR LH FENDER (BODY PANEL) N/S	Badly Dented / Buckled	2,850.00 F	*2,350.00 FL
21	1		*REAR LH FENDER COWLING N/S	Torn	230.00 F	*166.00 FL
22	1		*REAR BUMPER	Deformed	745.00 F	*734.34 FL
23	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*50.00 FL
24	1		*REAR BUMPER RETAINER N/S	Bent	155.00 F	*75.40 FL
25	1		*REAR BUMPER REINFORCEMENT	Bent	752.00 F	*520.92 FL
26	1		*REAR BUMPER REFLECTOR	Serviceable	117.60 F	*- FL
27	1		*REAR BUMPER REVERSE SENSOR	Serviceable	220.00 FS	*- FS
28	1		*REAR BUMPER TOWING COVER	Not Necessary	95.00 F	*- FL
29	1		*REAR FLOOR PANEL GARNISH	Not Necessary	1,379.80 F	*- FL
30	1		*REAR CORPORATE ADVERTISEMENT & ARTWORK	Necessary	150.00 FS	*80.00 FS
31	1		*FRONT BUMPER	Deformed / Torn	1,245.50 F	*864.07 FL
32	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 F	*50.00 FL
33	1		*FRONT BUMPER LOWER GARNISH	Torn	685.00 F	*228.60 FL
34	1		*FRONT GRILLE	Torn	484.70 F	*484.70 FL
35	1		*FRONT GRILLE EMBLEM	Not Necessary	142.10 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT NUMBER PLATE AND BASE	Serviceable	48.00 FS	*- FS
37	2		*FRONT HEADLAMP	Holder Cracked	1,724.80 F	*1,724.80 FL
38	2		*FRONT HEAD LAMP OUTER GARNISH	Not Necessary	352.60 F	*- FL
39	1		*FRONT ENGINE OIL SUMP	Not Necessary	1,780.00 F	*- FL
40	1		*FRONT ENGINE OIL SUMP LOWER COVER	Not Necessary	1,170.00 F	*- FL
41	1		*SET FRONT ENGINE OIL SUMP LOWER COVER CLIPS	Not Necessary	98.00 FS	*- FS
42	1		*SET FRONT ENGINE MOUNTING	Not Necessary	2,148.00 F	*- FL
43	1		*FRONT ENGINE LOWER COVER	Torn	974.00 F	*355.12 FL
44	1		*FRONT ENGINE COVER	O/S Torn	470.00 F	*235.00 FL
45	1		*FRONT ENGINE OIL 4L	Not Necessary	140.00 FS	*- FS
46	1		*FRONT STEERING RACK	Bent / Twisted	3,540.00 F	*2,650.42 FL
47	1		*FRONT EXHAUST PIPE	Bent / Twisted	1,195.00 F	*1,195.00 FL
48	2		*FRONT EXHAUST PIPE MOUNTING	Not Necessary	70.00 F	*- FL
49	1		*FRONT RH TYRE	Serviceable	195.00 FS	*- FS
50	1		*FRONT RH WHEEL HUB-CAB	Not Necessary	225.00 FS	*- FS
51	1		*FRONT RH WHEEL STEEL RIM	Not Necessary	679.00 FS	*- FS
52	1		*FRONT RH LOWER ARM	Bent	648.00 F	*455.10 FL
53	1		*FRONT RH SUSPENSION	Serviceable	1,044.00 F	*- FL
54	1		*FRONT RH SHOCK ABSORBER MOUNTING	Not Necessary	315.30 F	*- FL
55	1		*FRONT RH KNUCKLE ARM	Serviceable	684.00 F	*- FL
56	1		*FRONT RH KNUCKLE ARM BEARING	Damaged	175.00 F	*175.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **34,594.10** **17,263.77**
 - List Item Discount on L Items 0.00/10.00% (\$\$) 0.00 1,713.38

Total Parts (\$\$) 34,594.10 15,550.39

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REPLACE REAR EXHAUST PIPE SYSTEM TO FACILITATE REPAIRS	New	120.00	60.00
2	REMOVE AND REFIX REAR REVERSE SENSOR	New	90.00	40.00
3	REMOVE & REINSTALL FRONT WINDSCREEN GLASS TO FACILITATE REPAIRS	New	150.00	0.00
4	TO DISMANTLE & REPLACING UNDERCARRIAGE PARTS & COMPONENTS	New	400.00	350.00
5	TO REMOVE AND REFIX ENGINE LABOR CHARGE	New	600.00	0.00
6	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT	New	100.00	60.00
7	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	280.00	60.00
8	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	450.00	30.00
9	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETC	New	1,500.00	1,400.00
10	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFF	New	1,400.00	1,100.00
11	REMOVE & REINSTALL REAR LH WINDSCREEN GLASS TO FACILITATE REPAIRS	New	100.00	100.00
Gross Labour Cost (\$\$)			5,190.00	3,200.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >