

22/03/2002

ASS. REC. BY:

REF: CS/CT2 20002232/Ksf3n2

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Adeline chng

of CTI

Date/Time: 10.2.2020 8:36am

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 5315E

Insured:

SJX 54454

at Workshop m/s

Kum chow motor

Tel:

64536256

of 160 Sin Ming Drive #05-08

Policy No:

Claim No:

SUM 2017 200677 / SJX54454 / Berl

Sum Insured:

Excess:

Make of Veh:

D.O.A.

4.2.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10/2/2020 9:06am

Person Contacted:

mdm lim

Vehicle: IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SJB 5315E - X
	SJX 54454 - X
11/02/20	@ 14:35 pm checked with Mdm Lim, estimate will email to Kenneth.



## Summer Lee (LKK Auto)

---

**From:** Adeline Chng <adeline.chng@sg.cntaiping.com>  
**Sent:** Monday, 10 February, 2020 8:36 AM  
**To:** assignments@lkkauto.com  
**Cc:** kumchew1; Ben Tang; Claims Dept of CTI  
**Subject:** FW: OUR REF: SNM20D200677/SJX5445Y/BEN & YOUR REF: SJB5315E - ACCIDENT INVOLVING SJB 5315 E & SJX 5445 Y ON 04/02/2020.

Without Prejudice

Dear LKK

Please refer to below email and liaise with Third Party workshop accordingly.

Thank you.

Adeline Chng  
Executive  
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6155 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

-----Original Message-----

From: kumchew1 [mailto:kumchew1@singnet.com.sg]  
Sent: Saturday, 8 February 2020 2:35 PM  
To: Adeline Chng <adeline.chng@sg.cntaiping.com>  
Subject: RE: OUR REF: SNM20D200677/SJX5445Y/BEN & YOUR REF: SJB5315E - ACCIDENT INVOLVING SJB 5315 E & SJX 5445 Y ON 04/02/2020.

Hi Mr Adeline,

Refer to your email dated 7/2/2020.

Kindly appoint Mr. Kenneth Kong to pre-repair inspection our insured vehicle.

Thanks & Best Regards,  
Mdm Lim

-----Original Message-----

From: Adeline Chng [mailto:adeline.chng@sg.cntaiping.com]  
Sent: Friday, February 07, 2020 3:01 PM  
To: kumchew1@singnet.com.sg

Cc: Claims Dept of CTI; Ben Tang

Subject: RE: OUR REF: SNM20D200677/SJX5445Y/BEN & YOUR REF: SJB5315E - ACCIDENT INVOLVING SJB 5315 E & SJX 5445 Y ON 04/02/2020.

Without Prejudice

Dear Sirs

We refer to the above matter.

Attached herewith PRS letter for your next action.

Thank you.

Adeline Chng  
Executive  
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
DID: (65) 6389 6155 | F: (65) 6222 1033

W: [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | FB: [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | WeChat: 太平獅城 Taiping SG

-----Original Message-----

From: Claims Dept of CTI

Sent: Friday, 7 February 2020 1:52 PM

To: Ben Tang <[Ben.Tang@sg.cntaiping.com](mailto:Ben.Tang@sg.cntaiping.com)>; Adeline Chng <[adeline.chng@sg.cntaiping.com](mailto:adeline.chng@sg.cntaiping.com)>

Subject: OUR REF: SNM20D200677/SJX5445Y/BEN & YOUR REF: SJB5315E - ACCIDENT INVOLVING SJB 5315 E & SJX 5445 Y ON 04/02/2020.

Dear Adeline,

Please conduct PRS -SJB5315E soonest possible on behalf of Ben Tang.

Officer in charge-Ben Tang-DID: 6389 6175.

Dear Mdm Kum,

\*\*\* kindly quote our reference number when replying.\*\*\*

Thank you.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road #15-00 Springleaf Tower Singapore 079909  
Tel: 6389 6116  
Fax (65) 6224 7175 / 6224 7478

Email : claimsdept@sg.cntaiping.com  
Website:www.sg.cntaiping.com

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

-----Original Message-----

From: kumchew1 <kumchew1@singnet.com.sg>  
Sent: Friday, February 7, 2020 10:34 AM  
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>  
Subject: FW: ACCIDENT INVOLVING SJB 5315 E & SJX 5445 Y ON 04/02/2020.

Dear Sir,

We are acting on behalf of Mr Low Thiam Siew, the owner of SJB 5315 E in the above matter.

Kindly arrange for pre-repair with the following details;

Venue : Kum Chew Motor Workshop

160, Sin Ming Drive #05-08

Sin Ming Autocity

Singapore 575722.

Contact No. : 64536256.

Thank & Best Regards,  
Mdm Lim

Ks

# KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08  
 SIN MING AUTOCITY, SINGAPORE 575722.  
 Tel No. : 64536256/64563715 Fax No. : 64557754  
 E-Mail : kumchew1@singnet.com.sg  
 GST Reg.No. : M90367665T Buss. Reg. No. : 52855130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 3, ANSON ROAD #16-00  
 SPRINGLEAF TOWER, SINGAPORE 079909.  
 claimsdept@sg.cntaiping.com

Attention : Motor Claim Department

Contact : 63896111 Fax No. : 62221033

Estimate : ES004763

Date : 25/02/2020  
 Vehicle Num : SJB E315 E  
 Make/Model : BMW 318i-2015  
 Chassis/Engl : WBAHE36080NT39344  
 Accident Date : 04/02/2020  
 Claim No. :  
 Reference : KC/TP5315/2000-01  
 Policy No. :

*Not Notified  
 L1 Reg B 235ch  
 Repairing After Paint  
 Glass*

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1 PC	REAR BUMPER		
2.	1 PC	REAR BUMPER RETAINER		
3.	2 PCS	REAR BUMPER BRACKET		
4.	1 PC	REAR BUMPER REINFORCEMENT		
5.	1 PC	REAR BUMPER TOW COVER		
6.	2 PCS	REAR BUMPER RETAINER		
7.	6 PCS	REAR BUMPER CLIP		
8.	1 PC	REAR BUMPER INNER CENTER GARNISH		
9.	1 PC	REAR BUMPER LOWER DUST COVER		
10.	4 PCS	REAR BUMPER LOWER DUST COVER CLIPS		
11.	1 PC	REAR END PANEL		

Bumper	1,199.63	✓
Sub	61.00	X
81.26	162.48	X
383.53		✓
96.74		✓
Sub	55.64	X
13.50	81.00	✓
	100.35	✓
	254.70	✓
13.50	54.00	✓
	740.22	X
List Total S\$ :	3,246.93	
5.00% Discount S\$ :	162.35	
	3,084.58	

1.	1 SET	SPECIAL NETT ITEMS : REVERSE SENSOR		
----	-------	--	--	--

Per 486.80 X  
 486.80

Special Nett Total S\$ :

LABOUR :

TO PULL, KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART. 680.00 *30d*

TO SPRAY & PAINT ON REAR ACCIDENT PORTION. 850.00 *45d*

CONTINUE / ...

*To: MR KENNETH  
 From: Kum Chew*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before (re) spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

# KUM CHEW MOTOR WORKSHOP

160, SIN MING DRIVE #05-08  
 SIN MING AUTOCITY, SINGAPORE 575722.  
 Tel No. : 64536256/64563715 Fax No. : 64557754  
 E-Mail : kumchew1@singnet.com.sg  
 GST Reg.No. : M90367665T Buss. Reg. No. : 52835130K

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD  
 3, ANSON ROAD #16-00  
 SPRINGLEAF TOWER, SINGAPORE 079909.  
 claimsdept@sg.cntaiping.com  
 Attention : Motor Claim Department  
 Contact : 63896111 Fax No. : 62221033

## Estimate : ES004768

Date : 25/02/2020  
 Vehicle Num. : SJB 5315 E  
 Make/Model : BMW 318i-2015  
 Chassis/Eng# : WBAUE36080NT39344  
 Accident Date : 04/02/2020  
 Claim No. :  
 Reference : KC/TP5315/2002-01  
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO ANTI-RUST REAR AFFECTED AREAS.		80.00 <i>X</i>
		TO CHECK WIRING FUNCTIONS & RE-WIRING.		65.00 <i>201</i>
		TO DISMANTLE & REPLACE REVERSE SENSOR.		80.00 <i>501</i>
		TO RESET, DIAGNOSTIC AND PROGRAMME REVERSE SENSOR.		150.00 <i>801</i>
		Labour Total S\$ :		1,905.00

SingDollars : Five Thousand Four Hundred Seventy-Six & Cents Thirty-Eight Only

Total S\$ : 5,476.38

KUM CHEW MOTOR WORKSHOP

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20002232/KSF3N2  
**Date:** 03/03/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMHCSNA00000782000  
 Claimant Vehicle No: SJB5315E Insured Vehicle No: SJX5445Y  
 Date of Loss: 04/02/2020 Nature of Claim: TP Claim No: SNM20D200677C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJB5315E**  
 Make & Model: BMW 318i, 1.5 (A) Engine No: F3851263B38B15A  
 Reg. Date: 02/03/2016 (Man. Year: 2015) Chassis No: WBA8E36080NT39344  
 Colour: Metallic White Odometer: 60701 km  
 Engine Capacity: 1499 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55R16 Rear Tyre Size: 225/55R16  
 Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm  
 Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %	
Parts	3,571.38	2,063.35	1,508.03	42.23	
Miscellaneous Items	0.00	0.00	0.00		
Labour	1,905.00	900.00	1,005.00	52.76	
Paintwork Labour	0.00	0.00	0.00		
Towing	0.00	0.00	0.00		
<b>Calculated Gross Total (S\$)</b>	<b>5,476.38</b>	<b>2,963.35</b>	<b>2,513.03</b>	<b>45.89</b>	
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>			
	(S\$)	5,476.38	2,350.00	3,126.38	57.09
	<b>+ GST 7.00/7.00% (S\$)</b>	383.35	164.50	218.85	57.09
	<b>Nett Amount (S\$)</b>	<b>5,859.73</b>	<b>2,514.50</b>	<b>3,345.23</b>	<b>57.09</b>

### INSPECTION

Date of Assignment: 02/03/2020  
 Date Inspected: 10/02/2020 Inspected At: Kum Chew Motor Workshop (160 Sin Ming) (HQ)  
 160 Sin Ming Drive, #05-08 Sin Ming Autocity  
 Singapore 575722  
 Estimated Period of Repair: 4.0 days

**Adjuster:** KENNETH KONG

**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

**REPAIR DETAILS****Reference**

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 03 Mar 2020)
<b>Parts:</b> 143	BMW 318i 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJB5315E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

**Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/Cracked	1,199.63 FL	*1,199.63 FL
2	1		*REAR BUMPER RETAINER	Serviceable	61.00 FL	*- FL
3	2		*REAR BUMPER BRACKET	Serviceable	162.48 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	383.53 FL	*383.53 FL
5	1		*REAR BUMPER TOW COVER	Dented	98.74 FL	*98.74 FL
6	2		*REAR BUMPER RETAINER	Serviceable	111.28 FL	*- FL
7	6		*REAR BUMPER CLIP	Missing	81.00 FL	*81.00 FL
8	1		*REAR BUMPER INNER CENTER GARNISH	Cracked	100.35 FL	*100.35 FL
9	1		*REAR BUMPER LOWER DUST COVER	Cracked	254.70 FL	*254.70 FL
10	4		*REAR BUMPER LOWER DUST COVER CLIPS	Necessary	54.00 FL	*54.00 FL
11	1		*REAR END PANEL	Repair	740.22 FL	*- FL
12	1		*SET REVERSE SENSOR	Serviceable	486.80 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,733.73</b>	<b>2,171.95</b>
<b>- List Item Discount on L Items 5.00/5.00% (\$\$)</b>	162.35	108.60
<b>Total Parts (\$\$)</b>	<b>3,571.38</b>	<b>2,063.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO PULL,KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART	New	680.00	300.00
2	TO SPRAY & PAINT ON REAR ACCIDENT PORTION	New	850.00	450.00
3	TO ANTI-RUST REAR AFFECTED AREAS	New	80.00	0.00
4	TO CHECK WIRING FUNCTIONS & RE-WIRING	New	65.00	20.00
5	TO DISMANTLE & REPLACE REVERSE SENSOR	New	80.00	50.00
6	TO RESET DIAGNOSTIC AND PROGRAMME REVERSE SENSOR	New	150.00	80.00
<b>Gross Labour Cost (S\$)</b>			<b>1,905.00</b>	<b>900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >