

ASS. REC. BY

REF: CS/CTI 20002238/Ey f302

Special Instructions:

Surveyor

Steve

ASSIGNMENT (Office)

From (Person):

Adeline chng

of

CTI

Date/Time:

10.2.2020 11.20am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 63644

Insured:

GBH 9229H

at Workshop n/s

Z-one Automotive

Tel:

6630212

of

1 Kaki Bukit Ave 6 #101-85/87 Autobay

Policy No:

DMEVSR30736019000

Claim No:

SNM2017200667

Sum Insured:

Excess:

Make of Veh:

D.O.A.

5.2.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

Mup

H.O.D. Endorsement:

Date/Time:

10/2/2020 11.42am

Person Contacted:

Syarifah

Vehicle

IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 63644 - NH/CTI 20001931/r3 D.O.A - 05/01/2020
	GBH 9229H - NH/CTI 20001921/r3 D.O.A - 05/01/2020

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Rpt	Adj. Submitted	Ins. Auth'd	Status
Main	07 Feb 2020		10 Feb 2020 11:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:									
Main Claimant:	ISLANTIS PTE LTD, Co. Reg. No.: 201536922M								
Vehicle Reg. No.:	GBH6364U	Date of Loss:	05/02/2020 08:00 - :59						
Claim Type:	TP / SNM20D200667C02	Policy/Cover Note No.:	DMCVSN30736019000						
Vehicle Reg. No. (Insured):	GBH9229H	Policy No. (Claimant):	5111802277						
		Excess:	S\$350.00						
Repairer:	Z-One Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, Bldg D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6634 2112								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 19/02/2020]								
Adj. Asg. Remarks:	survey revert								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Steve Chen (LKK Auto)

From: Nur Syafirah <service@z-one.com.sg>
Sent: Tuesday, February 18, 2020 3:28 PM
To: Steve Chen (LKK Auto); enquiry@z-one.com.sg
Subject: Re: GBH6364U - Finalize

Dear Steve,

We confirm to **accept** the finalize lump sum of **\$9650.00** before GST.

Thank you!

Best Regards,

Nur Syafirah
Z-One Automotive Pte Ltd
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883
Tel: 66342112 Fax: 6634 2122

From: Steve Chen (LKK Auto)
Sent: Tuesday, February 18, 2020 9:54 AM
To: Yvonne Yong ; enquiry@z-one.com.sg
Subject: GBH6364U - Finalize

Dear Sir,

Kindly refer our finalize \$9650 (L/S, before GST). 7 repair days.

Kindly confirm.

Thanks.

Best Regards,
Steve Chen | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: SteveChen@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Summer Lee (LKK Auto)

From: Adeline Chng <adeline.chng@sg.cntaiping.com>
Sent: Monday, 10 February, 2020 11:26 AM
To: assignments@lkkauto.com
Cc: Nur Syafirah; Irene Tay; Claims Dept of CTI
Subject: FW: OUR REF : SNM20D200667/GBH9229H/ADELINE - PRS - ACCIDENT INVOLVING VEHICLES GBH6364U, GBH9229H & SMA8047D ALONG TPE TWDS PASIR RIS BEFORE TAMPINES AVE 10 EXIT ON 05/02/2020 AT 0830HRS

Without Prejudice

Dear Lkk

Please refer to below email and liaise with Third Party Workshop.

Thank you.

Adeline Chng
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

-----Original Message-----

From: Nur Syafirah [mailto:service@z-one.com.sg]
Sent: Friday, 7 February 2020 2:28 PM
To: Adeline Chng <adeline.chng@sg.cntaiping.com>; Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: OUR REF : SNM20D200667/GBH9229H/ADELINE - PRS - ACCIDENT INVOLVING VEHICLES GBH6364U, GBH9229H & SMA8047D ALONG TPE TWDS PASIR RIS BEFORE TAMPINES AVE 10 EXIT ON 05/02/2020 AT 0830HRS

Dear Adeline,

As spoken, kindly appoint LKK for the PRS.

Vehicle is already in the workshop.

Thank you!

Best Regards,

Nur Syafirah
Z-One Automotive Pte Ltd
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883
Tel: 66342112 Fax: 6634 2122

From: Adeline Chng
Sent: Friday, February 7, 2020 2:21 PM
To: Claims Dept of CTI ; service@z-one.com.sg
Subject: RE: OUR REF : SNM20D200667/GBH9229H/ADELINE - PRS - ACCIDENT INVOLVING VEHICLES GBH6364U, GBH9229H & SMA8047D ALONG TPE TWDS PASIR RIS BEFORE TAMPINES AVE 10 EXIT ON 05/02/2020 AT 0830HRS

Without Prejudice

Dear Sirs

We refer to your email of 06/02/2020 pertaining to the above matter.

Attached herewith PRS letter for your next action.

Thank you.

Adeline Chng

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6155 | F: (65) 6222 1033

W: www.sg.cntaiping.com <<http://www.sg.cntaiping.com/>> | FB: www.facebook.com/chinataipingsg/
<<http://www.facebook.com/chinataipingsg/>> | WeChat: 太平獅城 Taiping SG

From: Claims Dept of CTI
Sent: Friday, 7 February 2020 11:01 AM
To: service@z-one.com.sg; Adeline Chng <adeline.chng@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: OUR REF : SNM20D200667/GBH9229H/ADELINE - PRS - ACCIDENT INVOLVING VEHICLES GBH6364U, GBH9229H & SMA8047D ALONG TPE TWDS PASIR RIS BEFORE TAMPINES AVE 10 EXIT ON 05/02/2020 AT 0830HRS

Dear Adeline,

Please conduct PRS for GBH6364U.

Note : officer in charge – Adeline 63896155.

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6116 | F: (65) 6222 1033

W: www.sg.cntaiping.com <<http://www.sg.cntaiping.com/>> | FB: www.facebook.com/chinataipingsg/
<<http://www.facebook.com/chinataipingsg/>> | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or

partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Nur Syafirah <service@z-one.com.sg>
Sent: Thursday, February 6, 2020 12:41 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>
Cc: Sya Z1 <enquiry@z-one.com.sg>
Subject: (DS) PRS TO BE ARRANGE @ Z-ONE / ACCIDENT INVOLVING VEHICLES GBH6364U, GBH9229H & SMA8047D
ALONG TPE TWDS PASIR RIS BEFORE TAMPINES AVE 10 EXIT ON 05/02/2020 AT 0830HRS

Dear Sir /Mdm,

Kindly find the attached PRS Request for your kind attention.

Please do send us the list of your 10 surveyor for us to choose.

Do revert back to us at the soonest.

For any further clarifications, kindly contact Sya @ 66342112.

Thank you!

Best Regards,

Nur Syafirah
Z-One Automotive Pte Ltd
1 Kaki Bukit Ave 6, #01-85/87 Autobay @ Kaki Bukit Singapore 417883
Tel: 66342112 Fax: 6634 2122

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/02/2020 17:11
Date Of Accident	05/02/2020 08:30
Exact Location Of Accident	TPE TWDS PASIR RIS BEFORE TAMPINES AVE 10 EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH6364U
Insured/Policyholder	
Name Of Registered Owner	ISLANTIS PTE LTD
Co Reg No	2XXXXX922M
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-94750100

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5111802277
Cover Note Number	

Driver

Name of Driver	ONG THIAM TENG
NRIC No	SXXXXX400B
Date Of Birth	15/01/1971
Occupation	OUTDOOR
Date Of Driving Pass	17/04/1991
Driving Experience	28 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94750100
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 743 WOODLANDS CRICLE #03-455
Postcode	730743
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	3
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON THE STATED DATE AND TIME, AT THE STATED VENUE, MY VEHICLE A (GBH6364U) WAS TRAVELLING STRAIGHT ON MY RIGHTFUL LANE. VEHICLE C (SMA8047D) IN FRONT OF ME STOPPED. SO, I FOLLOWED SUIT. MOMENTS LATER, I FELT A GREAT IMPACT ON THE REAR PORTION OF MY STATIONARY VEHICLE. VEHICLE B (GBH9229H) COULD NOT MAKE IT TO STOP HENCE COLLIDED ONTO THE REAR PORTION OF MY VEHICLE CAUSING MY VEHICLE TO PROPEL FORWARD AGAINST VEHICLE C.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBH9229H
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SMA8047D
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE C
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	ONG THIAM TENG
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBH6364U
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/Fin No.:

2 ONE

SKETCH PLAN TPE towards Pasir Ris before Tampines Ave 10 Exit



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On the stated date and time at the stated venue, my vehicle 'A' GBH 6364U was travelling straight on my rightful lane. Vehicle 'C' SMA 8047D in front of me stopped so I followed suit. Moments later, I felt a great impact on the rear portion of my stationary vehicle. Vehicle 'B' GBH 9229H could not make it to stopped, hence collided onto the rear portion of my vehicle causing my vehicle to propel forward against vehicle 'C'.

DECLARATION

I/We hereby declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	922M
Vehicle Details	
Vehicle No.:	GBH6364U
Vehicle to be Exported:	No
Intended Deregistration Date:	10 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE DX 2.8 AUTO
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1GD8298391
Chassis No.:	GDH2011008962
Maximum Power Output:	-
Open Market Value:	\$33,799.00
Original Registration Date:	13 Aug 2018
First Registration Date:	13 Aug 2018
Transfer Count:	0
Actual ARF Paid:	\$1,690.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	12 Aug 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$28,002.00
COE Rebate Amount:	\$23,816.00
Total Rebate Amount:	\$23,816.00

The information contained herein is correct as at 10 Feb 2020

OK



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

ESTIMATE

Islandis Pte Ltd
743 Woodlands Circle #03-455 Singapore 730743

Contact : 94750100

Code : C101966

Date in : 05/02/2020

Vehicle Num. : GBH6364U

Model : Toyota Hiace DX 2.8 Auto

Chassis/Eng# : GDH2011008962/1GD8298391

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
Aircon condensor ? / DO	1	1488.00	1,488.00 856 ✓
Front bonnet / DO	1	825.50	825.50 ✓
Front bonnet emblem 'LOGO' / MC	1	126.87	126.87 60 ✓
Front bonnet hinge RH/LH X NN	2	65.90	131.80 X
Front bonnet rubber seal RH/LH X NN	2	51.20	102.40 X
Front bumper / CRA	1	673.45	673.45 486 ✓
Front bumper lower center grille X / BR	1	393.40	393.40 200 ✓
Front bumper reinforcement X NN	1	497.10	497.10 X
Front bumper reinforcement bracket RH/LH X NN	2	155.60	311.20 X
Front bumper side retainer RH/LH / DR	2	124.10	248.20 ✓
Front bumper top beam ? / DT	1	232.60	232.60 ✓
Front bumper top beam bracket RH/LH ? X NN	2	201.10	402.20 X
Front bumper tow cover X NN	1	40.20	40.20 X
Front grille bottom ? / CRA	1	490.80	490.80 315 ✓
Front grille inner ? / CRA	1	410.35	410.35 ✓
Front grille millimeter wave sensor ? X NN	1	1403.19	1,403.19 X
Front grille top ? / CRA	1	435.10	435.10 245 ✓



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

Front headlamp RH/LH	✓ DR	2	2483.42	554.10	4,966.84	1199.60	✓
Front support panel	? / DO	1	760.25		760.25		✓
Front support panel garnish RH/LH	? (RH) TAI	1	110.20		220.40	110.20	✓
Front support panel top garnish	? X NN	1	215.60		215.60		X
Radiator	X NN	1	1987.60		1,987.60		X
Radiator spare tank	X NN	1	399.10		399.10		X
Rear bumper	✓ CRH	1	422.64		422.64		✓
Rear bumper lower brackets	? / BT	4	51.70		206.80		✓
Rear bumper reinforcement	X NN	1	311.00		311.00		X
Rear bumper side holders	✓ DR	2	40.70		81.40		✓
Rear end panel	? / DO	1	422.07		422.07		✓
Rear end panel top moulding	? / BT	1	156.10		156.10		✓
Rear floor panel	X R	1	1700.60		1,700.60		X
Rear side panel	(RH) X CRH R	1	1415.80		1,415.80		X
Rear spare tyre carriage	X NAI	1	312.70		312.70		X
Rear spare tyre lock catch	X NN	1	110.35		110.35		X
Rear tailgate	✓ DO	1	2179.24		2,179.24	2072	✓
Rear tailgate 'HIACE' sticker	✓ MC	1	40.77		40.77		✓
Rear tailgate dampers	X NN	2	149.80		299.60		X
Rear tailgate inner board	? / TN	1	211.60		211.60		✓



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Rear tailgate lock	✓ BT	1	422.60	422.60	182 ✓
Rear tailgate lock catch	X NN	1	103.20	103.20	X
Rear tailgate lock cover	? / CRA	1	70.60	70.60	✓
Rear tailgate logo	✓ MC	1	61.70	61.70	✓
Rear tailgate outer garnish	X NN	1	159.20	159.20	X
Rear tailgate rubber	? / TN	1	401.79	401.79	281 ✓
Rear taillamp filter panel	(RH) / DO	1	487.90	487.90	187.49 ✓
Rear taillamp lower garnishes	(RH) / CR	2	104.70	209.40	104.70 ✓
Rear taillamps	(RH) / BR	2	289.95	579.90	289.95 ✓
Turbo inter cooler	? / DO	1	1514.95	1,514.95	1211 ✓
Washer tank	X NN	1	110.95	110.95	X
Subtotal before discount				28,755.01	11,955.4
Percentage discount 25%				7,188.75	-75%
Sub-total 1				21,566.28	8966.57
Rear camera (set)(sn)	X NN	1	450.00	450.00	X
Rear LED light (sn)	X NN	1	180.00	180.00	X
Rear reverse sensor (set)(sn)	✓ MC	1	280.00	280.00	280 ✓
Rear tailgate '70km/h' sticker (sn)	✓ MC	1	25.00	25.00	✓
Rear tailgate '8Pax' sticker (sn)	✓ MC	1	25.00	25.00	✓
Rear windscreen seal (sn)	✓ MC	1	85.00	85.00	30 ✓



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Rear windscreen sealant (sn)	1	80.00	80.00	40
Subtotal before discount			1,125.00	
Percentage discount 0%			0.00	
Sub-total 2			1,125.00	320
Parts-total			22,691.26	

LABOUR

Description	Price
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	150.00 30
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	150.00 X
To remove, refix / renew reverse sensor assy and rectify for proper functioning.	130.00 20
To remove, refix / renew reverse camera assy	140.00 30
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	180.00 X
To remove, reinstall rear tailgate windscreen (to FR)	160.00 120
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,800.00 850
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,200.00 1300
Labour Total	4,910.00
Parts & Labour Total	27,601.26 2350


14/2/2020
Steve (LKK)
8322 8813
Stevechn@lkkath.com

ML PL
10/2/20, 3:00pm
7 dy
L/S
R/L/S

27408.91

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Z-ONE AUTOMOTIVE PTE LTD

1 Kall Bukit Ave 6, Blk D #01-85/87, Autobay@Kall Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE  PERFORMANCE Company Registration No. 201118055N

ESTIMATE

Islands Pte Ltd
743 Woodlands Circle #03-455 Singapore 730743

Contact : 94750100

Code : C101966

Date in : 05/02/2020

Vehicle Num. : GBH6364U

Model : Toyota Hiace DX 2.8 Auto

Chassis/Eng# : GDH2011006962/1GD8298391

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
Aircon condensor <i>Pux ✓</i>	1	1488.00	1,488.00
Front bonnet <i>/ 00</i>	1	825.50	825.50
Front bonnet emblem 'LOGO' <i>/ AC</i>	1	126.87	126.87
Front bonnet hinge RH/LH <i>X</i>	2	65.90	131.80
Front bonnet rubber seal RH/LH <i>X</i>	2	51.20	102.40
Front bumper <i>/ CRH</i>	1	673.45	673.45
Front bumper lower center grille <i>X / BR</i>	1	393.40	393.40
Front bumper reinforcement <i>X</i>	1	497.10	497.10
Front bumper reinforcement bracket RH/LH <i>X</i>	2	155.60	311.20
Front bumper side retainer RH/LH <i>/ OR</i>	2	124.10	248.20
Front bumper top beam <i>BR ✓</i>	1	232.60	232.60
Front bumper top beam bracket RH/LH <i>X</i>	2	201.10	402.20
Front bumper tow cover <i>X</i>	1	40.20	40.20
Front grille bottom <i>Can ✓</i>	1	490.80	490.80
Front grille inner <i>Can ✓</i>	1	410.35	410.35
Front grille millimeter wave sensor <i>X</i>	1	1403.19	1,403.19
Front grille top <i>Can ✓</i>	1	435.10	435.10



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-S5/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

Front headlamp RH/LH / DR	2	2483.42	4,966.84
Front support panel Bl ✓	1	760.25	760.25
Front support panel garnish RH/LH RH 701 ✓	2	110.20	220.40
Front support panel top garnish X	1	215.60	215.60
Radiator X	1	1987.60	1,987.60
Radiator spare tank X	1	399.10	399.10
Rear bumper / CR ✓	1	422.64	422.64
Rear bumper lower brackets Bl ✓	4	51.70	206.80
Rear bumper reinforcement X	1	311.00	311.00
Rear bumper side holders / DR	2	40.70	81.40
Rear end panel DD ✓	1	422.07	422.07
Rear end panel top moulding R ✓	1	156.10	156.10
Rear floor panel X R	1	1700.60	1,700.60
Rear side panel (RH) X LH R	1	1415.80	1,415.80
Rear spare tyre carriage X	1	312.70	312.70
Rear spare tyre lock catch X	1	110.35	110.35
Rear tailgate / DR	1	2179.24	2,179.24
Rear tailgate 'HIACE' sticker / MC	1	40.77	40.77
Rear tailgate dampers X	2	149.80	299.60
Rear tailgate inner board 701 ✓	1	211.60	211.60



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE PERFORMANCE Company Registration No. 201118055N

Rear tailgate lock	✓ BT	1	422.60	422.60
Rear tailgate lock catch	X	1	103.20	103.20
Rear tailgate lock cover	One ✓	1	70.60	70.60
Rear tailgate logo	✓ MC	1	61.70	61.70
Rear tailgate outer garnish	X	1	159.20	159.20
Rear tailgate rubber	One ✓	1	401.79	401.79
Rear taillamp filter panel	RY RD ✓	1	487.90	487.90
Rear taillamp lower garnishes	(RY) / (RD)	2 / 1	104.70	209.40
Rear taillamps	(RY) / BR	2 / 1	269.95	579.90
Turbo inter cooler	SPU ✓	1	1514.95	1,514.95
Washer tank	X	1	110.95	110.95

Subtotal before discount

28,755.01

Percentage discount 25%

7,188.75

Sub-total 1

21,566.26

Rear camera (set)(sn)	X	1	450.00	450.00
Rear LED light (sn)	X	1	180.00	180.00
Rear reverse sensor (set)(sn)	✓ MC SL	1	280.00	280.00
Rear tailgate '70km/h' sticker (sn)	✓ MC	1	25.00	25.00
Rear tailgate '6Pax' sticker (sn)	✓ MC	1	25.00	25.00
Rear windscreen seal (sn)	✓ MC	1	85.00	85.00

page 3



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg ; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE

Company Registration No. 201118055N

Rear windscreen sealant (sn) / ml	1	80.00	80.00	40
Subtotal before discount			1,125.00	
Percentage discount 0%			0.00	
Sub-total 2			1,125.00	
Parts-total			22,591.26	

LABOUR

Description	Price
To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)	150.00 30
Diagnose, replace and/or repair to rectify rear portion electrical system for proper functioning.	150.00 X
To remove, refix / renew reverse sensor assy and rectify for proper functioning.	130.00 20
To remove, refix / renew reverse camera assy	140.00 30
Diagnose, replace and/or repair to rectify front portion electrical system for proper functioning.	180.00 X
To remove, reinstall rear tailgate windscreen (to FR)	160.00 120
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	1,800.00 850
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2,200.00 1300
Labour Total	4,910.00
Parts & Labour Total	27,501.26

page 4

Star (LKK)
8322 8813
Stevchn@1KKath.com

mt PL
10/2/20. 3:00pm
7 dy
L/S
Ry L Sy



Z-ONE AUTOMOTIVE PTE LTD

1 Kaki Bukit Ave 6, Blk D #01-85/87, Autobay@Kaki Bukit Singapore 417883

Tel: 62502115/66342112 Fax: 66342122

Email: service@z-one.com.sg; enquiry@z-one.com.sg

AUTOMOTIVE • PERFORMANCE Company Registration No. 201118055N

ESTIMATE

Islandis Pte Ltd
743 Woodlands Circle
#03-455
Singapore 730743

Code : C101966
Date In: 5/2/2020
Vehicle Num. : GBH6364U
Model : Toyota Hiace DX 2.8 Auto
Chassis/ Eng # : GDH2011008962/ 1GD8298391

Contact:

Supplementary for Estimate Items

Description of part	Qty	Unit Price	Amount
FRONT BONNET LOCK <i>7w.</i>	1		139.50
FRONT BUMPER SIDE GARNISH RH <i>de</i>	1		61.40
REAR BUMPER STEEP PANEL <i>gert</i>	1	<i>54</i>	329.30

Subtotal 530.20
Percentage discount 25% 132.55

Sub-total \$ 397.65

Parts total \$ 397.65

P- 8966.57
N- 320
L- 2350
Supp- 397.65
12,034.72
L/S- 9627.37
= 9650

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Feb 2020		10 Feb 2020 11:35 Edit Adj Rpt	S\$9,650.00 Edit Estimates	S\$9,650.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ISLANTIS PTE LTD , Co. Reg. No.: 201536922M								
Vehicle Reg. No.:	GBH6364U	Date of Loss:	05/02/2020 08:00 - :59 [17 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200667C02	Policy/Cover Note No.:	DMCV5N30736019000						
Vehicle Reg. No. (Insured):	GBH9229H	Policy No. (Claimant):	5111802277						
		Excess:	S\$350.00						
Repairer:	Z-One Automotive Pte Ltd (HQ) 1 Kaki Bukit Avenue 6, Blk D #01-87, Autobay @ Kaki Bukit, 417883 Kaki Bukit - Tel: 6634 2112								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 19/02/2020]								
Adj Asg. Remarks:	survey revert								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH6364U (SNM20D200667C02)
[GBH9229H]
TP
ISLANTIS PTE LTD
Feb 5 2020 8:00AM
[-]
Z-One Automotive Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print					
1	05/02/20 17:33	Accident Statement			Load HTM					
2	07/02/20 11:05	Addendum Sheet			Load TIF					
3	07/02/20 11:06	Accident Statement Addm. #1			Load HTM					
Photos/Images							3 per page		☒	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print					
1	05/02/20 17:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
2	05/02/20 17:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
3	05/02/20 17:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
4	05/02/20 17:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
5	05/02/20 17:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
6	05/02/20 17:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
7	05/02/20 17:33	Accident Photo [Linked Accident Report Documents]			Load JPG		☒			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	10/02/20 17:29	General View			Load JPG		☒			
2	10/02/20 17:29	General View			Load JPG		☒			
3	10/02/20 17:29	General View			Load JPG		☒			
4	10/02/20 17:29	General View			Load JPG		☒			
5	10/02/20 17:29	General View			Load JPG		☒			
6	10/02/20 17:29	General View			Load JPG		☒			
7	10/02/20 17:29	General View			Load JPG		☒			
8	10/02/20 17:29	General View			Load JPG		☒			
9	10/02/20 17:29	General View			Load JPG		☒			
10	10/02/20 17:29	General View			Load JPG		☒			
11	10/02/20 17:29	General View			Load JPG		☒			
12	10/02/20 17:29	General View			Load JPG		☒			
13	10/02/20 17:29	General View			Load JPG		☒			
14	10/02/20 17:29	General View			Load JPG		☒			
15	10/02/20 17:29	General View			Load JPG		☒			
16	10/02/20 17:29	General View			Load JPG		☒			
17	10/02/20 17:29	General View			Load JPG		☒			
18	10/02/20 17:29	Odometer Reading			Load JPG		☒			
19	10/02/20 17:29	General View			Load JPG		☒			
20	10/02/20 17:29	General View			Load JPG		☒			
21	10/02/20 17:29	General View			Load JPG		☒			
22	10/02/20 17:29	General View			Load JPG		☒			

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
23	10/02/20 17:29	General View	 Load JPG	☒
24	10/02/20 17:29	General View	 Load JPG	☒
25	10/02/20 17:30	Chassis Number	 Load JPG	☒
26	10/02/20 17:30	General View	 Load JPG	☒
27	10/02/20 17:30	General View	 Load JPG	☒
28	10/02/20 17:30	General View	 Load JPG	☒
29	10/02/20 17:30	General View	 Load JPG	☒
30	10/02/20 17:30	General View	 Load JPG	☒
31	10/02/20 17:30	General View	 Load JPG	☒
32	10/02/20 17:30	General View	 Load JPG	☒
33	10/02/20 17:30	General View	 Load JPG	☒
34	10/02/20 17:30	General View	 Load JPG	☒
35	10/02/20 17:30	General View	 Load JPG	☒
36	10/02/20 17:30	General View	 Load JPG	☒
37	10/02/20 17:30	General View	 Load JPG	☒
38	10/02/20 17:30	General View	 Load JPG	☒
39	10/02/20 17:30	General View	 Load JPG	☒
40	10/02/20 17:30	General View	 Load JPG	☒
41	10/02/20 17:30	General View	 Load JPG	☒
42	10/02/20 17:30	General View	 Load JPG	☒
43	10/02/20 17:30	General View	 Load JPG	☒
44	10/02/20 17:30	General View	 Load JPG	☒
45	10/02/20 17:30	General View	 Load JPG	☒
46	10/02/20 17:30	General View	 Load JPG	☒
47	10/02/20 17:30	General View	 Load JPG	☒
48	10/02/20 17:30	General View	 Load JPG	☒
49	10/02/20 17:30	General View	 Load JPG	☒
50	10/02/20 17:30	General View	 Load JPG	☒
51	10/02/20 17:30	General View	 Load JPG	☒
52	10/02/20 17:30	General View	 Load JPG	☒
53	10/02/20 17:30	General View	 Load JPG	☒
54	10/02/20 17:30	General View	 Load JPG	☒
55	10/02/20 17:30	General View	 Load JPG	☒
56	10/02/20 17:30	General View	 Load JPG	☒
57	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
58	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
59	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
60	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
61	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
62	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
63	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
64	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
65	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
66	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
67	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
68	18/02/20 09:12	Photographs of Damaged Parts	 Load JPG	☒
69	18/02/20 09:12	Photographs of Damaged Parts	Load JPG	☒
70	18/02/20 09:12	Photographs of Damaged Parts	Load JPG	☒
71	18/02/20 09:12	Photographs of Damaged Parts	Load JPG	☒
72	18/02/20 09:12	Photographs of Damaged Parts	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
73	18/02/20 09:12	Photographs of Damaged Parts		☒
74	18/02/20 09:12	Photographs of Damaged Parts		☒
75	18/02/20 09:12	Photographs of Damaged Parts		☒
76	18/02/20 09:12	Photographs of Damaged Parts		☒
77	18/02/20 09:12	Photographs of Damaged Parts		☒
78	18/02/20 09:12	Photographs of Damaged Parts		☒
79	18/02/20 09:12	Photographs of Damaged Parts		☒
80	18/02/20 09:12	Photographs of Damaged Parts		☒
81	18/02/20 09:12	Photographs of Damaged Parts		☒
82	18/02/20 09:12	Photographs of Damaged Parts		☒
83	18/02/20 09:12	Photographs of Damaged Parts		☒
84	18/02/20 09:12	Photographs of Damaged Parts		☒
85	18/02/20 09:12	Photographs of Damaged Parts		☒
86	18/02/20 09:12	Photographs of Damaged Parts		☒
87	18/02/20 09:12	Photographs of Damaged Parts		☒
88	18/02/20 09:12	Photographs of Damaged Parts		☒
89	18/02/20 09:12	Photographs of Damaged Parts		☒
90	18/02/20 09:12	Photographs of Damaged Parts		☒
91	18/02/20 09:12	Photographs of Damaged Parts		☒
92	18/02/20 09:12	Photographs of Damaged Parts		☒
93	18/02/20 09:12	Photographs of Damaged Parts		☒
94	18/02/20 09:12	Photographs of Damaged Parts		☒
95	18/02/20 09:12	Photographs of Damaged Parts		☒
96	18/02/20 09:12	Photographs of Damaged Parts		☒
97	18/02/20 09:12	Photographs of Damaged Parts		☒
98	18/02/20 09:12	Photographs of Damaged Parts		☒
99	18/02/20 09:12	Photographs of Damaged Parts		☒
100	18/02/20 09:12	Photographs of Damaged Parts		☒
101	18/02/20 09:12	Photographs of Damaged Parts		☒
102	18/02/20 09:12	Photographs of Damaged Parts		☒
103	18/02/20 09:12	Photographs of Damaged Parts		☒
104	18/02/20 09:12	Photographs of Damaged Parts		☒
105	18/02/20 09:12	Photographs of Damaged Parts		☒
106	18/02/20 09:12	Photographs of Damaged Parts		☒
107	18/02/20 09:12	Photographs of Damaged Parts		☒
108	18/02/20 09:12	Photographs of Damaged Parts		☒
109	18/02/20 09:12	Photographs of Damaged Parts		☒
110	18/02/20 09:12	Photographs of Damaged Parts		☒
111	18/02/20 09:12	Photographs of Damaged Parts		☒
112	18/02/20 09:12	Photographs of Damaged Parts		☒
113	18/02/20 09:12	Photographs of Damaged Parts		☒
114	18/02/20 09:12	Photographs of Damaged Parts		☒
115	18/02/20 09:12	Photographs of Damaged Parts		☒
116	18/02/20 09:12	Photographs of Damaged Parts		☒
117	18/02/20 09:12	Photographs of Damaged Parts		☒
118	18/02/20 09:12	Photographs of Damaged Parts		☒
119	18/02/20 09:12	Photographs of Damaged Parts		☒
120	18/02/20 09:12	Photographs of Damaged Parts		☒
121	18/02/20 09:12	Photographs of Damaged Parts		☒
122	18/02/20 09:12	Photographs of Damaged Parts		☒

Assessment Reports				1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
123	18/02/20 09:12	Photographs of Damaged Parts		Load JPG	☒
124	18/02/20 09:12	Photographs of Damaged Parts		Load JPG	☒
125	18/02/20 09:12	Photographs of Damaged Parts		Load JPG	☒
126	18/02/20 09:12	After Repair Photo		Load JPG	☒
127	18/02/20 09:12	After Repair Photo		Load JPG	☒
128	18/02/20 09:12	After Repair Photo		Load JPG	☒
129	18/02/20 09:12	After Repair Photo		Load JPG	☒
130	18/02/20 09:12	After Repair Photo		Load JPG	☒
131	18/02/20 09:12	After Repair Photo		Load JPG	☒
Documentation				1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	10/02/20 11:36	Singapore Accident Statement		Load PDF	
2	10/02/20 11:36	Pre-Repair Survey		Load PDF	
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	05/02/20 17:28	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	05/02/20 17:28	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	05/02/20 17:28	Driving License [Linked Accident Report Documents]		Load TIF	
4	05/02/20 17:28	CI [Linked Accident Report Documents]		Load TIF	
5	07/02/20 11:06	POLICE REPORT [Linked Accident Report Documents]		Load TIF	
6	07/02/20 11:06	POLICE REPORT [Linked Accident Report Documents]		Load TIF	
7	07/02/20 11:06	POLICE REPORT [Linked Accident Report Documents]		Load TIF	
8	07/02/20 11:06	POLICE REPORT [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

Assessment Reports				1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	05/02/20 17:33	Accident Statement		Load HTM	
2	07/02/20 11:05	Addendum Sheet		Load TIF	
3	07/02/20 11:06	Accident Statement Addm. #1		Load HTM	
Photos/Images				3 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	05/02/20 17:33	Accident Photo		Load JPG	☒
2	05/02/20 17:33	Accident Photo		Load JPG	☒
3	05/02/20 17:33	Accident Photo		Load JPG	☒
4	05/02/20 17:33	Accident Photo		Load JPG	☒
5	05/02/20 17:33	Accident Photo		Load JPG	☒
6	05/02/20 17:33	Accident Photo		Load JPG	☒
7	05/02/20 17:33	Accident Photo		Load JPG	☒
Documentation				3 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)		Thumbnail	Print
1	05/02/20 17:28	Sketch Plan		Load TIF	
2	05/02/20 17:28	Sketch Plan #2		Load TIF	
3	05/02/20 17:28	Driving License		Load TIF	
4	05/02/20 17:28	CI		Load TIF	
5	07/02/20 11:06	POLICE REPORT		Load TIF	
6	07/02/20 11:06	POLICE REPORT		Load TIF	

Assessment Reports			1 per page	☒
No	Finalized On	SME Motor Pte Ltd (Kaki Bukit)	Thumbnail	Print
7	07/02/20 11:06	POLICE REPORT	 Load TIF	
8	07/02/20 11:06	POLICE REPORT	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002238/EYF3E2

Date: 20/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN30736019000

Claimant Vehicle
No: GBH6364UInsured Vehicle
No: GBH9229H

Date of Loss: 05/02/2020

Nature of Claim: TP

Claim
No: SNM20D200667C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH6364U

Make & Model: TOYOTA HIACE, 2.0 (M)

Reg. Date: 13/08/2018 (Man. Year: 2018)

Colour: Silver

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 1GD8298391

Chassis No: GDH2011008962

Odometer: 58890 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15

Rear Tyre Size: 195/80 R15

Front Left Side: Dunlop 5 mm

Rear Left Side: Dunlop 5 mm

Front Right Side: Dunlop 5 mm

Rear Right Side: Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	23,088.91	9,684.22	13,404.69	58.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,910.00	2,350.00	2,560.00	52.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,998.91	12,034.22	15,964.69	57.02
Approved Total (Overridden) (S\$)		9,650.00		
(S\$)	27,998.91	9,650.00	18,348.91	65.53
+ GST 7.00/7.00% (S\$)	1,959.92	675.50	1,284.42	65.53
Nett Amount (S\$)	29,958.83	10,325.50	19,633.33	65.53

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 10/02/2020 Inspected At:

Z-One Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6, Blk D #01-87,
Autobay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 20 Feb 2020)

Parts: N/A TOYOTA HIACE 2.0 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH6364U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*AIRCON CONDENSOR	Dented	1,488.00 FL	*856.00 FL
2	1	*FRONT BONNET	Dented	825.50 FL	*825.50 FL
3	1	*FRONT BONNET EMBLEM LOGO	Necessary	126.87 FL	*60.00 FL
4	2	*FRONT BONNET HINGE RH / LH	Not Necessary	131.80 FL	*- FL
5	2	*FRONT BONNET RUBBER SEAL RH / LH	Not Necessary	102.40 FL	*- FL
6	1	*FRONT BUMPER	Crushed	673.45 FL	*486.00 FL
7	1	*FRONT BUMPER LOWER CENTER GRILLE	Broken	393.40 FL	*200.00 FL
8	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	497.10 FL	*- FL
9	2	*FRONT BUMPER REINFORCEMENT BRACKET RH / LH	Not Necessary	311.20 FL	*- FL
10	2	*FRONT BUMPER SIDE RETAINER RH / LH	Broken	248.20 FL	*248.20 FL
11	1	*FRONT BUMPER TOP BEAM	Bent	232.60 FL	*232.60 FL
12	2	*FRONT BUMPER TOP BEAM BRACKET RH / LH	Not Necessary	402.20 FL	*- FL
13	1	*FRONT BUMPER TOW COVER	Not Necessary	40.20 FL	*- FL
14	1	*FRONT GRILLE BOTTOM	Cracked	490.80 FL	*315.00 FL
15	1	*FRONT GRILLE INNER	Cracked	410.35 FL	*410.35 FL
16	1	*FRONT GRILLE MILIMETER WAVE SENSOR	Not Necessary	1,403.19 FL	*- FL
17	1	*FRONT GRILLE TOP	Cracked	435.10 FL	*245.00 FL
18	2	*FRONT HEADLAMP RH / LH	Broken	4,968.84 FL	*1,109.60 FL
19	1	*FRONT SUPPORT PANEL	Dented	760.25 FL	*760.25 FL
20	1	*FRONT SUPPORT PANEL GARNISH RH / LH	O/S Torn	220.40 FL	*110.20 FL
21	1	*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	215.60 FL	*- FL
22	1	*RADIATOR	Not Necessary	1,987.60 FL	*- FL
23	1	*RADIATOR SPARE TANK	Not Necessary	399.10 FL	*- FL
24	1	*REAR BUMPER	Crushed	422.64 FL	*422.64 FL
25	4	*REAR BUMPER LOWER BRACKETS	Bent	206.80 FL	*206.80 FL
26	1	*REAR BUMPER REINFORCEMENT	Not Necessary	311.00 FL	*- FL
27	2	*REAR BUMPER SIDE HOLDERS	Broken	81.40 FL	*81.40 FL
28	1	*REAR END PANEL	Dented	422.07 FL	*422.07 FL
29	1	*REAR END PANEL TOP MOULDING	Bent	156.10 FL	*156.10 FL
30	1	*REAR FLOOR PANEL	Repair	1,700.60 FL	*- FL
31	1	*REAR SIDE PANEL	Repair	1,415.80 FL	*- FL
32	1	*REAR SPARE TYRE CARRIAGE	Not Necessary	312.70 FL	*- FL
33	1	*REAR SPARE TYRE LOCK CATCH	Not Necessary	110.35 FL	*- FL
34	1	*REAR TAILGATE	Dented	2,179.24 FL	*2,072.00 FL
35	1	*REAR TAILGATE HIACE STICKER	Necessary	40.77 FL	*40.77 FL
36	2	*REAR TAILGATE DAMPERS	Not Necessary	299.60 FL	*- FL
37	1	*REAR TAILGATE INNER BOARD	Torn	211.60 FL	*211.60 FL
38	1	*REAR TAILGATE LOCK	Bent	422.60 FL	*282.00 FL
39	1	*REAR TAILGATE LOCK CATCH	Not Necessary	103.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*REAR TAILGATE LOCK COVER	Cracked	70.60 FL	*70.60 FL
41	1		*REAR TAILGATE LOGO	Necessary	61.70 FL	*61.70 FL
42	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	159.20 FL	*- FL
43	1		*REAR TAILGATE RUBBER	Torn	401.79 FL	*281.00 FL
44	1		*REAR TAILLAMP FILTER PANEL	O/S Dented	487.90 FL	*182.40 FL
45	1		*REAR TAILLAMP LOWER GARNISHES	O/S Crushed	209.40 FL	*104.70 FL
46	1		*REAR TAILLAMPS	O/S Broken	579.90 FL	*289.95 FL
47	1		*TURBO INTER COOLER	Dented	1,514.95 FL	*1,211.00 FL
48	1		*WASHER TANK	Not Necessary	110.95 FL	*- FL
49	1		*SET REAR CAMERA	Not Necessary	450.00 FS	*- FS
50	1		*REAR LED LIGHT	Not Necessary	180.00 FS	*- FS
51	1		*SET REAR REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
52	1		*REAR TAILGATE 70KM/H STICKER	Necessary	25.00 FS	*25.00 FS
53	1		*REAR TAILGATE 8 PAX STICKER	Necessary	25.00 FS	*25.00 FS
54	1		*REAR WINDSCREEN SEAL	Necessary	85.00 FS	*30.00 FS
55	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
56	1		*FRONT BONNET LOCK	Torn	139.50 FL	*139.50 FL
57	1		*FRONT BUMPER SIDE GARNISH RH	Deformed	61.40 FL	*61.40 FL
58	1		*REAR BUMPER STEEP PANEL	Bent	329.30 FL	*329.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **30,410.21** **12,805.63**
 - List Item Discount on L Items 25.00/25.00% (S\$) 7,321.30 3,121.41

Total Parts (S\$) **23,088.91** **9,684.22**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND RESETTING HEADLAMP FOCUSING. (TO FR)	New	150.00	30.00
2	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY REAR PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	150.00	0.00
3	TO REMOVE, REFIX / RENEW REVERSE SENSOR ASSY AND RECTIFY FOR PROPER FUNCTIONING	New	130.00	20.00
4	TO REMOVE, REFIX / RENEW REVERSE CAMERA ASSY	New	140.00	30.00
5	DIAGNOSE, REPLACE AND/OR REPAIR TO RECTIFY FRONT PORTION ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	180.00	0.00
6	TO REMOVE, REINSTALL REAR TAILGATE WINDSCREEN (TO FR)	New	160.00	120.00
7	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT	New	1,800.00	850.00
8	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	2,200.00	1,300.00
Gross Labour Cost (S\$)			4,910.00	2,350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >