



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKM 8045U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR DOOR LH	DENTED	2,680.00	2,340.00
1	REAR DOOR REGULATOR MOTOR LH	NOT NECESSARY	622.00	-
1	REAR DOOR REGULATOR LH	NOT NECESSARY	480.00	-
1	REAR DOOR REGULATOR BRACKET LH	NOT NECESSARY	82.00	-
1	REAR DOOR TRIMBOARD LH (NPA)	NOT NECESSARY	-	-
1	REAR DOOR OUTER HANDLE LH	DAMAGED	475.00	369.00
1	REAR DOOR OUTER CHROME LH	NOT NECESSARY	180.00	-
1	REAR DOOR SASH PILLAR BLACK STICKER LH	NECESSARY	120.00	60.00
2	REAR DOOR HINGE LH @\$215.00	NOT NECESSARY	430.00	-
1	REAR DOOR STRIKER LH	NOT NECESSARY	285.00	-
1	REAR DOOR CHANNEL LH (NPA)	NOT NECESSARY	-	-
1	REAR DOOR LOWER WEATHERSTRIP LH	NOT NECESSARY	258.00	-
1	REAR DOOR WEATHERSTRIP LH	NECESSARY	363.00	363.00
1	ROCKER PANEL LH (NPA)	NOT NECESSARY	-	-
1	REAR DOOR OUTER HANDLE INNER BRACKET LH (ADDITIONAL)	DAMAGED	565.00	245.00
	LESS 10% DISCOUNT		-654.00	-337.70
			5,886.00	3,039.30
<u>SPECIAL NETT ITEMS</u>				
10	REAR DOOR TRIMBOARD CLIP @\$9.00 (SN)	NOT NECESSARY	90.00	-
10	REAR DOOR RIVET LH @\$9.00 (SN)	NOT NECESSARY	90.00	-
			180.00	-
<u>LABOUR</u>				
	TO CHECK WIRING.		80.00	30.00
	PANEL BEATING CHARGES TO REMOVE AND REPLACE, TO CUT AND WELD, TO KNOCK AND RESHAPE DAMAGED PARTS & AREAS.		400.00	250.00
	SPRAY PAINTING ALL AFFECTED PARTS & AREAS.		600.00	250.00
	TO REMOVE AND REFIT REAR DOOR GLASS LH.		100.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT REAR DOOR QUARTER GLASS LH.		80.00	30.00
			1,260.00	620.00
GRAND TOTAL			7,326.00	3,659.30
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00

Report Ref No. CS/GAI20002249/Asf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.