

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: *SL596412*
 at Workshop mls *ST.*
 of _____
 Insured: *SGD 333K*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: *68K*
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PF Seen: *9* Consistent? : Yes or No
 Est. Repairs: *20* days Res.: Yes or No
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: *27437*

Date / Time

Action / Instruction

274 40266 7 yrs. 8 mth.

Veh No: *SL596412* Yr Regn: *11/10/17*
 Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA*
 Make: *Honda Vezel / Hybrid 1496*
 Colour: *white* A/C: *Insured / Std / NI / NA*
 Sp. Reading: *207078* T/Radio: *Insured / Std / NI / NA*
 Eng/No: _____
 C/No: *R431260085*
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Modi: ☒ Nil / S/Rim / STD A/Rim or
 Tyre Size: F: *2.5 / 60 R 16*
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or *FALKEN*

Front _____ Rear _____
 R/Bal. *6* mm R/Bal. *6* mm
 L/Bal. _____ mm L/Bal. *6* mm
 D.O.A. *7/6/20* D.O.I. *10/2/20*
 Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear & L.
 The ☒ Chassis frame / Body Structure affected due to collision.

11/2 @ 11:41am Revised via email GIA & Police report
12/3/20 4/5 @ 23500 confirmed with Aler. (Ref 402251: 63%)

RECEIVED 13 MAR 2020

Date/Time, File Pass to?

☐ : Prel. Report1) *13/3 Typist*☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: *20*

Resurvey No. of Trip: _____

Survey Fee: *300*

Transportation: _____

Add Fee: ☐ : Site Insp (\$)

) S + RS \$

☐ : Interview (\$)

) Photos

☐ : Tech. Invs (\$)

) Others

☐ : Weekend (\$)

)

Report Format: *TP*Lump Sum / I.B.I. (\$) *23500*

TOTAL

311

13/3/2020

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 11 February 2020 11:41 AM
To: motorsurvey@sg.msig-asia.com
Cc: SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - FASTECH AUTO PTE LTD, DOA: 07/02/2020 , SLS 9641Z (TP VEHICLE), SGD 333K (OI VEHICLE)
Attachments: police report.pdf, gia report.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle SLS 9641Z at M/s: FASTECH AUTO PTE LTD, 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 on 10/02/2020.

Enclosed herewith a copy of TP's GIA report, Police report and estimated cost of repair will forward to you shortly.

Meanwhile, kindly provide us the claim reference number for our necessary action

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-6805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Katherine Wong

Date: 13 Mar 2020

Preliminary Advice

Insured Vehicle No	: SGD333K	Accident Date	: 07/02/2020
TP Vehicle No	: SLS9641Z	Assignment Date	: 11/02/2020
Make	: HONDA VEZEL	Est. Duration of Repair	: 20.00
Date of Inspection	: 10/02/2020		
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear and front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	64,522.51
Revised Amount	:S\$	29,666.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	29,666.56
Lump Sum Repair	:S\$	23,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Business

Owner ID: 059E

Vehicle Details

Vehicle No.: SLS9641Z

Vehicle to be Exported: No

Intended Deregistration Date: 10 Feb 2020

Vehicle Make: HONDA

Vehicle Model: VEZEL HYBRID 1.5X AUTO

Primary Colour: White

Manufacturing Year: 2017

Engine No.: LEB5960102

Chassis No.: RU31260085

Maximum Power Output: 112.0 kW (150 bhp)

Open Market Value: \$30,017.00

Original Registration Date: 12 Oct 2017

First Registration Date: 12 Oct 2017

Transfer Count: 0

Actual ARF Paid: \$5,000.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 11 Oct 2027

PARF Rebate Amount: \$3,750.00

Intended COE Rebate Details

COE Expiry Date: 11 Oct 2027

COE Category: E - Open - all except motorcycle

COE Period(Years): 10

QP Paid: \$48,005.00

COE Rebate Amount: \$36,816.00

Total Rebate Amount: \$40,566.00

The information contained herein is correct as at 10 Feb 2020

OK

Advertise on LinkedIn

Reach a community of 2M+ professionals in Singapore LinkedIn Marketing

LEARN MORE

Vezel Hybrid 1.5A X

Price Range

Depreciation

2017

Vehicle Type

Submit

Advanced Search

Home > Used Cars > AL Autocar Pte Ltd > Honda Vezel Hybrid 1.5A X

- Honda Vezel Hybrid 1.5A X
- Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map
- PREMIUM AD



Price	\$75,800	Fuel Type	Petrol-Electric
Depreciation	\$9,540 /yr View models with similar depre	Reg Date	17-Oct-2017 (7yrs 8mths 6days COE left)
Mileage	26,630 km (11.5k /yr)	Manufactured	2017
Road Tax	N.A.	Transmission	Auto
Dereg Value	\$41,551 as of today (change)	OMV	\$26,162
COE	\$49,189	ARF	\$5,000
Engine Cap	1,496 cc	No. of Owners	1
Curb Weight	1,280 kg		
Type of Vehicle	SUV		

Features
Efficient 1.5L I-VTEC Hybrid Engine. 150BHP. 7 Speed DCT Transmission. Steering And Cruise Control. Auto Headlights. Auto Brake Hold. View specs of the Honda Vezel Hybrid (2014)

Description
100% Loan Available Z10 Used Welcome! Cheapest In Market, Low Depreciation. Well Maintained Unit, Bank/In House Loan Available. Subject To Approval! Buy With A Peace Of Mind. Trade-In Welcome, Come View And Test Drive To Believe. Please Contact Direct Sales Person HP For Viewing.

Category
PARF Car, Premium Ad Car, Hybrid Cars

Status
Available

Resources

STA

Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more.

Car Valuation - Free
Find out the market value of your existing car for free. Get started



- Price Chart
- Summary

Click on the point to view the vehicle

- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information

AL Autocar Pte Ltd

38 vehicles for sale. 48 sold in past 3 mths

210 Turf Club Road Lot 801
Car Mall @ The Grandstand
Tel: 63655335

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources



CLEARANCE SALE NOW ON!

40% OFF ALL SELECTED ITEMS



Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Volkswagen Scirocco 1.4A TSI



Car Ideal For COE Renewal As Major Wear And Tear Parts Have been Replaced!
Direct Owner - StarAd



click here to view our PRISTINE USED CARS at GREAT PRICES

Browse by Category

< Back (1 2) Next >

Sort by Date Posted

20 results/page

30 vehicles

Vezel Hybrid 1.5A X

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Vezel Hybrid 1.5A X		Any	Any	2017	Any	Any	Any	Available
	Honda Vezel Hybrid 1.5A X	Honda Sensing	\$73,800	\$9,410 /yr	07-Sep-2017	1,496 cc	70,000 km	SUV	Available
Fuel Type: Petrol-Electric Low Fuel Consumption Up To 24/L, New Condition, Warranty 1 Year Plus Free Servicing. Call For Viewing Now! Posted: 10-Feb-2020 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X		\$70,800	\$9,320 /yr	09-Jun-2017	1,496 cc	58,000 km	SUV	Available
Fuel Type: Petrol-Electric All Loan Are Welcome. Honda Sensing. Excellent Fuel Efficiency At Up To 24.2 Km/L. Well Maintained By 1 Owner. Autobrust Traders Pte Ltd Posted: 09-Feb-2020 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X	Honda Sensing	\$67,800	\$9,440 /yr	11-Jan-2017	1,496 cc	56,000 km	SUV	Available
Fuel Type: Petrol-Electric Very Sporty Vezel Hybrid. Brown Leather Interior. Well Maintained By 1 Owner Only. Sensing Model. Low Mileage. Accident Free. Servici... Posted: 09-Feb-2020 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X (OPC)		\$60,800	\$7,810 /yr	28-Jul-2017	1,496 cc	-	SUV	Available
Fuel Type: Petrol-Electric Lowest Interest Rate At 2.28% Only! Full Loan Available! Buy With Assurance! Call Us Now Before This Beauty Is Gone! Autobrust Traders Pte Ltd Posted: 08-Feb-2020 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Steering Audio Ctrl Fr Shuttle/Vezel/Fit/Jazz								
Steering Audio Control for Honda Shuttle/Vezel/Fit GK/Jazz GK to control your audio system directly while driving. More info about this product									
	Honda Vezel Hybrid 1.5A X	Honda Sensing	\$69,800	\$9,560 /yr	24-Feb-2017	1,496 cc	51,500 km	SUV	Available
Fuel Type: Petrol-Electric Under Sheltered Parking. Well Maintained. Optional 1 Year / 20K Km Warranty. Highest Trade In. Std Bank Loan, Balloon Loan, In Hous... Posted: 08-Feb-2020 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									
	Honda Vezel Hybrid 1.5A X		\$73,800	\$9,940 /yr	13-Apr-2017	1,496 cc	66,989 km	SUV	Available
Fuel Type: Petrol-Electric 1 Owner, 1.98% Interest, Low Mileage, Low Depreciation, Buy From Reputed Company, All Credit Profiles Welcome, 100% Loan Availabl... Hamilton Autohub Pte Ltd Posted: 08-Feb-2020 Tags: 2017 Honda Vezel, 2017 honda vezel, Honda Vezel, honda vezel, Honda, Vezel, vezel, Used Honda									

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	08/02/2020 16:32
Date Of Accident	07/02/2020 17:30
Exact Location Of Accident	AYE TWRDS TUAS NORMANTAN PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLS9641Z
Insured/Policyholder	
Name Of Registered Owner	GSH SERVICES
Co Reg No	5XXXX059E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90925715

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID 1.5X AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094657132-02
Cover Note Number	

Driver

Name of Driver	GOH SOON HONG
NRIC No	SXXXX755B
Date Of Birth	19/03/1965
Occupation	OUTDOOR
Date Of Driving Pass	10/10/1990
Driving Experience	29 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90925715
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 645 #09-114 JURONG WEST STREET 61
Postcode	640645
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	8
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	EUNOS
Police Station Address	ROAD: 9 EUNOS CRESCENT #01-2687 , POSTCODE: 400009 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

AS PER POLICE REPORT No.T/20200207/2144; NOTE: CAR OWNER ARRANGE TOWING STRAIGHT TO WORKSHOP.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGD333K
Vehicle Make/Model/Colour	PORSCHE / CAYENNE TURBO (E2-II) TIP E5
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SHA4627R

Vehicle Make/Model/Colour

HYUNDAI / I40 1.7 CRDI F/L AT ABS AIRBAG 4DR

Details Of Properties

Vehicle Category

TAXI

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number

SKM3997A

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number

SLQ8547E

Vehicle Make/Model/Colour

AUDI / A4 1.4 TFSI S TRONIC

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number

SMJ5795A

Vehicle Make/Model/Colour

HONDA / GRACE HYBRID 1.5DX AUTO

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number SJR4343X
Vehicle Make/Model/Colour MITSUBISHI / LANCER 1.5 MIVEC GLS 4A/T
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 7

Vehicle Registration Number SGX9299L
Vehicle Make/Model/Colour VOLKSWAGEN / TIGUAN 1.4 TSI AT BMT 5N22QY
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name GOH SOON HONG
Approximate Age 54
Injuries Sustain
Injured person in which vehicle? SLS9641Z
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance?
Address BLK 645 #09-114 JURONG WEST STREET 61
Postcode 640645

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature:
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KARI BUKIT (VAC)
23 Kari Bukit Ave 4 #02-02
Singapore 411033
Tel: 67416097 Fax: 67492305
Email: vac@idac.com.sg
Reporting Centre Personnel's Signature
Name:
NIC/VIN No.:

Accident Sketch Plan

SKETCH PLAN



A: SLS 9641 Z

B: SGD 333K

C: SHA 4627 R

D: SKM 3997 A

E: SLQ 8547 E

F: SMJ 5795 A

G: STR 4343 X

H: SGX 9299 L

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

* Refer the attached Police Report No T/20200207/2144

DECLARATION

I/We declare that the particulars are true in every respect.



Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KARI BURIT (YAC)
23 Kallang Road, Level 4, 802-02
Singapore 410033
Tel: 67416887 Fax: 67492305
Reporting Officer's Personnel's Signature
Name:
NRIC/FIN No.:

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200207/2144

1 of 4

Police Station Of Origin:
Eunos NPP
529 Bedok Reservoir Road #01-1520
SINGAPORE 470629
Tel No: 1800-4439999

Report No: T/20200207/2144

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/02/2020 20:53		Vide Report No.:		Station Diary No.: 44	
Informant's Particulars					
Name of Informant: GOH SOON HONG			Address: APT BLK 645 JURONG WEST STREET 61 #09-114 SINGAPORE 640645		
ID Type / ID No.: NRIC NO / S1725755B			Contact No.: Home/Office: Mobile: 909C 1715		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 54	Date of Birth: 19/03/1965	Type of Informant: Driver		
Race: Chinese			Language: Mandarin		Institution / School Name:
Occupation: GRAB DRIVER			Driving Licence Information: Class:		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 07/02/2020 17:30	Type of Location:
Location: Along Road 1 AYER RAJAH EXPRESSWAY TOWARDS TUAS, NORMANTON PARK BY THE LEFT				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SGD333K						0
SGX9299L						0
SHA4527R						0
SJR4343X						0
SKM3997A						0

Accident Sketch Plan



**SINGAPORE
POLICE FORCE**



T/20200207/2144

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

2 of 4
Report No. T/20200207/2144

CONTINUATION OF REPORT

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLQ8547E						0
SLS9641Z		HONDA	VEZEL	White		1
SMJ5795A						0

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	HOOY KOK WAI		ID No. NIL
Related Vehicle	SGD333K		Contact No. 96613588
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Driver			
Name	REDDY		ID No. NIL
Related Vehicle	SGX9299L		Contact No. 96671527
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge NIL
No. of Days granted Medical Leave	NIL		Degree of Injury NIL
Driver			
Name	GOH SOON HONG		ID No. S1725755B
Related Vehicle	SLS9641Z		Contact No. 90925715
Hospital/Clinic	THE CHONG FAMILY CLINIC PTE LTD		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	07/02/2020		Date Discharge 07/02/2020
No. of Days granted Medical Leave	03		Degree of Injury NIL

Accident Sketch Plan



SINGAPORE
POLICE FORCE



T/20200207/2144

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 4

Report No. T/20200207/2144

CONTINUATION OF REPORT

Brief Details.

On 7/2/2020 at around 530pm, I was driving a white Honda Vezel along AYE towards Tuas (Normanton Park by the left). Suddenly the front vehicle (SGX9299L) applied brakes and I applied brakes. I came to a complete stop however the vehicle behind (SGD333K) me was unable to react on time and pushed my vehicle forward and thus colliding onto the front vehicle. I had a passenger with me but he was not injured. I then found out that I was involved in a chain collision of 8 vehicles including mine and I was the 7th vehicle in the accident.

Due to the collision, I felt some pain at the back of my head, back and front ribs. My vehicle's front and rear bumper was damaged; the rear window was cracked too.

I then visited the clinic and was given 3 days of Medical Leave.

Accident Sketch Plan



SINGAPORE
POLICE FORCE



T20200207/2144

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

4 of 4

Report No: T20200207/2144

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

G /

Sgt 1 TAN LI JIE

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

07/02/2020 20:53

Officer In Charge Of Case:

TP / AEIT /

SI MOHAMAD ZULFAZDLI BIN ABDULLAH

Contact No.: 85476204

Classification Of Case:

Authentication Stamp

NP188

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

Not Authorized
Date
10/2/20
1/5 @ 23.500
20 days.

VEHICLE NO: SL596412

QTY	PARTICULAR		
1 PCS	BONNET	892.30	Suc \$915.00 ✓
2 PCS	BONNET HINGES @\$78.10		Boat \$170.00 ✓
1 PCS	BONNET INSULATOR	185.40	To. n \$211.30 ✓
1 SET	BONNET INSULATOR CLIPS		ner \$35.00 ✓
1 PCS	BONNET LOCK		twi \$135.50 ✓
2 PCS	BONNET RUBBERS @\$32.00		ner \$64.00 ✓
1 PCS	FRONT BUMPER	801.70	DJ \$950.00 ✓
1 PCS	FRONT BUMPER REINFORCEMENT	321.00	DJ \$480.00 ✓
2 PCS	FRONT BUMPER SIDE RETAINERS@ \$65.00	48.50 x 2 = 97.00	Set \$130.00 ✓
2 PCS	FRONT BUMPER BRACKETS @\$115.00		ns \$230.00 X
1 PCS	FRONT BUMPER CENTRE GRILLE	145.30	To. n \$285.00 ✓
1 PCS	FRONT BUMPER LOWER SPOILER	480.00	no/De \$525.00 ✓
1 PCS	FRONT BUMPER UNDER COVER		11 \$480.00 X
1 SET	FRONT BUMPER UNDER COVER CLIPS		11 \$35.00 X
1 PCS	FRONT BUMPER TOW COVER		De \$45.00 ✓
2 PCS	FRONT BUMPER FOG LAMP COVERS @\$180.00	91.70 x 2 = 183.40	twi \$360.00 ✓
2 PCS	FRONT BUMPER FOG LAMPS @\$445.00	327.70	n/s/cue \$890.00 1PC
1 SET	FRONT BUMPER CLIPS		rec \$40.00 ✓
1 PCS	FRONT GRILLE	295.00	cne \$525.00 ✓
1 PCS	FRONT GRILLE OUTER GARNISH	350.50	cne \$548.00 ✓
1 PCS	FRONT GRILLE 'H' LOGO		ner \$38.80 ✓
2 PCS	HEADLAMPS @\$2250	1859.10 x 2 = 3718.20	cne \$4,500.00 ✓
2 PCS	HEADLAMP LOWER BRACKETS @\$85.00		cne \$170.00 ✓
1 PCS	FRONT SUPPORT PANEL	576.20	Boat \$745.11 ✓
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	162.30	DJ \$322.30 ✓
1 SET	FRONT SUPPORT PANEL TOP GARNISH CLIPS		ner \$50.00 ✓
2 PCS	FRONT FENDERS @\$688.00	558.20	n/s/cue/1R \$1,376.00 1PC
2 PCS	FRONT FENDER INNERSHIELDS @\$166.50		11 \$333.00 X
2 PCS	FRONT FENDER OUTER PROTECTORS @\$295.00		De/to. n \$590.00 ✓
1 PCS	AIR CON CONDENSER	748.00	DJ/p. n \$1,568.00 ✓
2 PCS	AIR CON CONDENSER SIDE GARNISH @\$148.00		n/s/p. n \$296.00 1PC
1 PCS	RADIATOR	1376.20	DJ/p. n \$1,817.50 ✓
1 PCS	RADIATOR FAN COWLING	185.50	cne \$288.30 ✓
1 PCS	RADIATOR FAN MOTOR	350.50	JM \$488.20 ✓
1 PCS	RADIATOR FAN BLADE		Set \$101.50 ✓
1 PCS	FRONT FENDER INNER PANEL N/S		n \$525.30 X
1 PCS	FRONT WHEEL HOUSING PANEL N/S		n \$988.20 X
1 PCS	FRONT LOCK CENTRE BRACKET		cne \$115.00 ✓
1 PCS	AIR DUCT		DJ \$215.00 ✓

(202)

13672-20

1 PCS	intake manifold	
1 PCS	FRONT air con fan Assy	
1 PCS	RESONATOR BOX	
2 PCS	FRONT GRILLE CHROME MOULDING @\$98.50	
1 PCS	BATTERY TRAY	
1 PCS	WASHER TANK	
1 PCS	FRONT WINDSCREEN	1455.20
1 PCS	TAILGATE	953.00
1 PCS	TAILGATE 'H' LOGO	
1 PCS	TAILGATE 'VEZEL' EMBLEM	
1 PCS	TAILGATE OUTER HANDLE GARNISH	
2 PCS	TAILGATE REFLECTORS @\$460.50	353.20
1 PCS	TAILGATE INNER LOCK	
1 PCS	TAILGATE INNER TRIM BOARD	
1 SET	TAILGATE INNER TRIM BOARD CLIPS	
2 PCS	TAILGATE DAMPERS @\$299.10	
1 PCS	TAILGATE WEATHERSTRIP	
1 PCS	TAILGATE REAR WIPER ARM	
1 PCS	TAILGATE REAR WIPER MOTOR	
1 PCS	TAILGATE KEYLESS SENSOR	
1 PCS	REAR WINDSCREEN	1425.20
1 PCS	REAR WINDSCREEN MOULDING	118.00
1 PCS	TAILGATE TOP SPOILER	
1 PCS	REAR BUMPER	
2 PCS	REAR BUMPER SIDES @\$285.10	
2 PCS	REAR BUMPER SIDE RE TAINERS @\$35.20	
2 PCS	REAR BUMPER REFLECTORS @\$85.00	
1 PCS	REAR BUMPER DIFFUSER	
1 SET	REAR BUMPER DIFFUSER CLIPS	
2 PCS	REAR BUMPER MUDFLAPS @\$145.00	
2 PCS	TAILLAMPS @\$485.20	
2 PCS	TAILGATE HOUSING PANELS @\$195.00	
1 PCS	REAR END PANEL	
1 PCS	REAR END PANEL TOP GARNISH	
1 PCS	REAR FLOOR PANEL	
1 PCS	REAR FLOOR PANEL TOP BOARD	216.50
1 PCS	REAR FLOOR PANEL Hybrid battery cover	305.20
1 PCS	REAR FLOOR PANEL side panel n/s	188.50
1 PCS	REAR FLOOR PANEL TOP TRAY	
2 PCS	REAR FENDERS @\$885.10	
2 PCS	REAR FENDER OUTER PROTECTORS @\$264.00	
2 PCS	REAR FENDER INNER TRIM BOARD @\$645.30	344.20
1 PCS	REAR EXHAUST	
2 PCS	REAR EXHAUST MOUNTINGS @\$45.00	
2 PCS	REAR SHOCK ABSORBERS @\$305.00	
2 PCS	REAR WHEELHUB BEARINGS @\$450.00	
1 PCS	REAR AXLE ARM	
1 PCS	REAR EXHAUST HEAT SHIELD	

eng	\$788.00	✓
cris/m	\$344.20	✓
11	\$385.20	X
neu	\$197.00	✓
11	\$180.20	X
11	\$305.20	X
me	\$1,488.20	✓
Body m	\$1,100.90	✓
neu	\$35.80	✓
neu	\$56.20	✓
surface	\$399.20	✓
n/s cr	\$921.00	1PC
neu	\$198.50	✓
D.S	\$321.70	✓
neu	\$45.00	✓
11	\$598.20	X
11	\$135.70	✓
11	\$188.20	X
11	\$695.00	X
11	\$180.00	X
Shothead	\$1,566.20	✓
neu	\$181.00	✓
11	\$950.00	X
11	\$762.70	✓
n/s D.S	\$570.20	1PC
n/s cr	\$70.40	1PC
n/s cr	\$170.00	1PC
11	\$348.20	✓
neu	\$50.00	✓
11	\$290.00	X
n/s B.S	\$970.40	1PC
n/s n/s	\$390.00	1PC
Body m	\$514.00	✓
cr	\$184.00	✓
Body m/su	\$912.00	✓
11	\$499.20	✓
De	\$685.00	✓
Body m	\$399.20	✓
cr	\$299.20	✓
n/s D.S	\$1,770.20	1PC
n/s D.S	\$528.00	1PC
n/s D.S	\$1,290.60	1PC
11	\$899.20	X
11	\$90.00	X
11	\$610.00	X
n/s D.S	\$900.00	1PC
11	\$1,885.00	X
11	\$199.00	X

(20%)

1 PCS
1 PCS
1 PCS
1 PCS
2 PCS

REAR WHEEL HOUSING PANELS N/S 850.50
REAR END LOCK SENSOR
REAR FENDER UNDER TRIM N/S 248.50
REAR CHASSIS MEMBER N/S
REAR DOOR @\$998.20

Body AD \$1,150.00 ✓
11 \$288.50 X
DIS \$299.30 ✓
2 \$699.20 X
2 \$1,996.40
\$52,562.51

20%

1 PCS
1 PCS
1 PCS
1 SET
1 PCS
1 PCS
1 SET
1 PCS
1 PCS
1 BOT

S.NETT
REAR WINDSCREEN SEALANT
REAR WINDSCREEN SOLAR FILM
REAR WINDSCREEN INNER SEAL
REAR REVERSE CARMERA
FRONT LICENCE PLATE W/HOLDER
REAR END PANEL SEALANT
REAR FLOOR PANEL INSULATOR
FRONT LICENCE PLATE W/HOLDER
BATTERY
RADIATOR COOLANT

RE \$50.00 40
RE \$250.00 150
RE \$50.00 30
SHIPS \$380.00 300
CNA \$50.00 40
RE \$50.00 ✓
RE \$200.00 120
REPAIR \$50.00 X
AD \$220.00 100
RE \$50.00 30

LABOUR CHARGES:

TO CHECK WIRING
TO DISMANTLE & REPLACING REVERSE SENSOR
TO TRANSFER TAILGATE MECHANISM
TO DISMANTLE & REPLACING REAR WINDSCREEN
TO DISMANTLE & REFIX REAR EXHAUST
TO DISMANTLE & REFIX SEAT,CUSHION UPHOLSTREY
TO DISMANTLE & REFIX PETROL TANK
TO DISMANTLE & REFIX REAR UNDERCARRIAGE
TO SPRAY RUSTPROOFING
TO REFILL AIR CON GAS
TO DISMANTLE & REFIX Hybrid battery & reprogramme
TO CONDUCT WHEEL ALIGNEMENT
TO DISMANTLE & REFIX FRONT WINDSCREEN
LABOUR FOR PANEL BEATING,CUT ,WELD,STRAIGHTEN
& REPLACING PARTS
TO PUTTY & SPRAY PAINTING

\$100.00 30
\$100.00 50
\$100.00 60
\$150.00 120
11 \$100.00 X
\$150.00 80
\$100.00 60
\$380.00 200
\$200.00 150
\$150.00 100
\$380.00 350
\$100.00 80
\$150.00 120
\$4,500.00 2600
\$3,800.00 2000
TOTAL \$64,522.51

LKK Auto Consultants hence notify
the Repairer of the following:
• To survey before/after spray painting
• To display damaged part(s) during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

28128.20
22806.20
29666.50
23733

6472.51

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Feb 2020 13:23		11 Feb 2020 13:33 Edit Adj Rpt	S\$23,500.00 Edit Estimates	S\$23,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	HOOY KOK WAI , ID: S1294467E								
Main Claimant:	GSH SERVICES , Co. Reg. No.: S3314059E								
Vehicle Reg. No.:	SLS9641Z	Date of Loss:	07/02/2020 17:00 - :59 [27 Months and 26 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 619562	Policy/Cover Note No.:	28968500MPQ (Comprehensive) Coverage: 10/06/2019 - 09/06/2020						
Vehicle Reg. No. (Insured):	SGD333K	Policy No. (Claimant):							
		Excess:							
Repairer:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay, 417883 Kaki Bukit - Tel: 67465405								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 12/03/2020]								
Driver/Custodian (Insured):	HOOY KOK WAI (), NRIC: S1294467E Email:								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLS9641Z (619562)
[SGD333K]
TP
GSH SERVICES
Feb 7 2020 5:00PM
[HOY KOK WAI]
Fastech Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	13/03/20 14:00	Adjuster Immediate Advice	1	Load HTM						
Photos/Images							3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	12/03/20 08:14	Odometer Reading	1	Load JPG	☒					
2	12/03/20 08:14	Chassis Number	1	Load JPG	☒					
3	12/03/20 08:15	General View	1	Load JPG	☒					
4	12/03/20 08:15	General View	1	Load JPG	☒					
5	12/03/20 08:15	General View	1	Load JPG	☒					
6	12/03/20 08:15	General View	1	Load JPG	☒					
7	12/03/20 08:15	General View	1	Load JPG	☒					
8	12/03/20 08:15	General View	1	Load JPG	☒					
9	12/03/20 08:15	General View	1	Load JPG	☒					
10	12/03/20 08:15	General View	1	Load JPG	☒					
11	12/03/20 08:15	General View	1	Load JPG	☒					
12	12/03/20 08:15	General View	1	Load JPG	☒					
13	12/03/20 08:15	General View	1	Load JPG	☒					
14	12/03/20 08:15	General View	1	Load JPG	☒					
15	12/03/20 08:15	General View	1	Load JPG	☒					
16	12/03/20 08:15	General View	1	Load JPG	☒					
17	12/03/20 08:15	General View	1	Load JPG	☒					
18	12/03/20 08:15	General View	1	Load JPG	☒					
19	12/03/20 08:15	General View	1	Load JPG	☒					
20	12/03/20 08:15	General View	1	Load JPG	☒					
21	12/03/20 08:15	General View	1	Load JPG	☒					
22	12/03/20 08:15	General View	1	Load JPG	☒					
23	12/03/20 08:15	General View	1	Load JPG	☒					
24	12/03/20 08:15	General View	1	Load JPG	☒					
25	12/03/20 08:15	General View	1	Load JPG	☒					
26	12/03/20 08:15	General View	1	Load JPG	☒					
27	12/03/20 08:15	General View	1	Load JPG	☒					
28	12/03/20 08:15	General View	1	Load JPG	☒					
29	12/03/20 08:15	General View	1	Load JPG	☒					
30	12/03/20 08:15	General View	1	Load JPG	☒					
31	12/03/20 08:15	General View	1	Load JPG	☒					
32	12/03/20 08:15	General View	1	Load JPG	☒					
33	12/03/20 08:15	General View	1	Load JPG	☒					
34	12/03/20 08:15	General View	1	Load JPG	☒					

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	12/03/20 08:15	General View	 Load JPG	☒
36	12/03/20 08:15	General View	 Load JPG	☒
37	12/03/20 08:15	General View	 Load JPG	☒
38	12/03/20 08:15	General View	 Load JPG	☒
39	12/03/20 08:15	General View	 Load JPG	☒
40	12/03/20 08:15	General View	 Load JPG	☒
41	12/03/20 08:15	General View	 Load JPG	☒
42	12/03/20 08:15	General View	 Load JPG	☒
43	12/03/20 08:15	General View	 Load JPG	☒
44	12/03/20 08:15	General View	 Load JPG	☒
45	12/03/20 08:15	General View	 Load JPG	☒
46	12/03/20 08:15	General View	 Load JPG	☒
47	12/03/20 08:15	General View	 Load JPG	☒
48	12/03/20 08:15	General View	 Load JPG	☒
49	12/03/20 08:15	General View	 Load JPG	☒
50	12/03/20 08:15	General View	 Load JPG	☒
51	12/03/20 08:15	General View	 Load JPG	☒
52	12/03/20 08:15	General View	 Load JPG	☒
53	12/03/20 08:15	General View	 Load JPG	☒
54	12/03/20 08:15	General View	 Load JPG	☒
55	12/03/20 08:15	General View	 Load JPG	☒
56	12/03/20 08:15	General View	 Load JPG	☒
57	12/03/20 08:15	General View	 Load JPG	☒
58	12/03/20 08:15	General View	 Load JPG	☒
59	12/03/20 08:15	General View	 Load JPG	☒
60	12/03/20 08:15	General View	 Load JPG	☒
61	12/03/20 08:15	General View	 Load JPG	☒
62	12/03/20 08:15	General View	 Load JPG	☒
63	12/03/20 08:15	General View	 Load JPG	☒
64	12/03/20 08:15	General View	 Load JPG	☒
65	12/03/20 08:15	General View	 Load JPG	☒
66	12/03/20 08:15	General View	 Load JPG	☒
67	12/03/20 08:15	General View	 Load JPG	☒
68	12/03/20 08:15	General View	 Load JPG	☒
69	12/03/20 08:15	General View	 Load JPG	☒
70	12/03/20 08:15	General View	 Load JPG	☒
71	12/03/20 08:15	General View	 Load JPG	☒
72	12/03/20 08:15	General View	 Load JPG	☒
73	12/03/20 08:15	General View	 Load JPG	☒
74	12/03/20 08:15	General View	 Load JPG	☒
75	12/03/20 08:15	General View	 Load JPG	☒
76	12/03/20 08:15	General View	 Load JPG	☒
77	12/03/20 08:15	General View	 Load JPG	☒
78	12/03/20 08:15	General View	 Load JPG	☒
79	12/03/20 08:15	General View	 Load JPG	☒
80	12/03/20 08:15	General View	Load JPG	☒
81	12/03/20 08:15	General View	Load JPG	☒
82	12/03/20 08:15	General View	Load JPG	☒
83	12/03/20 08:15	General View	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	12/03/20 08:15	General View	 Load JPG	☒
85	12/03/20 08:15	General View	 Load JPG	☒
86	12/03/20 08:15	General View	 Load JPG	☒
87	12/03/20 08:15	General View	 Load JPG	☒
88	12/03/20 08:15	General View	 Load JPG	☒
89	12/03/20 08:15	General View	 Load JPG	☒
90	12/03/20 08:15	General View	 Load JPG	☒
91	12/03/20 08:15	General View	 Load JPG	☒
92	12/03/20 08:15	General View	 Load JPG	☒
93	12/03/20 08:15	General View	 Load JPG	☒
94	12/03/20 08:15	General View	 Load JPG	☒
95	12/03/20 08:15	General View	 Load JPG	☒
96	12/03/20 08:15	General View	 Load JPG	☒
97	12/03/20 08:15	General View	 Load JPG	☒
98	12/03/20 08:15	General View	 Load JPG	☒
99	12/03/20 08:15	General View	 Load JPG	☒
100	12/03/20 08:15	General View	 Load JPG	☒
101	12/03/20 08:15	General View	 Load JPG	☒
102	12/03/20 08:15	General View	 Load JPG	☒
103	12/03/20 08:15	General View	 Load JPG	☒
104	12/03/20 08:15	General View	 Load JPG	☒
105	12/03/20 08:15	General View	 Load JPG	☒
106	12/03/20 08:15	General View	 Load JPG	☒
107	12/03/20 08:15	General View	 Load JPG	☒
108	12/03/20 08:15	General View	 Load JPG	☒
109	12/03/20 08:15	General View	 Load JPG	☒
110	12/03/20 08:15	General View	 Load JPG	☒
111	12/03/20 08:15	General View	 Load JPG	☒
112	12/03/20 08:15	General View	 Load JPG	☒
113	12/03/20 08:15	General View	 Load JPG	☒
114	12/03/20 08:15	General View	 Load JPG	☒
115	12/03/20 08:15	General View	 Load JPG	☒
116	12/03/20 08:15	General View	 Load JPG	☒
117	12/03/20 08:15	General View	 Load JPG	☒
118	12/03/20 08:15	General View	 Load JPG	☒
119	12/03/20 08:15	General View	 Load JPG	☒
120	12/03/20 08:15	General View	 Load JPG	☒
121	12/03/20 08:15	General View	 Load JPG	☒
122	12/03/20 08:15	General View	 Load JPG	☒
123	12/03/20 08:15	General View	 Load JPG	☒
124	12/03/20 08:15	General View	 Load JPG	☒
125	12/03/20 08:15	General View	 Load JPG	☒
126	12/03/20 08:15	General View	 Load JPG	☒
127	12/03/20 08:15	General View	 Load JPG	☒
128	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
129	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
130	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
131	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
132	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
133	12/03/20 08:17	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
134	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
135	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
136	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
137	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
138	12/03/20 08:17	Reinspection Photo	 Load JPG	☒
139	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
140	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
141	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
142	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
143	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
144	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
145	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
146	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
147	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
148	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
149	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
150	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
151	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
152	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
153	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
154	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
155	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
156	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
157	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
158	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
159	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
160	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
161	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
162	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
163	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
164	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
165	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
166	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
167	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
168	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
169	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
170	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
171	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
172	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
173	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
174	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
175	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
176	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
177	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
178	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
179	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
180	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
181	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
182	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
183	12/03/20 08:18	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
184	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
185	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
186	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
187	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
188	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
189	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
190	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
191	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
192	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
193	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
194	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
195	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
196	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
197	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
198	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
199	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
200	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
201	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
202	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
203	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
204	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
205	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
206	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
207	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
208	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
209	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
210	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
211	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
212	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
213	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
214	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
215	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
216	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
217	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
218	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
219	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
220	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
221	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
222	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
223	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
224	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
225	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
226	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
227	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
228	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
229	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
230	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
231	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
232	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
233	12/03/20 08:18	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
234	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
235	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
236	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
237	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
238	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
239	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
240	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
241	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
242	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
243	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
244	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
245	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
246	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
247	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
248	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
249	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
250	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
251	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
252	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
253	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
254	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
255	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
256	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
257	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
258	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
259	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
260	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
261	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
262	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
263	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
264	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
265	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
266	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
267	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
268	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
269	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
270	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
271	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
272	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
273	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
274	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
275	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
276	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
277	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
278	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
279	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
280	12/03/20 08:18	Reinspection Photo	Load JPG	☒
281	12/03/20 08:18	Reinspection Photo	Load JPG	☒
282	12/03/20 08:18	Reinspection Photo	Load JPG	☒
283	12/03/20 08:18	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
284	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
285	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
286	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
287	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
288	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
289	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
290	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
291	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
292	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
293	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
294	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
295	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
296	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
297	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
298	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
299	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
300	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
301	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
302	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
303	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
304	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
305	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
306	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
307	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
308	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
309	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
310	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
311	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
312	12/03/20 08:18	Reinspection Photo	 Load JPG	☒
313	12/03/20 08:18	After Repair Photo	 Load JPG	☒
314	12/03/20 08:18	After Repair Photo	 Load JPG	☒
315	12/03/20 08:18	After Repair Photo	 Load JPG	☒
316	12/03/20 08:18	After Repair Photo	 Load JPG	☒
317	12/03/20 08:18	After Repair Photo	 Load JPG	☒
318	12/03/20 08:18	After Repair Photo	 Load JPG	☒
319	12/03/20 08:18	After Repair Photo	 Load JPG	☒
320	12/03/20 08:18	After Repair Photo	 Load JPG	☒
321	12/03/20 08:18	After Repair Photo	 Load JPG	☒
322	12/03/20 08:18	After Repair Photo	 Load JPG	☒
323	12/03/20 08:18	After Repair Photo	 Load JPG	☒
324	12/03/20 08:18	After Repair Photo	 Load JPG	☒
325	12/03/20 08:18	After Repair Photo	 Load JPG	☒
326	12/03/20 08:18	After Repair Photo	 Load JPG	☒
327	12/03/20 08:18	After Repair Photo	 Load JPG	☒
328	12/03/20 08:18	After Repair Photo	 Load JPG	☒
329	12/03/20 08:18	After Repair Photo	 Load JPG	☒
330	12/03/20 08:18	After Repair Photo	 Load JPG	☒
331	12/03/20 08:18	After Repair Photo	 Load JPG	☒
332	12/03/20 08:18	After Repair Photo	 Load JPG	☒
333	12/03/20 08:18	After Repair Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
334	12/03/20 08:18	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/02/20 13:25	TP SL59641Z Gia & Police Report - 7/8	 Load PDF	
2	11/02/20 13:29	TP SJR4343X Gal & Police Report 5/8	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20002251/UTF3E2

Date: 20/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28968500MPQ

Claimant Vehicle No : SLS9641Z

Insured Vehicle No : SGD333K

Date of Loss: 07/02/2020

Nature of Claim: TP

Claim No: 619562

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLS9641Z

Make & Model: HONDA VEZEL, 1.5 HYBRID X (A)

Engine No: LEB5960102

Reg. Date: 12/10/2017 (Man. Year: 2017)

Chassis No: RU31260085

Colour: White

Odometer: 207078 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Falken 6 mm

Rear Left Side: Falken 6 mm

Front Right Side: Falken 6 mm

Rear Right Side: Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	53,912.51	23,666.56	30,245.95	56.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,460.00	6,000.00	4,460.00	42.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	64,372.51	29,666.56	34,705.95	53.91
Approved Total (Overridden) (S\$)		23,500.00		
(S\$)	64,372.51	23,500.00	40,872.51	63.49
+ GST 7.00/7.00% (S\$)	4,506.08	1,645.00	2,861.08	63.49
Nett Amount (S\$)	68,878.59	25,145.00	43,733.59	63.49

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 10/02/2020 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
Singapore 417883

Estimated Period of Repair: 20.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Mar 2020)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS9641Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	915.00 F	*892.30 FL
2	2		*BONNET HINGES	Bent	170.00 F	*170.00 FL
3	1		*BONNET INSULATOR	Torn	211.30 F	*185.40 FL
4	1		*SET BONNET INSULATOR CLIPS	Necessary	35.00 F	*35.00 FL
5	1		*BONNET LOCK	Twisted	135.50 F	*135.50 FL
6	2		*BONNET RUBBERS	Necessary	64.00 F	*64.00 FL
7	1		*FRONT BUMPER	Distorted	950.00 F	*801.70 FL
8	1		*FRONT BUMPER REINFORCEMENT	Distorted	480.00 F	*321.00 FL
9	2		*FRONT BUMPER SIDE RETAINERS	Bent	130.00 F	*97.00 FL
10	2		*FRONT BUMPER BRACKETS	No such part	230.00 F	*- FL
11	1		*FRONT BUMPER CENTRE GRILLE	Torn	285.00 F	*145.30 FL
12	1		*FRONT BUMPER LOWER SPOILER	Dented / Deformed	525.00 F	*480.00 FL
13	1		*FRONT BUMPER UNDER COVER	Not Necessary	480.00 F	*- FL
14	1		*SET FRONT BUMPER UNDER COVER CLIPS	Not Necessary	35.00 F	*- FL
15	1		*FRONT BUMPER TOW COVER	Deformed	45.00 F	*45.00 FL
16	2		*FRONT BUMPER FOG LAMP COVERS	Twisted	360.00 F	*183.40 FL
17	1		*FRONT BUMPER FOG LAMPS	N/S Cracked	890.00 F	*327.70 FL
18	1		*SET FRONT BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
19	1		*FRONT GRILLE	Cracked	525.00 F	*295.00 FL
20	1		*FRONT GRILLE OUTER GARNISH	Cracked	548.00 F	*350.50 FL
21	1		*FRONT GRILLE H LOGO	Necessary	38.80 F	*38.80 FL
22	2		*HEADLAMPS	Cracked	4,500.00 F	*3,718.20 FL
23	2		*HEADLAMP LOWER BRACKETS	Cracked	170.00 F	*170.00 FL
24	1		*FRONT SUPPORT PANEL	Bent	745.11 F	*576.20 FL
25	1		*FRONT SUPPORT PANEL TOP GARNISH	Distorted	322.30 F	*162.30 FL
26	1		*SET FRONT SUPPORT PANEL TOP GARNISH CLIPS	Necessary	50.00 F	*50.00 FL
27	1		*FRONT FENDERS	N/S Buckled / O/S Repair	1,376.00 F	*558.20 FL
28	2		*FRONT FENDER INNERSHIELDS	Not Necessary	333.00 F	*- FL
29	2		*FRONT FENDER OUTER PROTECTORS	Deformed / Torn	590.00 F	*590.00 FL
30	1		*AIR CON CONDENSER	Distorted / Punctured	1,568.00 F	*748.00 FL
31	1		*AIR CON CONDENSER SIDE GARNISH	N/S Torn	296.00 F	*148.00 FL
32	1		*RADIATOR	Distorted / Punctured	1,817.50 F	*1,376.20 FL
33	1		*RADIATOR FAN COWLING	Cracked	288.30 F	*185.50 FL
34	1		*RADIATOR FAN MOTOR	Jammed	488.20 F	*350.50 FL
35	1		*RADIATOR FAN BLADE	Bent	101.50 F	*101.50 FL
36	1		*FRONT FENDER INNER PANEL N/S	Repair	525.30 F	*- FL
37	1		*FRONT WHEEL HOUSING PANEL N/S	Repair	988.20 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
38	1		*FRONT LOCK CENTRE BRACKET	Cracked	115.00 F	*115.00 FL
39	1		*AIR DUCT	Distorted	215.00 F	*215.00 FL
40	1		*INTAKE MANIFOLD	Cracked	788.00 F	*788.00 FL
41	1		*FRONT AIR CON FAN ASSY	Cracked / Jammed	344.20 F	*344.20 FL
42	1		*RESONATOR BOX	Not Necessary	385.20 F	*- FL
43	2		*FRONT GRILLE CHROME MOULDING	Necessary	197.00 F	*197.00 FL
44	1		*BATTERY TRAY	Not Necessary	180.20 F	*- FL
45	1		*WASHER TANK	Not Necessary	305.20 F	*- FL
46	1		*FRONT WINDSCREEN	Cracked	1,488.20 F	*1,455.20 FL
47	1		*TAILGATE	Badly Dented	1,100.90 F	*953.00 FL
48	1		*TAILGATE H LOGO	Necessary	35.80 F	*35.80 FL
49	1		*TAILGATE VEZEL EMBLEM	Necessary	56.20 F	*56.20 FL
50	1		*TAILGATE OUTER HANDLE GARNISH	Bent / Cracked	399.20 F	*399.20 FL
51	1		*TAILGATE REFLECTORS	N/S Cracked	921.00 F	*355.20 FL
52	1		*TAILGATE INNER LOCK	Twisted	198.50 F	*198.50 FL
53	1		*TAILGATE INNER TRIM BOARD	Distorted	321.70 F	*321.70 FL
54	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	45.00 F	*45.00 FL
55	2		*TAILGATE DAMPERS	Not Necessary	598.20 F	*- FL
56	1		*TAILGATE WEATHERSTRIP	Torn	135.70 F	*135.70 FL
57	1		*TAILGATE REAR WIPER ARM	Not Necessary	188.20 F	*- FL
58	1		*TAILGATE REAR WIPER MOTOR	Not Necessary	695.00 F	*- FL
59	1		*TAILGATE KEYLESS SENSOR	Not Necessary	180.00 F	*- FL
60	1		*REAR WINDSCREEN	Shattered	1,566.20 F	*1,425.20 FL
61	1		*REAR WINDSCREEN MOULDING	Necessary	181.00 F	*118.00 FL
62	1		*TAILGATE TOP SPOILER	Not Necessary	950.00 F	*- FL
63	1		*REAR BUMPER	Distorted	762.70 F	*762.70 FL
64	1		*REAR BUMPER SIDES	N/S Distorted	570.20 F	*285.10 FL
65	1		*REAR BUMPER SIDE RETAINERS	N/S Cracked	70.40 F	*35.20 FL
66	1		*REAR BUMPER REFLECTORS	N/S Broken	170.00 F	*85.00 FL
67	1		*REAR BUMPER DIFFUSER	Distorted	348.20 F	*348.20 FL
68	1		*SET REAR BUMPER DIFFUSER CLIPS	Necessary	50.00 F	*50.00 FL
69	2		*REAR BUMPER MUDFLAPS	Not Necessary	290.00 F	*- FL
70	1		*TAILLAMPS	N/S Broken	970.40 F	*485.20 FL
71	1		*TAILGATE HOUSING PANELS	N/S Badly Dented	390.00 F	*195.00 FL
72	1		*REAR END PANEL	Badly Dented	514.00 F	*514.00 FL
73	1		*REAR END PANEL TOP GARNISH	Cracked	184.00 F	*184.00 FL
74	1		*REAR FLOOR PANEL	Badly Dented / Buckled	912.00 F	*912.00 FL
75	1		*REAR FLOOR PANEL TOP BOARD	Distorted	499.20 F	*316.50 FL
76	1		*REAR FLOOR PANEL HYBRID BATTERY COVER	Deformed	685.00 F	*305.20 FL
77	1		*REAR FLOOR PANEL SIDE PANEL N/S	Badly Dented	399.20 F	*188.50 FL
78	1		*REAR FLOOR PANEL TOP TRAY	Cracked	299.20 F	*299.20 FL
79	1		*REAR FENDERS	N/S Distorted / O/S Repair	1,770.20 F	*885.10 FL
80	1		*REAR FENDER OUTER PROTECTORS	N/S Torn	528.00 F	*264.00 FL
81	1		*REAR FENDER INNER TRIM BOARD	N/S Distorted	1,290.60 F	*344.20 FL
82	1		*REAR EXHAUST	Not Necessary	899.20 F	*- FL
83	2		*REAR EXHAUST MOUNTINGS	Not Necessary	90.00 F	*- FL
84	2		*REAR SHOCK ABSORBERS	Not Necessary	610.00 F	*- FL
85	1		*REAR WHEELHUB BEARINGS	N/S Damaged	900.00 F	*450.00 FL
86	1		*REAR AXLE ARM	Repair	1,885.00 F	*- FL
87	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	199.00 F	*- FL
88	1		*REAR WHEEL HOUSING PANEL N/S	Badly Dented	1,150.00 F	*850.50 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
89	1		*REAR END LOCK SENSOR	Not Necessary	288.50 F	*- FL
90	1		*REAR FENDER UNDER TRIM N/S	Distorted	299.30 F	*248.50 FL
91	1		*REAR CHASSIS MEMBER N/S	Repair	699.20 F	*- FL
92	2		*REAR DOOR	Repair	1,996.40 F	*- FL
93	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
94	1		*REAR WINDSCREEN SOLAR FILM	Necessary	250.00 FS	*150.00 FS
95	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*30.00 FS
96	1		*SET REAR REVERSE CAMERA	Shorted	380.00 FS	*300.00 FS
97	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
98	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
99	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	200.00 FS	*120.00 FS
100	1		*FRONT LICENCE PLATE W/HOLDER	Repeated	50.00 FS	*- FS
101	1		*BATTERY	Dented	220.00 FS	*100.00 FS
102	1		*BOT RADIATOR COOLANT	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **53,912.51** **29,368.20**
 - List Item Discount on L Items 0.00/20.00% (S\$) 0.00 5,701.64

Total Parts (S\$) **53,912.51** **23,666.56**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	100.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	100.00	50.00
3	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REPLACING REAR WINDSCREEN	New	150.00	120.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY	New	150.00	80.00
7	TO DISMANTLE & REFIX PETROL TANK	New	100.00	60.00
8	TO DISMANTLE & REFIX REAR UNDERCARRIAGE	New	380.00	200.00
9	TO SPRAY RUST PROOFING	New	200.00	150.00
10	TO REFILL AIR CON GAS	New	150.00	100.00
11	TO DISMANTLE & REFIX HYBRID BATTERY & REPROGRAMME	New	380.00	350.00
12	TO CONDUCT WHEEL ALIGNMENT	New	100.00	80.00
13	TO DISMANTLE & REFIX FRONT WINDSCREEN	New	150.00	120.00
14	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS	New	4,500.00	2,600.00
15	TO PUTTY & SPRAY PAINTING	New	3,800.00	2,000.00
Gross Labour Cost (S\$)			10,460.00	6,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >