



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006912
INV Date 08/10/2020
Reference CC4/FCI20002268/R1ba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLB 7882Y
Insured Veh. SHD 3127H
Claim No. D20000797MFSH
Policy No. D-20094922MFSH
Accident Date 01/02/2020
Inspection Date 10/02/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20002268/R1ba3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 08-10-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3127H	Veh. Inspected	SLB 7882Y	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20000797MFSH	Excess (\$)	0.00	
Assign From	CHRIS	Assign Date	10/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA COROLLA ALTIS 1.6	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MR053REH104548626	Colour	GREY	
Odometer	270174	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	HANKOOK	6 mm	
L/H Front Tyre	205/55 R16	HANKOOK	6 mm	
R/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
L/H Rear Tyre	205/55 R16	HANKOOK	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/02/2020	Inspection Date	10/02/2020	
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 7882Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	458.00	458.00
10	FRONT BUMPER CLIPS @\$5.50	NECESSARY	55.00	55.00
2	FRONT BUMPER OUTER BRACKET LH/RH @\$81.00	N/S NECESSARY / O/S NOT NECESSARY	162.00	81.00
1	FRONT FOG LAMP LH	SERVICEABLE	325.00	-
1	FRONT FOG LAMP COVER LH	CRACKED	92.00	92.00
1	FRONT REINFORCEMENT	SERVICEABLE	382.00	-
1	FRONT REINFORCEMENT SPONGE	CRACKED	79.00	79.00
1	FRONT CENTRE GRILLE	SERVICEABLE	564.00	-
1	FRONT CENTRE LOWER GRILLE	SERVICEABLE	155.00	-
1	HEADLAMP LH	BROKEN	850.00	850.00
1	HEADLAMP CHROME LH	CRACKED	181.00	181.00
1	FRONT FENDER LH	BENT	781.00	781.00
1	FRONT FENDER SHIELD LH	CUT	200.00	200.00
10	FRONT FENDER SHIELD CLIPS LH @\$5.50	NECESSARY	55.00	55.00
10	FRONT FENDER SQUARE CLIPS LH @\$5.50	NECESSARY	55.00	55.00
1	FRONT VVT-I LOGO LH	NECESSARY	48.00	48.00
1	BONNET	BENT	1,037.00	1,037.00
2	BONNET HINGE LH/RH @\$75.00	SERVICEABLE	150.00	-
1	BONNET LOCK	SERVICEABLE	130.00	-
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	1,100.00	-
1	AIR CLEANER BOX	NOT NECESSARY	1,100.00	-
1	AIR CLEANER TUBE	NOT NECESSARY	160.00	-
1	SHOCK ABSORBER LH	BENT	402.00	402.00
1	SHOCK ABSORBER MOUNTING LH	NECESSARY	182.00	182.00
1	LOWER ARM LH	BENT	608.00	608.00
1	KNUCKLE ARM LH	BENT	521.00	521.00
1	FRONT WHEEL BEARING LH	BENT	142.00	142.00
1	LOWER ARM BALL JOINT LH	BENT	228.00	228.00
1	TIE ROD END LH	SERVICEABLE	146.00	-

Report Ref No. CC4/FCI20002268/R1ba3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	STEERING RACK	SERVICEABLE	1,625.00	-
1	STABILIZER LINK LH	SERVICEABLE	202.00	-
1	FRONT TYRE LH	SERVICEABLE	82.00	-
1	FRONT FENDER RH (NPA)	TO REPAIR SEE LABOUR	-	-
1	HEADLAMP RH (ADDITIONAL)	CRACKED	850.00	850.00
1	WHEEL HUB (ADDITIONAL)	BENT	220.00	220.00
1	RESONATOR (ADDITIONAL)	CRACKED	103.00	103.00
	LESS 25% DISCOUNT		-3,357.50	-1,807.00
			10,072.50	5,421.00
1	FRONT RIM 16 INCH (SN)	SCRATCHED	800.00	500.00
	LESS 25% DISCOUNT		-200.00	-
			600.00	500.00
	LABOUR			
	REMOVE,REPAIR AND REPLACE PARTS FOR AFFECTED AREAS.INCLUSIVE OF THE REPAIR OF FRONT DOOR LH AND FRONT FENDER RH.		1,250.00	750.00
	SPRAY PAINT ON THE AFFECTED AREAS.		1,250.00	1,000.00
	CHECK WIRING,RE-ALIGN HEADLAMPS & ENSURE PROPER FUNCTIONING.		100.00	30.00
	REMOVE & REPLACE FRONT UNDERCARRIAGE & SUBFRAME.		400.00	100.00
	CHECK,RE-ADJUST AND COMPUTERISE WHEEL ALIGNMENT/SIDE SLIP TEST.		200.00	60.00
	DISMANTLE & REPLACE STEERING SYSTEM,BRAKE PUMP & BOOSTER TO FACILITATE REPAIR.	NOT NECESSARY	180.00	-
	REMOVE,REPLACE & BALANCE RIM/TYRE.		40.00	40.00
			-	-
			-	-
			-	-
			3,420.00	1,980.00
GRAND TOTAL			14,092.50	7,901.00
RECOMMENDED COST OF REPAIRS				7,901.00

Report Ref No. CC4/FCI20002268/R1ba3q2



Report Ref No. CC4/FCI20002268/R1ba3q2

A handwritten signature in black ink, appearing to read 'MRB'.

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

A handwritten signature in black ink, appearing to read 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 7882Y

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

