Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002277/KGS3Q2

M9R8839C003300

Date: 08/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 1900082984 Policy No: Claimant SHF769P Insured Vehicle No: SMK2840S Vehicle No:

Date of Loss: ΤP 06/02/2020 Nature of Claim: Claim No: 3171680391SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHF769P Reg No:

RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR Engine No: Make & Model:

30/06/2016 (Man. Year: 2015) Reg. Date: Chassis No: VF1ABL15AUC283238

Colour: Metallic White/Red Odometer: 432824 km

1995 cc **Engine Capacity:** Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16 Front Left Side: Sailun 9 mm Rear Left Side: Sailun 8 mm Front Right Side: Rear Right Side: Sailun 8 mm Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,841.00	436.71	9,404.29	95.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,170.00	320.00	13,850.00	97.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	24,011.00	756.71	23,254.29	96.85
Approved Total (Overridden) (S\$)		600.00		
(S\$)	24,011.00	600.00	23,411.00	97.50
+ GST 7.00/7.00% (S\$)	1,680.77	42.00	1,638.77	97.50
Nett Amount (S\$)	25,691.77	642.00	25,049.77	97.50
+ Car Rental (3.0 x S\$8	31.13/day) (S\$)	243.39		
+ Doc/S	earch Fee (S\$)	7.45		
Net	tt Liability (S\$)	892.84		

INSPECTION

Date of Assignment: 07/02/2020

Trans-cab Auto Services Pte Ltd Date Inspected: 07/02/2020 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 1.0 days Adjuster Report Page 2 of 5

Adjuster: KENNETH KONG Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

F	$\mathbf{\overline{2}}$	0	\sim	m	m	er	10	lec	ΙP	ar	te
	•	ᆫ	CU			CI	IU			aı	LO

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BUMPER COVER REAR	Repair	561.70 FL	*- FL	
2	1		*BUMPER LOWER REAR	Dented/Cut	411.90 FL	*411.90 FL	
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL	
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL	
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL	
6	1		*BUMPER REFLECTOR RH	Serviceable	16.60 FL	*- FL	
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL	
8	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL	
9	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL	
10	1		*BUMPER BEAM REAR	Repair	547.80 FL	*- FL	
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL	
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	100.90 FL	*- FL	
13	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL	
14	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	404.56 FL	*- FL	
15	1		*TAILLAMP RH	Serviceable	313.10 FL	*- FL	
16	1		*TAILLAMP PANEL RH	Repair	401.40 FL	*- FL	
17	1		*TAILLAMP LH	Serviceable	401.40 FL	*- FL	
18	1		*TAILLAMP PANEL LH	Repair	401.40 FL	*- FL	
19	1		*BOOT REAR	Repair	1,677.20 FL	*- FL	
20	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL	
21	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL	
22	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL	
23	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL	
24	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL	
25	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL	
26	1		*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*- FL	
27	1		*BOOT LOCK	Serviceable	246.60 FL	*- FL	
28	1		*BOOT HINGE LH	Serviceable	254.20 FL	*- FL	
29	1		*BOOT HINGE RH	Serviceable	253.80 FL	*- FL	
30	1		*BOOT STRUT LH	Serviceable	145.10 FL	*- FL	
31	1		*BOOT STRUT RH	Serviceable	145.10 FL	*- FL	
32	1		*EXHAUST CAP REAR	Serviceable	125.40 FL	*- FL	
33	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS	
34	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS	
35	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*-FS	
36	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*-FS	
37	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*-FS	
38	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS	
39	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS	
40	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*-FS	
41	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS	
42	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*-FS	
43	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS	
44	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS	
45	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS	
46	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*-FS	
47	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS	
48	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*-FS	
49	1		*REAR LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS	
	-	part. S=Spcl	Nett. L=ListItemDisc.	,			
			Sub Total (S\$)	10,793.76	477.90		
			952.76	41.19			

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=ge... 8/1/2021

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
				Total Parts (S\$)	9,841.00	436.71	
	Report was unsubmitted during this print-out.						

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount			
Lab	our Items						
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00			
2	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00			
3	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00			
4	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00			
5	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00			
6	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00			
7	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	100.00			
8	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00			
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00			
10	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00			
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00			
12	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00			
	Gross Labour	14,170.00	320.00				
	Report was unsubmitted during	g this print-out.					

< END OF ESTIMATES >