

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002292/T1DA3Q2

Date: 07/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900078928

Claimant
Vehicle No : SML3598E **Insured Vehicle No :** SLZ3354E

Date of Loss: 06/02/2020 Nature of Claim: TP Claim No: 3031078923SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML3598E		
Make & Model:	HONDA FIT, 1.3 GF CVT (A)	Engine No:	L13B1452541
Reg. Date:	15/05/2019 (Man. Year: 2019)	Chassis No:	GK31344110
Colour:	Red	Odometer:	6560 km
Engine Capacity:	1317 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/70 R14	Rear Tyre Size:	175/70 R14
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,909.26	3,601.54	7,307.72	66.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,690.00	2,090.00	2,600.00	55.44
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,599.26	5,691.54	9,907.72	63.51
Approved Total (Overridden) (S\$)		4,550.00		
(S\$)	15,599.26	4,550.00	11,049.26	70.83
+ GST 7.00/7.00% (S\$)	1,091.95	318.50	773.45	70.83
Nett Amount (S\$)	16,691.21	4,868.50	11,822.71	70.83
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
Nett Liability (S\$)		5,768.50		

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 10/02/2020 Inspected At:

Teamwork Garage Pte Ltd (HQ)
53 Ubi Ave 1 #01-24, Paya Ubi
Industrial Park
Singapore 408934

Estimated Period of Repair: 7.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,012.81 FL	*803.20 FL
2	2		*TAILGATE HINGE	Repair	89.02 FL	*- FL
3	2		*TAILGATE DAMPER	Not Necessary	277.62 FL	*- FL
4	1		*TAILGATE LOCK	Bent	234.00 FL	*234.00 FL
5	1		*TAILGATE LOCK STRIKER	Not Necessary	36.84 FL	*- FL
6	1		*TAILGATE INNER TRIM	Cracked	336.00 FL	*336.00 FL
7	1		*TAILGATE GLASS MOULDING	Necessary	72.84 FL	*72.84 FL
8	1		*TAILGATE OUTER GARNISH	Not Necessary	348.00 FL	*- FL
9	1		*TAILGATE EMBLEM LOGO	Necessary	45.60 FL	*45.60 FL
10	1		*TAILGATE EMBLEM -FIT	Necessary	43.20 FL	*43.20 FL
11	1		*TAILGATE WIPER MOTOR	Not Necessary	354.00 FL	*- FL
12	1		*TAILGATE INNER HANDLE COVER	Deformed	45.60 FL	*45.60 FL
13	1		*REAR BUMPER	Deformed	622.68 FL	*545.30 FL
14	1		*REAR BUMPER RETAINER	N/S Not Necessary /O/SDeformed	78.48 FL	*39.24 FL
15	1		*REAR BUMPER SIDE COVER	N/S Not Necessary /O/SDeformed	116.88 FL	*58.44 FL
16	1		*REAR BUMPER LOWER GARNISH	Deformed	482.44 FL	*210.00 FL
17	1		*REAR BUMPER TOW COVER	Not Necessary	42.00 FL	*- FL
18	1		*REAR BUMPER UNDERCOVER	Not Necessary	126.48 FL	*- FL
19	1		*END PANEL	Bent	692.00 FL	*366.50 FL
20	1		*END PANEL TOP GARNISH	Deformed	296.84 FL	*185.50 FL
21	1		*FLOOR COMPARTMENT	Repair	956.88 FL	*- FL
22	1		*SPARE TYRE TOP BOARD	Not Necessary	347.64 FL	*- FL
23	1		*SPARE TYRE TOOL SPONGE	Cracked	294.00 FL	*294.00 FL
24	2		*REAR FENDER INNER TRIM	Not Necessary	816.00 FL	*- FL
25	1		*REAR TAILLAMP	N/S Not Necessary / O/S Cut	740.88 FL	*305.00 FL
26	2		*REAR TAILLAMP PANEL	Not Necessary	284.88 FL	*- FL
27	1		*REAR EXHAUST SILENCER	Bent	744.44 FL	*505.00 FL
28	2		*REAR EXHAUST MOUNTING	Not Necessary	68.88 FL	*- FL
29	1		*REAR FENDER	Not Necessary	1,404.72 FL	*- FL
30	1		*REAR EXTENTION PANEL RH	Repair	344.84 FL	*- FL
31	1		*REAR AIRVENT RH	Not Necessary	70.44 FL	*- FL
32	1		*KEYLESS SENSOR	Not Necessary	148.05 FL	*- FL
33	1		*KEYLESS SPEAKER	Not Necessary	161.60 FL	*- FL
34	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
35	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
36	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
37	1		*SET REAR TAILGATE INNER TRIM CLIP	Necessary	20.00 FS	*20.00 FS
38	1		*SET REAR REVERSE SENSOR	Not Working	400.00 FS	*200.00 FS
39	1		*REAR REVERSE CAMERA	Not Necessary	600.00 FS	*- FS
40	1		*FLOOR INSULATOR	Not Necessary	120.00 FS	*- FS
41	1		*JOINT SEALANT	Necessary	120.00 FS	*40.00 FS
42	1		*WINDSCREEN SEALANT	Necessary	120.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 13,256.58 4,419.42
- List Item Discount on L Items 20.00/20.00% (\$\$) 2,347.32 817.88

Total Parts (\$\$) 10,909.26 3,601.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE AND RENEW REAR REVERSE SENSOR	New	120.00	30.00
3	REMOVE,REFIT LINING ,TRIM AND GARNISH	New	200.00	60.00
4	REMOVE AND RENEW REAR EXHAUST	New	120.00	60.00
5	REMOVE AND REFIT FUEL TANK	New	120.00	0.00
6	REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
7	TRANDFER PARTS ,ATACHMENT FROM OLD TAILGATE TO NEW	New	200.00	60.00
8	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	900.00
9	SPRAY PAINTING ON AFFECTED AREAS	New	1,800.00	800.00
10	APPLY ANTI RUST ON AFFECTED AREAS	New	150.00	30.00
Gross Labour Cost (\$)			4,690.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >