

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC3/AIG20002297/GDA3Q2**Date:** 03/09/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100447099  
**Claimant**  
**Vehicle No :** SLX8488E **Insured Vehicle No :** SFU2507K  
Date of Loss: 05/02/2020 Nature of Claim: TP Claim No: 3090063205SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX8488E**  
Make & Model: BMW X1 SDRIVE18I, 1.5 LED NAV (A) Engine No: F334H333B38A15A  
Reg. Date: 30/11/2016 (Man. Year: 2016) Chassis No: WBAHS120505F03008  
Colour: Black Odometer: 63099 km  
Engine Capacity: 1499 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R18 Rear Tyre Size: 225/50 R18  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,168.20	3,242.00	926.20	22.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,948.00	4,781.00	1,167.00	19.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,116.20</b>	<b>8,023.00</b>	<b>2,093.20</b>	<b>20.69</b>
<b>+ GST 7.00/7.00% (S\$)</b>	708.13	561.61	146.52	20.69
<b>Nett Amount (S\$)</b>	<b>10,824.33</b>	<b>8,584.61</b>	<b>2,239.72</b>	<b>20.69</b>
<b>+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		428.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>9,014.61</b>		

INSPECTION

Date of Assignment: 02/03/2020  
Date Inspected: 02/03/2020 Inspected At: Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 5.0 days

**Adjuster:** XING GUO QIANG

**Manager:** CHAN JIA LE

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*BOOTLID	Buckled	1,236.65 FS	*1,236.65 FS
3	1		*RR BUMPER CARRIER	Not Necessary	496.35 FS	*- FS
4	1		*MOUNTING SMART OPENER	Not Necessary	45.55 FS	*- FS
5	1		*RR BUMPER LH CORNER MOUNTING	Not Necessary	142.65 FS	*- FS
6	1		*RR BUMPER RH CORNER MOUNTING	Not Necessary	142.65 FS	*- FS
7	1		*REAR BUMPER PANEL PRIMED	Deformed	903.40 FS	*903.40 FS
8	1		*REAR BUMPER MIDDLE TRIM PANEL (PDC)	Deformed	265.65 FS	*265.65 FS
9	1		*REAR BUMPER TRIM BOTTOM (LINES)	Cut	232.45 FS	*232.45 FS
10	2		*EMBLEM GROMMET	Necessary	1.70 FS	*1.70 FS
11	1		*BMW PLAQUE WITH ADHESIVE FILM	Necessary	71.60 FS	*71.60 FS
12	1		*LETTERING X1	Necessary	64.45 FS	*64.45 FS
13	10		*BUMP STOP	Necessary (6 PCS ONLY)	37.50 FS	*22.50 FS
14	1		*EXPANDING RIVET BLACK (30 PCS)	Necessary (20 PCS ONLY)	42.00 FS	*28.00 FS
15	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
16	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
17	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Necessary	27.85 FS	*27.85 FS
18	4		*BLIND RIVET NUT M6	Necessary	10.80 FS	*10.80 FS
19	2		*EXPANDING NUT	Necessary	2.00 FS	*2.00 FS
20	2		*HOOK AND LOOP FASTENER	Necessary	5.70 FS	*5.70 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 4,168.20 3,242.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS BOOTLID INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT	New	2,550.00	1,700.00
2	TO RESPRAY REAR BUMPER AND BOOT LID	New	1,923.00	1,731.00
3	TO CARRY OUT BODY CAVIRT PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS TO TRANSFER FROM OLD TO NEW BOOT LID	New	574.00	574.00
5	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
6	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	531.00	451.00
7	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
			<b>Gross Labour Cost (S\$)</b>	<b>4,781.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >