

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002329/HKS3Q2

Date: 28/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900123431

Claimant
Vehicle No : GBJ5735D **Insured Vehicle No :** SKE1832C

Date of Loss: 06/02/2020 Nature of Claim: TP Claim No: 9205095724SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ5735D		
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Engine No:	1KD2857049
Reg. Date:	07/06/2019 (Man. Year: 2019)	Chassis No:	JTFAT35Y60K213302
Colour:	White	Odometer:	39837 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R12
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,564.35	2,358.32	6,206.03	72.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,100.00	1,230.00	1,870.00	60.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,664.35	3,588.32	8,076.03	69.24
Approved Total (Overridden) (S\$)		2,850.00		
Nett Amount (S\$)	11,664.35	2,850.00	8,814.35	75.57
+ Loss of Use (6.0 x S\$140.00/day) (S\$)		840.00		
Nett Liability (S\$)		3,690.00		

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 11/02/2020 Inspected At:

Carsmith Private Limited (HQ)
13 KAKI BUKIT ROAD 4 #01-20
BARTLEY BIZ CENTRE
Singapore 417807

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT SIDE GATE }	Bent	1,637.80 FL	*1,580.30 FL
2	1		*LEFT SIDE GATE HINGES }		440.00 FL	*- FL
3	1		*LEFT SIDE MEMBER	Repair	1,725.40 FL	*- FL
4	1		*REAR TAILGATE	Not Necessary	1,107.00 FL	*- FL
5	1		*REAR LEFT TAILGATE RUBBER BRACKET	Serviceable	295.60 FL	*- FL
6	1		*REAR LEFT TAILGATE RUBBER MOUNTING	Serviceable	168.80 FL	*- FL
7	1		*REAR LEFT TAILGATE LOCK	Serviceable	194.30 FL	*- FL
8	1		*REAR LEFT FLAP PANEL	Cut	699.80 FL	*590.30 FL
9	1		*REAR LEFT MUD FLAP	Crumpled	168.50 FL	*120.50 FL
10	1		*REAR LEFT TAILLAMP	Not Necessary	298.60 FL	*- FL
11	1		*REAR LEFT TAILLAMP BRACKET	Not Necessary	110.00 FL	*- FL
12	1		*REAR TAILGATE STICKER (70KM/H)	Not Necessary	50.00 FS	*- FS
13	1		*REAR TAILGATE STICKER (TOYOTA)	Not Necessary	80.00 FS	*- FS
14	1		*REAR TAILGATE STICKER (13PAX)	Not Necessary	50.00 FS	*- FS
15	1		*LEFT SIDE GATE ALUMINIUM CLADDING (SPECIAL TYPE)	Serviceable	1,100.00 FS	*- FS
16	1		*LEFT SIDE GATE ALUMINIUM CLADDING RIVET	Necessary	150.00 FS	*60.00 FS
17	1		*REAR TAILGATE ALUMINIUM CLADDING (SPECIAL TYPE)	Not Necessary	600.00 FS	*- FS
18	1		*REAR TAILGATE ALUMINIUM CLADDING RIVET	Not Necessary	80.00 FS	*- FS
19	1		*LEFT SIDE GATE CORPORATE STICKER	Necessary	550.00 FS	*200.00 FS
20	1		*REAR LEFT STEEL RIM	Bent	450.00 FS	*380.00 FS
21	1		*REAR LEFT TYRE	Not Necessary	320.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 10,275.80 2,931.10
- List Item Discount on L Items 25.00/25.00% (\$\$) 1,711.45 572.78

Total Parts (\$\$) 8,564.35 2,358.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,REMOVING & REPLACING OF PARTS	New	1,100.00	600.00
2	TO PUTTY & SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	500.00
3	TO REMOVE & RENEW TAILGATE ALUMINIUM CLADDING /RIVETS	New	200.00	0.00
4	TO REMOVE & RENEW LEFT SIDE GATE ALUMINIUM CLADDING /RIVETS	New	150.00	40.00
5	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
6	TO APPLY TUFF COAT	New	150.00	0.00
7	TO CONDUCT WHEEL ALIGNMENT	New	250.00	60.00
Gross Labour Cost (\$\$)			3,100.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >