

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002338/HKS3Q2

Date: 24/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800013180

Claimant
Vehicle No : FBN1159Y **Insured Vehicle No :** SJU450E

Date of Loss: 04/02/2020 Nature of Claim: TP Claim No: 0993697873SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN1159Y	Engine No:	G3H6E0014548
Make & Model:	YAMAHA NMAX155, 155cc	Chassis No:	MH3SG431000011694
Reg. Date:	10/09/2019 (Man. Year: 2019)	Odometer:	9988 km
Colour:	White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R13	Rear Tyre Size:	130/70 R13
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,589.00	829.90	759.10	47.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,344.00	404.00	940.00	69.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	2,933.00	1,233.90	1,699.10	57.93
+ GST 7.00/7.00% (\$\$)	205.31	86.37	118.94	57.93
Nett Amount (\$\$)	3,138.31	1,320.27	1,818.04	57.93
+ Loss of Use (4.0 x S\$20.00/day) (\$\$)		80.00		
Nett Liability (\$\$)		1,400.27		

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 10/02/2020 Inspected At:

Ban Hock Hin Co. Pte Ltd (HQ)
No. 6 Defu Lane 4
Singapore 539410

Estimated Period of Repair: 4.0 days

Adjuster: LEE HOCK ANN

Manager: Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BEARING STEERING CONE UPPER	Necessary	42.00 F	*42.00 FL
2	1		*BELLY PAN	Not Necessary	34.00 F	*- FL
3	1		*BOARD FOOTREST LH	Not Necessary	52.00 F	*- FL
4	1		*BOARD FOOTREST RH	Not Necessary	52.00 F	*- FL
5	1		*BOX REAR (GIVI) E450N BLACK W/O STOP LIGHT	Not Necessary	208.00 F	*- FL
6	1		*COVER CENTRE LH	Not Necessary	6.00 F	*- FL
7	2		*EMBLEM (YAMAHA) LOGO	Not Necessary	22.00 F	*- FL
8	1		*FORK FRONT ASSY	Bent / Twisted	763.00 F	*763.00 FL
9	1		*LAMP SIGNAL FRONT LH	Not Necessary	35.00 F	*- FL
10	1		*LAMP SIGNAL FRONT RH	Not Necessary	35.00 F	*- FL
11	1		*MIRROR RH	Not Necessary	37.00 F	*- FL
12	1		*MUDGUARD FRONT (WHITE)	Cracked	52.00 F	*52.00 FL
13	1		*PROTECTOR EXHAUST	Not Necessary	38.00 F	*- FL
14	1		*RACE BALL 1	Necessary	12.00 F	*12.00 FL
15	1		*RACE BALL 2	Necessary	12.00 F	*12.00 FL
16	4		*RIVET R/H	Not Necessary	4.00 F	*- FL
17	1		*STICKER (CERTISCO) NEW LOGO	Not Necessary	44.00 F	*- FL
18	1		*STICKER (CISCO) COVER CENTRE LH	Not Necessary	37.00 F	*- FL
19	1		*STICKER (CISCO) COVER REAR LH	Not Necessary	30.00 F	*- FL
20	1		*STICKER (CISCO) COWLING FRONT RH	Not Necessary	37.00 F	*- FL
21	1		*STICKER (CISCO) MUDGUARD FRONT	Not Necessary	37.00 FS	*37.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,589.00	918.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	88.10
Total Parts (\$\$)	1,589.00	829.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR-FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED	New	756.00	320.00
2	SPRAY LACQUER COVER REAR CENTRE LH	New	63.00	0.00
3	SPRAY LACQUER COVER REAR LH	New	63.00	0.00
4	SPRAY LACQUER FRONT COWLING RH	New	91.00	0.00
5	SPRAY LACQUER FRONT MUDGUARD	New	49.00	49.00
6	SPRAY PAINT COVER REAR LH	New	63.00	0.00
7	SPRAY PAINT FRONT COWLING RH	New	91.00	0.00
8	SPRAY PAINT FRONT LOWER SIDE COVER LH	New	35.00	0.00
9	SPRAY PAINT FRONT LOWER SIDE COVER RH	New	35.00	0.00
10	SPRAY PAINT FRONT PANEL LH	New	21.00	0.00
11	SPRAY PAINT FRONT PANEL RH	New	21.00	0.00
12	TRANSPORT CHARGES-DELIVERY /COLLECTION	New	56.00	35.00
Gross Labour Cost (\$\$)			1,344.00	404.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >