

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20002340/EKS3N2**Date:** 21/07/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900178843
<b>Claimant Vehicle No :</b>	SLT6865J	<b>Insured Vehicle No :</b>	SKA15Y
Date of Loss:	22/01/2020	Nature of Claim:	TP
		Claim No:	7462647457SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLT6865J</b>	Engine No:	0
Make & Model:	BLUECAR BLUECAR, (A)	Chassis No:	VL4BCEB4RHT002918
Reg. Date:	07/11/2017 (Man. Year: 2017)	Odometer:	0 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	Michelin 5 mm	Rear Right Side:	Michelin 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	1,665.60	1,417.45	248.15	14.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	950.00	380.00	570.00	60.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>2,615.60</b>	<b>1,797.45</b>	<b>818.15</b>	<b>31.28</b>
<b>+ GST 7.00/7.00% (S\$)</b>	183.09	125.82	57.27	31.28
<b>Nett Amount (S\$)</b>	<b>2,798.69</b>	<b>1,923.27</b>	<b>875.42</b>	<b>31.28</b>
<b>+ Loss of Use (3.0 x S\$70.00/day) (S\$)</b>		210.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,135.27</b>		

INSPECTION

Date of Assignment:	10/02/2020		
Date Inspected:	10/02/2020	Inspected At:	Indeco Engineers Pte Ltd (Defu) No. 39 Defu Lane 12 Singapore 539315
Estimated Period of Repair:	3.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** Khanchna Pothuraj

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER ASSY (WCP)	Broken	823.00 F	*823.00 F
2	10		*REAR BUMPER SCREW (WCP)	Necessary	20.00 F	*20.00 F
3	1		*REAR BUMPER REFLECTOR LH (WCP)	Not Necessary	48.00 F	*- F
4	1		*REAR BUMPER REFLECTOR RH (WCP)	Broken	48.00 F	*48.00 F
5	1		*REAR BUMPER REINFORCEMET (WCP)	Not Necessary	80.00 F	*- F
6	1		*REAR BUMPER REINFORCEMENT BRACKET (WCP)	Not Necessary	11.00 F	*- F
7	1		*REAR BUMPER REINFORCEMENT BRACKET (WCP)	Not Necessary	11.00 F	*- F
8	1		*REAR NUMBER PLATE W CASING	Broken	45.00 FS	*40.00 FS
9	1		*NUMBER PLATE LAMP LH (WCP)	Broken	42.00 F	*42.00 F
10	1		*NUMBER PLATE LAMP RH (WCP)	Broken	42.00 F	*42.00 F
11	1		*FRONT NUMBER PLATE W CASING	Broken	45.00 FS	*40.00 FS
12	1		*REAR RH FENDER COVER (WCP)	Broken	188.00 F	*188.00 F
F=Franchise part. S=SpcNett.						
Sub Total (S\$)					1,403.00	1,243.00
+ Margin on L,N Items 20.00/15.00% (S\$)					262.60	174.45
Total Parts (S\$)					1,665.60	1,417.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPAIR REPLACE REAR BUMPER ,REFLECTORS ,NUMBER PLATES AND AFFECTED AREA	New	400.00	300.00
2	TO PUTTY AND RESPRAY ON REAR BUMPER AND AFFECTED AREA	New	300.00	0.00
3	TO APPLY TUFF KOTE	New	150.00	30.00
4	TO CHECK WIRING	New	100.00	50.00
<b>Gross Labour Cost (\$\$)</b>			<b>950.00</b>	<b>380.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >