



Your Ref : S0M02FP5

Date: 18th March 2020

Our Ref : CS4/ASM20002344/Ntd3e2

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01

AXA Tower

Singapore 068811

(The Motor Claims Department)

Attn: Kitty Teo

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJK 4681G
ACCIDENT ON 07/02/2020**

Instruction was received to inspect the vehicle Reg. No. SJK 4681G. The inspection was conducted on 12/02/2020 at the premises of M/s Progressive Car Care Pte Ltd, Blk 3022A Ubi Road 1 #01-45/46, Singapore 048716.

The following vehicle information was recorded:

Registration Number	: SJK 4681G
Make/Model	: Honda Civic 1.8L 5AT
Year of Registration	: 2008
Body Colour	: Grey
Chassis Number	: JHMFD16309S200228
Engine Capacity	: 1799 cc
Speedometer Reading	: Battery Melted

The Vehicle Caught Fire. The Cause Of Fire Probably Due To Electrical Short Circuit.
(Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“uneconomical Total Loss”**.

Market Value	S\$ 28,000.00
Less: LTA Reimbursement Value (RV)	(S\$ 11,914.00)
Nett Liability	<u>S\$ 16,086.00</u>


Vehicle Inspected By:



MUHD NAZRIL (NAZ)

Technical Investigator

LL.B. (Hons) London



K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.