

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002347/R1QF3E2

Date: 29/06/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSN19287119000

Claimant Vehicle
No : SKU9282CInsured Vehicle
No : XE5058R

Date of Loss: 04/02/2020

Nature of Claim: TP

Claim
No: SNM20D200636C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKU9282C**

Make & Model: AUDI Q3, 1.4 TFSI (A)

Engine No: CZD886148

Reg. Date: 10/01/2020 (Man. Year: 2019)

Chassis No: WAUZZZF31L1010356

Colour: Grey

Odometer: 2332 km

Engine Capacity: 1395 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R18

Rear Tyre Size:

235/55 R18

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,467.90	5,797.10	11,670.80	66.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,472.00	4,172.00	2,300.00	35.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,939.90	9,969.10	13,970.80	58.36
+ GST 7.00/7.00% (S\$)	1,675.79	697.84	977.95	58.36
Nett Amount (S\$)	25,615.69	10,666.94	14,948.75	58.36

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 11/02/2020 Inspected At:

Premium Automobiles Pte Ltd - Alexandra
(HQ)

281 Alexandra Pte Ltd, Level B2

Singapore 159938

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Jun 2020)

Parts: M1-SUV AUDI Q3 1.4 TFSI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU9282C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	1,946.00 FS	*- FS
2	2		*FRONT BUMPER CLOSING ELEMENT - LH / RH	Serviceable	110.00 FS	*- FS
3	1		*FRONT BUMPER GRILLE - CENTRE	Serviceable	204.00 FS	*- FS
4	1		*FRONT BUMPER FRONT SPOILER	Serviceable	361.00 FS	*- FS
5	2		*FRONT BUMPER GRILLE - LH / RH	Serviceable	208.00 FS	*- FS
6	2		*FRONT BUMPER AIR GUIDE GRILLE - LH / RH	Serviceable	288.00 FS	*- FS
7	1		*RADIATOR GRILLE	Cracked	1,349.00 FS	*1,349.00 FS
8	1		*RADIATOR GRILLE STRIKER PLATE	Cracked	230.00 FS	*229.50 FS
9	1		*RADIATOR GRILLE COVER CAP	Serviceable	42.00 FS	*- FS
10	1		*RADIATOR GRILLE BRACKET	Serviceable	39.00 FS	*- FS
11	1		*FRONT CAMERA	Serviceable	1,098.00 FS	*- FS
12	1		*RADIATOR GRILLE SECURING PLATE	Serviceable	31.00 FS	*- FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Serviceable	96.00 FS	*- FS
14	1		*FRONT BUMPER CARRIER	Serviceable	793.00 FS	*- FS
15	1		*FRONT BUMPER COVER	Cracked	116.00 FS	*115.50 FS
16	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*12.80 FS
17	1		*AIRCON STICKER	Necessary	7.00 FS	*6.70 FS
18	2		*FRONT PARKING AID SENSOR (NPA)	Serviceable	0.00 FS	*- FS
19	2		*FRONT WHEEL COVER - LH / RH	Necessary	506.00 FS	*506.00 FS
20	1		*LED HEADLIGHT - LH	Serviceable	5,263.00 FS	*- FS
21	1		*BONNET	Bent	3,305.00 FS	*3,305.00 FS
22	1		*BONNET ATTACHMENT PARTS	Serviceable	279.00 FS	*- FS
23	1		*BONNET IMPACT PROTECTION - CENTRE	Serviceable	26.00 FS	*- FS
24	2		*BONNET STRIKER - LH / RH	Serviceable	208.00 FS	*- FS
25	2		*BONNET LID LOCK	Serviceable	403.00 FS	*- FS
26	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
27	1		*SUNDRIES	Necessary	300.00 FS	*25.70 FS
28	1		*HEADLIGHT MOUNTING LHS	Cracked	111.50 FS	*111.50 FS
29	1		*RADIATOR AIR GUIDE LHS	Cracked	35.10 FS	*35.10 FS
30	1		*HEADLIGHT SEALING FRAME LHS	Cut	60.30 FS	*60.30 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **17,467.90** **5,797.10**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER ASSY, BONNET AND LHS HEADLIGHT. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,600.00
3	TO RESPRAY FRONT BUMPER AND BONNET	New	2,700.00	1,600.00
4	TO CARRY OUT DIAGNOSTIC CHECKS	New	192.00	192.00
5	TO REAPPLY PAINT COATING ON AFFECTED AREA (BY OWNER)	New	300.00	300.00
Gross Labour Cost (\$\$)			6,472.00	4,172.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >