



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGV 9134P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DENTED	650.80	459.75
2	REAR BUMPER SIDE RETAINER	NOT NECESSARY	109.80	-
2	REAR BUMPER BRACKET	NOT NECESSARY	150.00	-
2	REAR BUMPER REFLECTOR	N/S CRACKED	296.00	106.25
1	REAR BUMPER CLIPS	NECESSARY	60.00	50.00
1	REAR BOOTLID PANEL	DENTED / BENT	699.90	665.90
1	REAR BOOTLID CENTRE MOULDING	NOT NECESSARY	168.00	-
1	REAR BOOTLID INNER LOCK	TWISTED	194.00	194.00
1	REAR BOOTLID CATCH	NOT NECESSARY	58.00	-
1	REAR BOOTLID LOGO	NECESSARY	75.90	42.60
1	REAR BOOTLID EMBLEM (VIOS)	NECESSARY	56.70	48.80
2	REAR TAILLAMPS	N/S CRACKED	699.60	349.80
1	REAR END PANEL	DENTED / BENT	756.70	615.00
1	REAR END PANEL TOP GARNISH	TWISTED	165.80	165.80
1	REAR END PANEL TOP GARNISH CLIPS	NOT NECESSARY	60.00	-
1	REAR LEFT FENDER	TO REPAIR SEE LABOUR	1,294.50	-
1	REAR LEFT FENDER INNER SHIELD	NOT NECESSARY	176.00	-
1	REAR LEFT FENDER INNER SHIELD CLIPS	NOT NECESSARY	60.00	-
1	REAR SPARE TYRE TOP GARNISH	NOT NECESSARY	265.40	-
2	REAR SPARE TYRE TOP FOAM	NOT NECESSARY	428.60	-
1	REAR SPARE TYRE PANEL	TO REPAIR SEE LABOUR	980.00	-
	LESS 25% DISCOUNT		-1,851.43	-674.48
			5,554.27	2,023.42
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	50.00
1	REAR NUMBER PLATE W/BASE GARNISH (SN)	NOT NECESSARY	80.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	280.00	200.00
			440.00	250.00

Report Ref No. CC4/TP20002352/Uea3q2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE,REPAIR & RENEW REAR AFFECTED ACCIDENT AREAS.INCLUSIVE OF THE REPAIR OF REAR LEFT FENDER AND REAR SPARE TYRE PANEL.		1,400.00	600.00
	TO PUTTY,SPRAY PAINT ON AFFECTED ACCIDENT AREAS.		1,400.00	900.00
	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING.		50.00	30.00
	TO REMOVE & INSTALL REAR BOOTLID COMPONENTS TRIM & GARNISH.		150.00	60.00
	TO REMOVE & INSTALL REAR LEFT FENDER TRIM,GARNISH.		150.00	80.00
	TO CONDUCT WATER LEAKAGE TEST.	NOT NECESSARY	150.00	-
	TO RUST PROOF AFFECTED AREAS.		200.00	60.00
			3,500.00	1,730.00
	<b>GRAND TOTAL</b>		<b>9,494.27</b>	<b>4,003.42</b>

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,200.00</b>
---	--	--	-----------------

Report Ref No. CC4/TP20002352/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.