

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002360/ESD3E2

Date: 15/04/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17307319022
Claimant Vehicle No :	SKF7833E	Insured Vehicle No :	YP2735U
Date of Loss:	31/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200598

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF7833E	Engine No:	20050518N63B44B
Make & Model:	BMW 650I, 4.4 (A)	Chassis No:	WBA6B22010D289330
Reg. Date:	25/07/2013 (Man. Year: 2013)	Odometer:	62294 km
Colour:	White		
Engine Capacity:	4395 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/35Z R20	Rear Tyre Size:	275/35Z R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,235.35	2,502.50	9,732.85	79.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,098.00	3,102.00	2,996.00	49.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,333.35	5,604.50	12,728.85	69.43
+ GST 7.00/7.00% (S\$)	1,283.33	392.32	891.01	69.43
Nett Amount (S\$)	19,616.68	5,996.82	13,619.86	69.43

INSPECTION

Date of Assignment:	25/02/2020	
Date Inspected:	19/02/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: CHEN TSUE YEE

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 15 Apr 2020)	
Parts:	N/A	BMW 650I 4.4 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF7833E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 FS	*80.00 FS
2	1		*GRILLE AIR INTAKE CENTER (M)	Not Necessary	110.85 FS	*- FS
3	1		*GRILLE AIR INTAKE LH (M)	Not Necessary	95.05 FS	*- FS
4	1		*GRILLE AIR INTAKE RH (M)	Not Necessary	95.05 FS	*- FS
5	1		*COVERING LH (M)	Not Necessary	28.70 FS	*- FS
6	1		*PRIMED FRONT BUMPER TRIM (M)	Dented	1,879.10 FS	*1,879.10 FS
7	1		*FRONT LH GRILLE	Not Necessary	199.35 FS	*- FS
8	1		*FRONT RH GRILLE	Not Necessary	199.35 FS	*- FS
9	1		*BMW EMBLEM	Necessary	71.60 FS	*71.60 FS
10	1		*LH ADAPTIVE HEADLIGHT (LED)	Not Necessary	4,502.25 FS	*- FS
11	1		*RH ADAPTIVE HEADLIGHT (LED)	Not Necessary	4,502.25 FS	*- FS
12	1		*M PERFORMANCE RH GRILLE BLACK	Cut	235.90 FS	*235.90 FS
13	1		*M PERFORMANCE LH GRILLE BLACK	Cut	235.90 FS	*235.90 FS
Total Parts (\$\$)					12,235.35	2,502.50

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER INCLUDING ATTACHMENT AND REPAIR FRONT BONNET	New	2,550.00	850.00
2	PAINTING FRONT BUMPER AND FRONT BONNET	New	2,336.00	2,102.00
3	TO REPLACE BOTH LEFT AND RIGHT HEADLIGHTS	New	1,062.00	0.00
4	TO CHECK ELECTRICAL WIRING SYSTEM OF THE FRONT SECTION FOR PROPER FUNCTION	New	150.00	150.00
Gross Labour Cost (S\$)			6,098.00	3,102.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >