

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002362/AKS3Q2

Date: 03/09/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800056019

Claimant
Vehicle No : SMA8969T **Insured Vehicle No :** GBH3953P

Date of Loss: 10/02/2020 Nature of Claim: TP Claim No: 2447495433SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA8969T		
Make & Model:	MERCEDES-BENZ C180K, 1.6 (A)	Engine No:	27191031301727
Reg. Date:	09/02/2010 (Man. Year: 2009)	Chassis No:	WDD2040452A357418
Colour:	Grey	Odometer:	98894 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Achilles 6 mm	Rear Left Side:	Achilles 6 mm
Front Right Side:	Achilles 6 mm	Rear Right Side:	Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,244.80	6,852.30	5,392.50	44.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,880.00	2,110.00	2,770.00	56.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,124.80	8,962.30	8,162.50	47.66
Approved Total (Overridden) (S\$)		7,100.00		
(S\$)	17,124.80	7,100.00	10,024.80	58.54
+ GST 7.00/7.00% (S\$)	1,198.74	497.00	701.74	58.54
Nett Amount (S\$)	18,323.54	7,597.00	10,726.54	58.54
+ Car Rental (5.0 x S\$120.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		8,204.45		
Global Sum Settlement (S\$)		8,200.00		

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 18/02/2020 Inspected At:

Dynamic Autowork Pte. Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @
Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*HEAD REST SENSOR	Not Necessary	634.00 FL	*- FL
2	1		*BOOTLID	Dented	1,444.00 FL	*1,444.00 FL
3	1		*BOOTLID SPOILER	Not Necessary	642.00 FL	*- FL
4	1		*BOOTLID OUTER MOULDING	Not Necessary	436.00 FL	*- FL
5	1		*BOOTLID LOGO	Necessary	64.00 FL	*64.00 FL
6	1		*BOOTLID EMBLEM KOMPRESSOR	Necessary	100.00 FL	*100.00 FL
7	1		*BOOTLID EMBLEM C180	Necessary	65.00 FL	*65.00 FL
8	2		*BOOTLID HINGE	Not Necessary	302.00 FL	*- FL
9	1		*BOOTLID TOP LOCK	Damaged	260.00 FL	*260.00 FL
10	1		*BOOTLID LOWER LOCK	Not Necessary	130.00 FL	*- FL
11	1		*BOOTLID WEATHERSTRIP	Cut	153.00 FL	*153.00 FL
12	1		*REAR BUMPER	Deformed	1,721.00 FL	*1,350.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	148.00 FL	*148.00 FL
14	1		*REAR BUMPER TOWING COVER	Not Necessary	48.00 FL	*- FL
15	1		*REAR BUMPER TOP CHROME (CENTER)	Necessary	190.00 FL	*190.00 FL
16	2		*REAR BUMPER TOP CHROME (SIDE)	Necessary	240.00 FL	*240.00 FL
17	1		*REAR BUMPER SIDE BOTTOM GARNISH RH	Not Necessary	265.00 FL	*- FL
18	1		*REAR BUMPER CENTRE FRAME	Cracked	365.00 FL	*365.00 FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	615.00 FL	*615.00 FL
20	1		*TAILLAMP	O/S Cut	1,084.00 FL	*542.00 FL
21	2		*TAILLAMP LOWER BRACKET	Not Necessary	118.00 FL	*- FL
22	2		*REAR FENDER TOP GARNISH	Not Necessary	150.00 FL	*- FL
23	2		*REAR FENDER COWLING	Not Necessary	244.00 FL	*- FL
24	2		*REAR FENDER INNER TRIM	Not Necessary	680.00 FL	*- FL
25	1		*REAR END PANEL	Dented	1,147.00 FL	*1,084.00 FL
26	1		*REAR END PANEL INNER GARNISH	Cracked	197.00 FL	*197.00 FL
27	1		*REAR FLOOR PANEL TOP BOARD	Torn	230.00 FL	*230.00 FL
28	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
30	1		*BOOTLID SEALANT	Not Necessary	120.00 FS	*- FS
31	1		*SET BOOTLID INSULATOR CLIP	Not Necessary	80.00 FS	*- FS
32	1		*SET BOOTLID MOULDING CLIP	Not Necessary	30.00 FS	*- FS
33	1		*SET TAILLAMP CLIPS	Necessary	30.00 FS	*10.00 FS
34	1		*SET REAR FENDER TOP GARNISH CLIP	Not Necessary	50.00 FS	*- FS
35	1		*SET REAR FENDER COWLING CLIPS	Not Necessary	80.00 FS	*- FS
36	1		*SET REAR FENDER INNER TRIM CLIPS	Not Necessary	80.00 FS	*- FS
37	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
38	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
39	4		*REAR REVERSE SENSOR	Damaged (2 PCS ONLY)	480.00 FS	*400.00 FS
40	1		*REVERSE CAMERA	Not Necessary	480.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,412.00	7,557.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,167.20	704.70
Total Parts (\$\$)	12,244.80	6,852.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING REMOVAL AND REPLACING PARTS	New	1,400.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING CHECK	New	150.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	250.00	60.00
6	TRANFER BOOTLID MECHANISM	New	80.00	60.00
7	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
8	RESET HEAD REST	New	350.00	300.00
9	REAR CHASSIS ALIGNMENT	New	250.00	0.00
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	650.00	0.00
Gross Labour Cost (\$\$)			4,880.00	2,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >