Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002369/KGA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 2100485411 Policy No: Claimant Insured Vehicle No: SLG1600H SHD5966P Vehicle No:

Date of Loss: 06/02/2020 Nature of Claim: ΤP Claim No: 4549324977SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

SHD5966P Reg No:

Make & Model: TOYOTA PRIUS, 1.8 5DR HATCHBACK (A) Engine No: 2ZR2B93227

Reg. Date: 19/12/2018 (Man. Year: 2018) Chassis No: JTDKB3FU903078631

Colour: Metallic Pearl White/Red Odometer: 102510 km

Engine Capacity: 1798 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Sailun 9 mm Rear Left Side: Sailun 6 mm Front Right Side: Rear Right Side: Sailun 6 mm Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,403.27	472.22	8,931.05	94.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	14,170.00	370.00	13,800.00	97.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	23,573.27	842.22	22,731.05	96.43
+ GST 7.00/7.00% (S\$)	1,650.13	58.96	1,591.17	96.43
Nett Amount (S\$)	25,223.40	901.18	24,322.22	96.43
+ Loss of Use (2.0 x S	\$\$50.00/day) (S\$)	100.00		
+ Car Rental (2.0 x S\$96.30/day) (S\$) + Doc/Search Fee (S\$)		192.60		
		7.45		
N	lett Liability (S\$)	1,201.23		

INSPECTION

10/02/2020 Date of Assignment:

Trans-cab Auto Services Pte Ltd Date Inspected: 10/02/2020 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 1.0 days

Adjuster: KENNETH KONG Manager: Chong Pui Lin Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	442.60 FL	*-FL
2	1		*REAR BUMPER RE-INFORCEMENT	Serviceable	332.70 FL	*- FL
3	1		*REAR BUMPER TOWING COVER	Serviceable	15.40 FL	*- FL
4	1		*GUARD,REAR BUMPER,CENTER	Dented/Cracked	576.30 FL	*576.30 FL
5	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER RH	Serviceable	117.70 FL	*- FL
7	1		*REAR TAILGATE	Serviceable	1,147.80 FL	*- FL
8	1		*REAR TAILGATE OUTER GARNISH	Serviceable	925.60 FL	*- FL
9	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
10	1		*PANEL SUB-ASSY,BODY LOWER BACK	Serviceable	650.30 FL	*- FL
11	1		*TAILLAMP LOWER RH	Serviceable	502.00 FL	*- FL
12	1		*TAILLAMP UPPER RH	Serviceable	451.80 FL	*- FL
13	1		*REAR BUMPER SIDE RH	Serviceable	123.70 FL	*- FL
14	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
15	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
16	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
17	1		*COVER,DECK TRIM,REAR	Serviceable	126.70 FL	*- FL
18	1		*COVER,FLOOR UNDER,NO 1	Serviceable	175.10 FL	*- FL
19	1		*COVER,FLOOR UNDER,NO 2	Serviceable	241.90 FL	*- FL
20	1		*COVER,REAR FLOOR	Serviceable	229.90 FL	*- FL
21	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
22	1		*SET REAR BUMPER CLIP	Not Necessary	66.00 FS	*- FS
23	1		*REAR TAILGATE TOYOTA LOGO	Not Necessary	47.00 FS	*- FS
24	1		*REAR TAILGATE WORDING PRIUS	Not Necessary	52.90 FS	*- FS
25	1		*REAR TAILGATE WORDING HYBRID	Not Necessary	53.50 FS	*- FS
26	1		*REAR TAILGATE STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
27	1		*REAR TAILGATE STICKER 6555-3333	Not Necessary	80.00 FS	*- FS
28	1		*REAR BUMPER PROTECTOR	Necessary	100.00 FS	*40.00 FS
29	1		*REAR WHEEL RIM	Serviceable	1,879.40 FS	*- FS
30	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*- FS
31	1		*REAR WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
32	1		*REAR RH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*- FS
33	1		*REAR LH BUMPER RETAINER CLIP	Not Necessary	35.00 FS	*-FS
F=Fra	nchise	part. S=SpcI	Nett. L=ListItemDisc.			
				Sub Total (S\$)	11,307.60	616.30
			- List Item Discount on L Iter	ns 25.00/25.00% (S\$) ຼ	1,904.33	144.08
				Total Parts (S\$)	9,403.27	472.22

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	Labour Items							
1	TO TRANSFER OF TAILGATE FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00				
2	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00				
3	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00				
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	6,000.00	220.00				
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00				
6	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00				
7	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00				
8	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	0.00				
9	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	N ew	170.00	0.00				
10	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH,TO FACILITATE REPAIR	New	380.00	0.00				
11	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	0.00				
12	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	6,000.00	150.00				
	Gross Labour Cost (S\$)		14,170.00	370.00				
	Report was unsubmitted during this print-out.							
Ь								

< END OF ESTIMATES >