

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III20002371/APS3Q2

Date: 09/04/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0004483
Claimant Vehicle No :	GBF8317D	Insured Vehicle No :	GBB9150G
Date of Loss:	05/02/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0000273

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF8317D	Engine No:	YD25406866A
Make & Model:	NISSAN NV350, 2.5 (A)	Chassis No:	JN1MC2E26Z0007260
Reg. Date:	22/03/2017 (Man. Year: 2016)	Odometer:	139136 km
Colour:	Silver		
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,151.70	1,757.16	394.54	18.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,660.00	990.00	1,670.00	62.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,811.70	2,747.16	2,064.54	42.91
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	4,811.70	2,200.00	2,611.70	54.28
+ GST 7.00/7.00% (S\$)	336.82	154.00	182.82	54.28
Nett Amount (S\$)	5,148.52	2,354.00	2,794.52	54.28
+ Loss of Use (4.0 x S\$70.00/day) (S\$)		280.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,636.00		
Global Sum Settlement (S\$)		2,630.00		

INSPECTION

Date of Assignment: 10/02/2020

Date Inspected: 10/02/2020 Inspected At:

New Hock Teck Motor Pte Ltd (HQ)
1 Kaki Bukit Ave 6, Blk C #01-43

Autobay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 20 Mar 2020)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF8317D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT WINDSCREEN SEAL	Necessary	135.00 F	*135.00 FL
2	1		*FRONT PANEL	Dented	1,350.30 F	*1,206.00 FL
3	1		*FRONT GRILLE	Cracked	521.50 F	*521.50 FL
4	10		*FRONT GRILLE CLIP	Necessary	65.00 F	*10.00 FL
5	1		*FRONT GRILLE EMBLEM LOGO	Necessary	79.90 F	*79.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,151.70	1,952.40
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	195.24
Total Parts (\$\$)	2,151.70	1,757.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE & REFIT AIR-CON BLOWER ,COOLANT COIL ,AIR DUCT BLOWER & TOP UP GAS	New	380.00	0.00
2	TO REMOVE & REFIT FRONT WINDSCREEN	New	120.00	120.00
3	GUM	New	60.00	60.00
4	TO REMOVE & REFIT FRONT DASHBOARD	New	450.00	0.00
5	TO CHECK WIRING	New	100.00	30.00
6	TUFF KOTE	New	150.00	80.00
7	PANEL BEATING	New	800.00	400.00
8	SPRAY PAINTING	New	600.00	300.00
Gross Labour Cost (\$\$)			2,660.00	990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >