



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 5416G

| Qty | Description of Parts   | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|--|----------------------|---------------------------|-------------------|
|     | <b><u>REPLACEMENT OF PARTS</u></b>   |                      |                           |                   |
| 1   | BONNET (CONSISTENT)  | BENT                 | 833.70                    | 833.70            |
| 1   | FRONT GRILLE (CONSISTENT)  | DENTED / DISTORTED   | 305.80                    | 305.80            |
| 1   | GRILLE LOGO (CONSISTENT)   | NECESSARY            | 60.20                     | 60.20             |
| 1   | FRONT BUMPER (CONSISTENT)  | BUCKLED              | 423.60                    | 423.60            |
| 1   | BUMPER ENFORCEMENT (CONSISTENT)  | TO REPAIR SEE LABOUR | 339.70                    | -                 |
| 1   | BUMPER LOWER GRILLE (CONSISTENT)   | SERVICEABLE          | 93.30                     | -                 |
|     | LESS 25% DISCOUNT  |                      | -514.08                   | -405.83           |
|     |  |                      | 1,542.22                  | 1,217.47          |
|     | <b><u>LABOUR</u></b>   |                      |                           |                   |
|     | TO REMOVE DAMAGED PARTS AND ATTACHMENTS .TO REPAIR /RESHAPE DENTED AREAS .REPLACE /ALIGN ABOVE PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF BUMPER ENFORCEMENT . |                      | 700.00                    | 500.00            |
|     | TO SPRAY PAINT .   |                      | 500.00                    | 450.00            |
|     |  |                      | 1,200.00                  | 950.00            |
|     | <b>GRAND TOTAL</b>   |                      | <b>2,742.22</b>           | <b>2,167.47</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>  |                      |                           | <b>1,700.00</b>   |

Report Ref No. CC4/ASM20002373/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.