

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

**Our File No:** CC4/III20002380/QPS3Q2  
**Date:** 14/06/2021

**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant Vehicle No :</b>	SLE8365B	<b>Insured Vehicle No :</b>	SHA1161L
Date of Loss:	06/02/2020	Nature of Claim:	TP
		Claim No:	MCT20020242

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SLE8365B</b>	Engine No:	L15Z12872843
Make & Model:	HONDA MOBILIO SV, 1.5 CVT (A)	Chassis No:	MRHDD4870GP000225
Reg. Date:	02/08/2016 (Man. Year: 2016)	Odometer:	68458 km
Colour:	Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,102.12	1,405.78	1,696.34	54.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,497.36	1,045.25	452.11	30.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,599.48</b>	<b>2,451.03</b>	<b>2,148.45</b>	<b>46.71</b>
<b>+ GST 7.00/7.00% (S\$)</b>	321.96	171.57	150.39	46.71

<b>Nett Amount (S\$)</b>	<b>4,921.44</b>	<b>2,622.60</b>	<b>2,298.84</b>	<b>46.71</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		321.00		
<b>Nett Liability (S\$)</b>		<b>2,943.60</b>		

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 26/02/2020

Estimated Period of Repair: 3.0 days

Inspected At: 25D SUNGEI KADUT STREET 1  
 Repairer: Hua Hong Pte Ltd (Sungei Kadut)

**Adjuster:** OI SUN PIN**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 May 2021)
<b>Parts:</b>	M1-MPV	HONDA MOBILIO SV 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLE8365B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BADGE I-DTEC (WCP) (NPA)	Serviceable	0.00 F	*- F
2	1		*BADGE HONDA (WCP) (NPA)	Serviceable	0.00 F	*- F
3	1		*BADGE I-VTEC (WCP)	Necessary	25.00 F	*25.00 F
4	1		*BADGE RS (WCP)	Necessary	32.00 F	*32.00 F
5	1		*BOOT/TAILGATE LOCK (WCP)	Serviceable	198.00 F	*- F
6	1		*BOOT /TAILGATE SEAL (WCP)	Serviceable	98.00 F	*- F
7	1		*BOOTLID /TAILGATE (WCP)	Dented	1,050.00 F	*1,050.00 F
8	1		*L/R BUMPER SUPPORT (WCP)	Serviceable	39.00 F	*- F
9	1		*L/R SIDE REFLECTOR (WCP)	Serviceable	25.00 F	*- F
10	1		*LWR REAR SCREEN SEAL (WCP)	Necessary	68.00 F	*68.00 F
11	1		*R/R BUMPER SUPPORT (WCP)	Serviceable	39.00 F	*- F
12	1		*R/R SIDE REFLECTOR (WCP)	Serviceable	25.00 F	*- F
13	1		*REAR BADGE (HONDA) (WCP)	Serviceable	38.00 F	*- F
14	1		*REAR BUMPER (WCP)	Repair	465.00 F	*- F
15	1		*REAR BUMPER CHROME (WCP)	Scratched	125.00 F	*125.00 F
16	1		*REAR BUMPER GARNISH (WCP)	Serviceable	125.00 F	*- F
17	1		*REAR PANEL (WCP)	Serviceable	350.00 F	*- F
18	1		*REAR PANEL TRIM (WCP)	Serviceable	65.00 F	*- F
19	1		*REAR SCREEN BOND KIT (WCP) (NPA)	Serviceable	0.00 F	*- F
20	1		*SET REAR SCREEN FIX (WCP) (NPA)	Serviceable	0.00 F	*- F
21	1		*RR BUMPER CLAMP KIT (WCP)	Necessary	39.00 F	*39.00 F
22	1		*SEALANT SEALANT	Necessary	40.00 FS	*40.00 FS
23	1		*REVERSE SENSOR REVERSE SENSOR	Serviceable	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Sub Total (S\$)</b>	<b>3,046.00</b>	<b>1,379.00</b>
<b>+ Margin on L,N Items 2.00/2.00% (S\$)</b>	56.12	26.78

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					3,102.12	1,405.78

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	149.0 WU X 50.00 SGD/H	New	745.00	500.00
2	LABOUR COST 113.0 WU X 50.00 SGD/H	New	565.00	425.00
3	MATERIAL COST	New	187.36	120.25
<b>Gross Labour Cost (\$\$)</b>			<b>1,497.36</b>	<b>1,045.25</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >