

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/III20002382/APS3Q2

**Date:** 24/09/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SJD7337T	<b>Insured Vehicle No :</b>	SHD3213S
Date of Loss: 19/01/2020	Nature of Claim: TP	Claim No: MCT20010438

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJD7337T	Engine No:	4A910076356
Make & Model:	MITSUBISHI LANCER, 1.6 EX SPORTS (M)	Chassis No:	JMYSRCY2A8U005359
Reg. Date:	29/01/2008 (Man. Year: 2007)	Odometer:	300420 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	225/45R17	Rear Tyre Size:	225/45R17
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,835.33	2,746.59	88.74	3.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	970.00	910.00	48.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,715.33</b>	<b>3,716.59</b>	<b>998.74</b>	<b>21.18</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
<b>Nett Amount (S\$)</b>	<b>4,715.33</b>	<b>2,900.00</b>	<b>1,815.33</b>	<b>38.50</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment:	19/02/2020	
Date Inspected:	19/02/2020 Inspected At:	Cas Garage Pte Ltd (HQ) No.1, Kaki Bukit Ave 6, #02-22 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 23 Sep 2020)
<b>Parts:</b>	143	MITSUBISHI LANCER 1.6 EX SPORTS (M) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJD7337T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Torn	882.70 FL	*882.70 FL
2	1		*FRONT LH BUMPER RETAINER	Necessary	59.80 FL	*59.80 FL
3	1		*FRONT LH FENDER	Dented	598.50 FL	*598.50 FL
4	1		*FRONT LH FENDER INNER COWLING LH	Torn	145.60 FL	*145.60 FL
5	1		*FRONT LH FOGLAMP COVER	Not Necessary	98.60 FL	*- FL
6	1		*FRONT LH HEADLAMP	Cut	798.50 FL	*798.50 FL
7	1		*SET FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
8	2		*SET FRONT FENDER INNER COWLING CLIPS	Necessary	30.00 FS	*30.00 FS
9	1		*FRONT BUMPER LOWER LIP	Cracked	450.00 FS	*450.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,093.70</b>	<b>2,995.10</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	258.37	248.51
<b>Total Parts (\$\$)</b>	<b>2,835.33</b>	<b>2,746.59</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO RENEW DAMAGED PARTS,REPLACE,BEAT,WELD,REALIGN AND ALIGNE ALL	New	800.00	300.00
2	TO RESPRAY AFFECTED AREAS	New	800.00	600.00
3	TO TUFFCOAT AFFECTED AREA	New	200.00	40.00
4	TO REMOVE/REFIT WIRING CHECK ON FRONT HEADLAMP	New	80.00	30.00
<b>Gross Labour Cost (S\$)</b>			<b>1,880.00</b>	<b>970.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >