

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM20002386/R1pa3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:CYNTHIA		Date: 13-04-2020 Code: ASM			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SBN 9604B	Veh. Inspected	SKP 5068H	
	Policy No.	GA502649	Coverage (\$)	0.00	
	Claim No.	S0M02FXI	Excess (\$)	0.00	
	Assign From		Assign Date	11/02/2020	
2. Vehicle Particulars & Condition					
	Make & Model	HYUNDAI AVANTE 1.6 AT	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2010	
	Chassis No.	KMHDU41BMAU987080	Colour	MAROON	
	Odometer	190837	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	FIRESTONE	5 mm	
	L/H Front Tyre	185/65 R15	FIRESTONE	5 mm	
	R/H Rear Tyre	185/65 R15	FIRESTONE	5 mm	
	L/H Rear Tyre	185/65 R15	FIRESTONE	5 mm	
4.	' v				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/02/2020	Inspection Date	12/02/2020	
	Survey held at	GOLD AUTOWORKS PTE LTD			
		48 TOH GUAN ROAD EAST #01-119 ENTERPRISE HUB SINGAPORE 608586			
5a.	Remarks				
	A)THE INSPECTION B)IN ACCORDANCE	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days			