

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002389/QEA3N2

Date: 20/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700053380

Claimant
Vehicle No : SLF5054M **Insured Vehicle No :** SLS5166E

Date of Loss: 29/01/2020 Nature of Claim: TP Claim No: 6809392849SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SLF5054M | | |
| Make & Model: | MAZDA 2, 1.5 SEDAN L SP.6EAT (A) | Engine No: | P520367725 |
| Reg. Date: | 29/08/2016 (Man. Year: 2016) | Chassis No: | MM6DL2SAAGW213216 |
| Colour: | Silver | Odometer: | 111354 km |
| Engine Capacity: | 1496 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (\$\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 185/65 R15 | Rear Tyre Size: | 185/65 R15 |
| Front Left Side: | Dunlop 5 mm | Rear Left Side: | Dunlop 5 mm |
| Front Right Side: | Dunlop 5 mm | Rear Right Side: | Dunlop 5 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------|-----------------|------------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (\$\$) | 0.00 | 0.00 | 0.00 | |
| Approved Total (Overridden) (\$\$) | | 5,622.00 | | |
| Nett Amount (\$\$) | 0.00 | 5,622.00 | -5,622.00 | |
| + Loss of Use (26.0 x S\$60.00/day) (\$\$) | | 1,560.00 | | |
| + Doc/Search Fee (\$\$) | | 2.00 | | |
| Nett Liability (\$\$) | | 7,184.00 | | |
| Global Sum Settlement (\$\$) | | 7,180.00 | | |

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 11/02/2020 Inspected At:

Lion City Rentals Pte Ltd (HQ)
1090 LOWER DELTA ROAD #05-12
Singapore 169201

Estimated Period of Repair: 0.0 days

Adjuster: OI SUN PIN

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

PLEASE BE INFORMED OWNER THAT THE VEHICLE NOT ECONOMICAL FOR REPAIR.

MARKET VALUE : \$48,000.00

LTA REIMBURSEMENT VALUE (RV) : \$42,378.00

NETT VALUE : \$5,622.00

IN VIEW OF THE ABOVE, THE VEHICLE IS UNECONOMICAL TO BE REPAIRED

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >