



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2003201
INV Date 16/04/2020
Reference CC4/LPC20002394/Eea3n2
Code LPC2



PROFESSIONAL SERVICE FEE

Vehicle No. SKP 3990H
Insured Veh. GBB 2891Y
Claim No. 19/20/20/VC05/023014
Policy No. Z19VC05002343
Accident Date 08/02/2020
Inspection Date 11/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20002394/Eea3n2

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 16-04-2020



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 2891Y	Veh. Inspected	SKP 3990H
Policy No.	Z19VC05002343	Coverage (\$)	0.00
Claim No.	19/20/20/VC05/023014	Excess (\$)	0.00
Assign From	ONG LI LI	Assign Date	10/02/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JHMGD18507S225972	Colour	YELLOW
Odometer	169395	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	DUNLOP	5 mm
L/H Front Tyre	195/55 R15	DUNLOP	5 mm
R/H Rear Tyre	195/55 R15	DUNLOP	5 mm
L/H Rear Tyre	195/55 R15	DUNLOP	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	08/02/2020	Inspection Date	11/02/2020
Survey held at	FALCON-AIR AUTO SERVICES PTE LTD BLK 8 PANDAN LOOP SINGAPORE 128226		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 3990H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	TAILGATE	DENTED	849.60	762.20
1	TAILGATE GLASS (BLACK)	BROKEN	980.00	686.50
1	TAILGATE LOCK	BENT	109.40	109.40
1	TAILGATE TRIMBOARD	CRUSHED	118.60	118.60
1	TAILGATE EMBLEM JAZZ	NECESSARY	58.80	58.80
1	TAILGATE LOGO	NECESSARY	20.70	20.70
1	TAILGATE WEATHERSTRIP	NOT NECESSARY	97.20	-
1	TAILGATE GARNISH	BROKEN	120.40	120.40
1	WIPER MOTOR	NOT NECESSARY	250.50	-
1	WIPER BLADE	TORN	48.00	48.00
1	WIPER ARM COVER	MISSING	12.50	12.50
1	RH TAIL LAMP	BROKEN	243.10	243.10
1	REAR END PANEL	DENTED	296.60	296.60
1	REAR BUMPER	DENTED	490.80	490.80
1	REAR BUMPER SIDE RETAINER	BROKEN	12.00	12.00
1	REAR END PANEL TOP GARNISH	NOT NECESSARY	56.10	-
	LESS 20% DISCOUNT		-752.86	-595.92
			3,011.44	2,383.68
<u>SPECIAL NETT ITEMS</u>				
1	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
1	REAR NUMBER PLATE (SN)	CUT	45.00	45.00
1	SEALANT (SN)	NECESSARY	40.00	40.00
			285.00	285.00
<u>LABOUR</u>				
	TO TRANSFER TAILGATE PARTS /MECHANISM .		50.00	50.00
	TO REMOVE/REFIX TAILGATE GLASS.		100.00	100.00
	TO REMOVE/REFIX REVERSE SENSOR & CHECK WIRING .		100.00	20.00
	TO RUSTPROOF & WATER LEAKAGE TEST.		150.00	30.00
	SPRAY PAINT ON ACCIDENT DAMAGED AREAS INNER /OUTER.		950.00	800.00

Report Ref No. CC4/LPC20002394/Eea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CUT OUT/RENEW REAR END PANEL ,REPAIR REAR CHASSIS RH REAR FENDER ,REAR FLOOR PANEL ,INCLUDING KNOCKING & REPLACEMENT OF PARTS.		750.00	600.00
			2,100.00	1,600.00
GRAND TOTAL			5,396.44	4,268.68
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,400.00

Report Ref No. CC4/LPC20002394/Eea3n2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.