

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20002404/EDA3Q2

Date: 23/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700040822

Claimant
Vehicle No : SJY58J **Insured Vehicle No :** SCE3600L

Date of Loss: 21/11/2019 **Nature of Claim:** TP **Claim No:** 9630884225SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJY58J		
Make & Model:	BMW 740LI, 3.0 (A)	Engine No:	16315722B58B30C
Reg. Date:	30/09/2019 (Man. Year: 2019)	Chassis No:	WBA7T22010BM61045
Colour:	Grey	Odometer:	9354 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40 R20	Rear Tyre Size:	245/40 R20
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,717.10	9,717.10	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,247.00	2,691.00	556.00	17.12
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	12,964.10	12,408.10	556.00	4.29
+ GST 7.00/7.00% (S\$)	907.49	868.57	38.92	4.29
Nett Amount (S\$)	13,871.59	13,276.67	594.92	4.29
+ Loss of Use (3.0 x S\$120.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		13,638.67		

INSPECTION

Date of Assignment: 26/02/2020

Date Inspected: 26/02/2020 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*FRT BUMPER RH PROTECTIVE RUBBER STR	Necessary	96.30 FS	*96.30 FS
3	1		*FRT BUMPER RH PROTECTIVE RUBBER STR	Necessary	67.40 FS	*67.40 FS
4	1		*FRT BUMPER PANEL PRIMED (PDC/PMA)	Dented	1,612.90 FS	*1,612.90 FS
5	1		*RH LASER HEADLIGTH	Cut	7,790.50 FS	*7,790.50 FS
					Total Parts (\$\$)	9,717.10 9,717.10

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRONT BUMPER INCLUDING ATTACHMENT	New	1,275.00	850.00
2	PAINTING FRONT BUMPER	New	1,038.00	934.00
3	TO REPLACE RIGHT HEADLIGHT	New	531.00	531.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	177.00	150.00
5	TO DIAGNOSE RIGHT LASER HEADLIGHT CONTROL UNIT/MODULE INCLUDE PROGRAMMING AND CONDUCTING TESTS FOR PROPER FUNCTION	New	226.00	226.00
Gross Labour Cost (\$\$)			3,247.00	2,691.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >