

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20002406/AYF3E2

Date: 29/05/2020

REFERENCE

Insured/Claimant:	KOH ZHAN YU	Policy No:	1800124130	
Date of Loss:	24/01/2020	Nature of Claim:	OD	Claim No: 3641074348SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF367G		
Make & Model:	AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A)	Engine No:	CZE802018
Reg. Date:	25/10/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V3J1082087
Colour:	Red	Odometer:	23492 km
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$92,000.00		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,882.00	9,385.52	11,496.48	55.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,122.00	8,992.00	13,130.00	59.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	43,004.00	18,377.52	24,626.48	57.27
- Excess (\$\$)	600.00	600.00	0.00	0.00
(\$\$)	42,404.00	17,777.52	24,626.48	58.08
+ GST 7.00/7.00% (\$\$)	2,968.28	1,244.43	1,723.85	58.08
Nett Amount (\$\$)	45,372.28	19,021.95	26,350.33	58.08

INSPECTION

Date of Assignment:	11/02/2020	
Date Inspected:	11/02/2020	Inspected At:
		Premium Automobiles Pte Ltd (UBI)
		55 Ubi Road 1
		Singapore 408699
Estimated Period of Repair:	8.0 days	

Adjuster: ADRIAN LING

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,894.00 FS	*1,515.20 FS
2	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	36.00 FS	*- FS
3	1		*FRONT FENDER - RH	Dented	802.00 FS	*641.20 FS
4	1		*FRONT FENDER BRACKET - RH	Damaged	26.00 FS	*20.56 FS
5	1		*FRONT FENDER BRACKET - RH	Damaged	36.00 FS	*28.80 FS
6	1		*FRONT FENDER BRACE - RH	Bent	90.00 FS	*71.92 FS
7	1		*FRONT FENDER ATTACHMENT PARTS	Not Necessary	68.00 FS	*- FS
8	1		*FRONT WHEEL HOUSING LINER - RH	Deformed	159.00 FS	*127.20 FS
9	1		*WHEEL HOUSING LINER ATTACHMENT PARTS	Not Necessary	84.00 FS	*- FS
10	1		*FRONT FENDER INSULATION - RH	Not Necessary	40.00 FS	*- FS
11	1		*FRONT FENDER CLOSING ELEMENT - RH	Not Necessary	31.00 FS	*- FS
12	1		*LED HEADLIGHT - RH	Cut	5,193.00 FS	*4,154.40 FS
13	1		*FRONT DOOR - RH	Dented	2,375.00 FS	*1,900.00 FS
14	1		*OUTER DOOR SEAL - RH	Necessary	151.00 FS	*120.80 FS
15	1		*BONDING AGENT	Necessary	46.00 FS	*36.72 FS
16	1		*CLEANING SOLUTION	Necessary	64.00 FS	*51.20 FS
17	1		*FRONT DOOR ATTACHMENT PARTS	Not Necessary	227.00 FS	*- FS
18	1		*FRONT DOOR CATCH	Not Necessary	99.00 FS	*- FS
19	1		*WINDOW REGULATOR - RH	Not Necessary	249.00 FS	*- FS
20	1		*REAR DOOR - RH	Repair	2,375.00 FS	*- FS
21	1		*REAR DOOR OUTER SEAL	Not Necessary	151.00 FS	*- FS
22	1		*BONDING AGENT	Not Necessary	46.00 FS	*- FS
23	1		*CLEANING SOLUTION	Not Necessary	64.00 FS	*- FS
24	1		*REAR DOOR CATCH	Not Necessary	89.00 FS	*- FS
25	1		*SIDE PANEL - RH	Repair	2,195.00 FS	*- FS
26	1		*SIDE WINDOW - RH	Not Necessary	537.00 FS	*- FS
27	1		*REAR WINDSCREEN	Not Necessary	766.00 FS	*- FS
28	2		*PRIMER	Not Necessary	37.00 FS	*- FS
29	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	30.00 FS	*- FS
30	1		*FRONT ALUMINIUM RIM - RH	Cut	666.00 FS	*532.40 FS
31	1		*REAR WINDSCREEN SEALANT	Not Necessary	200.00 FS	*- FS
32	1		*1/4 GLASS SEALANT	Not Necessary	100.00 FS	*- FS
33	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
34	1		*CAVITY WAX	Not Necessary	140.00 FS	*- FS
35	1		*STONE CHIP	Not Necessary	180.00 FS	*- FS
36	1		*METAL FILLER POWDER	Not Necessary	280.00 FS	*- FS
37	1		*SUNDRIES	Necessary	1,000.00 FS	*5.12 FS
38	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **20,882.00** **9,385.52**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, FOG LAMPS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND REINSTALL REAR PARKING AID. CHECK FUNCTION	New	280.00	280.00
3	TO REMOVE AND TRANSFER BOTH RHS FRONT AND REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES	New	560.00	280.00
4	TO REMOVE AND REINSTALL REAR SEATS, BACK REST, ABCD PILLAR TRIMS, ROOF LINER, HAT TRAYS, CARPETS, CURTAIN AIRBAG AND SILL TRIMS	New	1,400.00	0.00
5	TO REMOVE AND RENEW RHS QUARTER GLASS AND REAR WINDSCREEN FOR FENDER RENEWAL	New	600.00	0.00
6	TO REMOVE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS, FUSE UNITS, BATTERY MANAGER, FUSE AND RELAY TRAYS, AND ELECTRICAL COMPONENTS	New	1,400.00	0.00
7	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS, SEAT BELTS, DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC	New	1,400.00	0.00
8	TO DISMANTLE FRONT BUMPER, RHS FRONT FENDER, RHS FRONT AND REAR DOORS AND REAR BUMPER CUT OUT AND WELD RHS REAR FENDER. RENEW DAMAGED PANELS INCLUDING RHS HEADLIGHT, ALIGN TO POSITION. REINSTALL ALL PARTS REMOVED	New	8,050.00	3,000.00
9	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS FRONT AND REAR DOORS, RHS REAR FENDER, SILL PANEL, DOOR ENTRANCES, ROOF CHANNEL, DRAIN PANEL, END PANELLING AND REAR BUMPER. TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	7,600.00	4,600.00
10	TO RENEW RHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT	New	280.00	280.00
11	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			22,122.00	8,992.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >