

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CC3/AIG20002407/ATF3E2**Date:** 28/05/2020REFERENCEInsured/Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD Policy No: 1900159163  
Date of Loss: 04/02/2020 Nature of Claim: OD Claim No: 7405321678SGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMQ210S**  
Make & Model: AUDI Q7, 2.0 TFSI QU (A) Engine No: CYR051022  
Reg. Date: 26/12/2017 (Man. Year: 2017) Chassis No: WAUZZZ4M0JD014468  
Colour: Bronze Odometer: 29953 km  
Engine Capacity: 1984 cc  
Market Value/New Car Price: S\$195,000.00  
Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEYGeneral Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: YesCONDITION OF TYRESFront Tyre Size: 255/55 R19 Rear Tyre Size: 255/55 R19  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	20,875.28	7,410.50	13,464.78	64.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,422.00	2,272.00	4,150.00	64.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>27,297.28</b>	<b>9,682.50</b>	<b>17,614.78</b>	<b>64.53</b>
<b>- Excess (S\$)</b>	1,000.00	1,000.00	0.00	0.00
<b>(S\$)</b>	26,297.28	8,682.50	17,614.78	66.98
<b>+ GST 7.00/7.00% (S\$)</b>	1,840.81	607.78	1,233.03	66.98
<b>Nett Amount (S\$)</b>	<b>28,138.09</b>	<b>9,290.28</b>	<b>18,847.81</b>	<b>66.98</b>

INSPECTIONDate of Assignment: 12/02/2020  
Date Inspected: 11/02/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	2,449.00 FS	*1,959.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	420.00 FS	*- FS
3	1		*FRONT BUMPER TOWING EYE COVER	Not Necessary	37.00 FS	*- FS
4	1		*FRONT BUMPER AIR GUIDE - RH	Not Necessary	63.00 FS	*- FS
5	1		*FRONT BUMPER END CAP - RH	Missing	34.00 FS	*26.48 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE	Cracked	261.00 FS	*208.40 FS
7	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Not Necessary	194.00 FS	*- FS
8	1		*FRONT BUMPER UNDERRUN BAR	Deformed	759.00 FS	*607.20 FS
9	1		*FRONT BUMPER CLOSING ELEMENT	Cracked	198.00 FS	*158.80 FS
10	1		*FRONT BUMPER FRONT SPOILER	Not Necessary	199.00 FS	*- FS
11	1		*FRONT BUMPER SPOILER - RH OUTER	Repair	41.00 FS	*- FS
12	1		*RADIATOR GRILLE	Cracked	2,327.00 FS	*1,861.60 FS
13	1		*RADIATOR GRILLE COVER	Cracked	65.00 FS	*51.44 FS
14	1		*RADIATOR GRILLE INNER COVER	Not Necessary	58.00 FS	*- FS
15	1		*RADIATOR GRILLE COVER CAP	Not Necessary	128.00 FS	*- FS
16	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	280.00 FS	*224.00 FS
17	1		*FRONT BUMPER END CAP - RH	Damaged	32.00 FS	*24.96 FS
18	1		*RADIATOR GRILLE SPOILER - RH INNER	Cracked	56.00 FS	*44.48 FS
19	1		*FRONT BUMPER CARRIER	Bent	817.00 FS	*653.20 FS
20	1		*FRONT BUMPER GUIDE SECTION - RH	Not Necessary	41.00 FS	*- FS
21	2		*FRONT BUMPER SUPPORT - LH / RH	Not Necessary	68.00 FS	*- FS
22	1		*FRONT BUMPER SIGHT SHIELD	Not Necessary	123.00 FS	*- FS
23	1		*FRONT BUMPER FOAM FILLER PIECE	Cracked	161.00 FS	*128.80 FS
24	1		*CAUTION SIGN STICKER	Not Necessary	13.00 FS	*- FS
25	1		*HORN - RH HIGH TONE	Not Necessary	213.00 FS	*- FS
26	1		*FRONT PARKING AID - INNER / OUTER (2PCS)	Damaged (1Pc Only)	167.08 FS	*83.54 FS
27	1		*FRONT PARKING AID - SIDE (NPA)	Not Necessary	0.00 FS	*- FS
28	4		*FRONT PARKING AID SEAL RING	Not Necessary	14.00 FS	*- FS
29	2		*FRONT WHEEL COVER - LH / RH	Necessary	1,080.00 FS	*863.20 FS
30	1		*HEADLIGHT MOUNTING - RH	Not Necessary	112.00 FS	*- FS
31	1		*LED HEADLIGHT	Not Necessary	9,356.00 FS	*- FS
32	1		*LIFT CYLINDER - RH	Not Necessary	187.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - RH	Not Necessary	27.00 FS	*- FS
34	2		*RADIATOR AIR GUIDE - UPPER / LOWER	Not Necessary	80.00 FS	*- FS
35	1		*FRONT NO PLATE	Dented	40.00 FS	*40.00 FS
36	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
37	1		*WIRING SET FOR FRONT BUMPER	Cut	475.20 FS	*475.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 20,875.28 7,410.50**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,250.00	600.00
3	TO RESPRAY FRONT BUMPER, FRONT BUMPER RHS SPOILER, RHS FRONT FENDER, BOTH FRONT WHEEL ARCH TRIMS	New	3,500.00	1,000.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (S\$)</b>	<b>2,272.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >