

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

**Our File No:** CC3/AIG20002414/EQF3E2

**Date:** 22/04/2020

### REFERENCE

Insured/Claimant:	TAN MENG KHAI IVAN	Policy No:	1800071832	
Date of Loss:	07/02/2020	Nature of Claim:	OD	Claim No: 8066868508SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMA202A			
Make & Model:	AUDI A3, 999cc TFSI (A)	Engine No:	CHZ439400	
Reg. Date:	20/06/2018 (Man. Year: 2018)	Chassis No:	WAUZZZ8V5J1056400	
Colour:	Blue	Odometer:	17373 km	
Engine Capacity:	999 cc			
Market Value/New Car Price:	S\$90,000.00			
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>			

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	19,716.96	12,181.76	7,535.20	38.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,352.00	3,952.00	6,400.00	61.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>30,068.96</b>	<b>16,133.76</b>	<b>13,935.20</b>	<b>46.34</b>
<b>- Excess (\$\$)</b>	<b>300.00</b>	<b>300.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(\$\$)</b>	<b>29,768.96</b>	<b>15,833.76</b>	<b>13,935.20</b>	<b>46.81</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>2,083.83</b>	<b>1,108.36</b>	<b>975.47</b>	<b>46.81</b>
<b>Nett Amount (\$\$)</b>	<b>31,852.79</b>	<b>16,942.12</b>	<b>14,910.67</b>	<b>46.81</b>

### INSPECTION

Date of Assignment:	12/02/2020	
Date Inspected:	11/02/2020	Inspected At: 24 Benoi Sector
		Repairer : Premium Automobiles Pte Ltd
Estimated Period of Repair:	7.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	1,894.00 FS	*1,515.20 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	176.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION - RH	Missing	36.00 FS	*28.64 FS
4	1		*FRONT BUMPER GRILLE - CENTRE	Broken	151.00 FS	*120.40 FS
5	1		*FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	Broken	505.00 FS	*404.00 FS
6	1		*FRONT BUMPER CLOSING ELEMENT - RH	Broken	280.00 FS	*223.60 FS
7	1		*FRONT BUMPER COVER TRIM - RH	Missing	153.00 FS	*122.40 FS
8	1		*WHEEL HOUSING LINER ADAPTER - RH	Missing	36.00 FS	*28.16 FS
9	1		*RADIATOR GRILLE	Broken	1,338.00 FS	*1,070.40 FS
10	1		*RADIATOR GRILLE CLOSING ELEMENT	Broken	180.00 FS	*143.60 FS
11	1		*FRONT BUMPER AIR GUIDE GRILLE - RH	Missing	177.00 FS	*141.20 FS
12	1		*FRONT BUMPER SIDE REINFORCEMENT BEAM	Dented	681.00 FS	*544.80 FS
13	1		*FRONT BUMPER FOAM FILLER PIECE	Broken	178.00 FS	*142.40 FS
14	1		*FOAM FILLER PIECE COVER	Broken	115.00 FS	*91.60 FS
15	1		*SIGNAL HORN RETAINER - RH LOW TONE	Not Necessary	188.00 FS	*- FS
16	1		*BONNET	Dented	2,988.00 FS	*2,390.40 FS
17	1		*BONNET ATTACHMENT PARTS	Not Necessary	155.00 FS	*- FS
18	1		*BONNET GAS FILLED STRUT	Not Necessary	112.00 FS	*- FS
19	1		*BONNET SAFETY CATCH	Not Necessary	84.00 FS	*- FS
20	1		*BONNET STRIKER - RH	Not Necessary	104.00 FS	*- FS
21	1		*BONNET EDGE PROTECTION	Necessary	26.00 FS	*20.80 FS
22	1		*BONNET CATCH HOOK	Not Necessary	60.00 FS	*- FS
23	1		*BONNET LID LOCK	Not Necessary	202.00 FS	*- FS
24	1		*BONNET BOWDEN CABLE - CENTRE	Not Necessary	54.00 FS	*- FS
25	1		*LED HEADLIGHT - RH	Cut	5,193.00 FS	*4,154.40 FS
26	1		*LIFT CYLINDER - RH	Not Necessary	134.00 FS	*- FS
27	1		*HEADLIGHT HOSE	Not Necessary	64.00 FS	*- FS
28	1		*LOCK CARRIER	Not Necessary	685.00 FS	*- FS
29	1		*AIRCON CONDENSER	Not Necessary	519.00 FS	*- FS
30	1		*RADIATOR	Not Necessary	932.00 FS	*- FS
31	1		*ADDITIONAL RADIATOR	Not Necessary	851.00 FS	*- FS
32	1		*READY MIX COOLANT	Not Necessary	86.00 FS	*- FS
33	1		*RADIATOR AIR GUIDE - LH / RH	O/S Broken	46.00 FS	*18.16 FS
34	1		*RADIATOR AIR GUIDE - UPPER CENTRE	Not Necessary	12.00 FS	*- FS
35	1		*CAUTION SIGN STICKER	Necessary	13.00 FS	*10.24 FS
36	1		*FRONT NO PLATE	Bent	40.00 FS	*40.00 FS
37	1		*SUNDRIES	Necessary	300.00 FS	*2.40 FS
38	1		*WHEEL HOUSING LINER RHS FRONT	Broken	127.20 FS	*127.20 FS
39	1		*NOISE INSULATION	Broken	195.20 FS	*195.20 FS
40	1		*STICKER FOR AIR CONDITIONER	Necessary	5.36 FS	*5.36 FS
41	1		*RHS FRONT FENDER	Dented	641.20 FS	*641.20 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 19,716.96 12,181.76**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO REMOVE AND RENEW AIRCOND CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS	New	1,200.00	0.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	4,550.00	1,250.00
4	TO RESPRAY FRONT BUMPER AND BONNET	New	2,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO RENEW RHS FRONT FENDER	New	1,050.00	500.00
7	TO RESPRAY RHS FRONT FENDER	New	1,000.00	550.00
<b>Gross Labour Cost (S\$)</b>			<b>10,352.00</b>	<b>3,952.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >