

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002417/KDS3Q2
Date: 09/07/2020

REFERENCE

| | | |
|--|-----------------------------|------------------------|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: | 2100484568 |
| Claimant | | |
| Vehicle No : SJF657E | Insured Vehicle No : | SLG4403R |
| Date of Loss: 07/02/2020 | Nature of Claim: TP | Claim No: 2293490632SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SJF657E | | |
| Make & Model: | FORD FOCUS, 1.6 GHIA 5DR (A) | Engine No: | FK32680 |
| Reg. Date: | 28/08/2015 (Man. Year: 2015) | Chassis No: | WF05XXGCC5FK32680 |
| Colour: | Metallic Silver | Odometer: | 58647 km |
| Engine Capacity: | 1596 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/55 R16 | Rear Tyre Size: | 205/55 R16 |
| Front Left Side: | Yokohama 8 mm | Rear Left Side: | Yokohama 8 mm |
| Front Right Side: | Yokohama 8 mm | Rear Right Side: | Yokohama 8 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|------------------|-----------------|-----------------|--------------|
| Parts | 8,335.52 | 4,954.64 | 3,380.88 | 40.56 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,160.00 | 1,510.00 | 650.00 | 30.09 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 10,495.52 | 6,464.64 | 4,030.88 | 38.41 |
| Approved Total (Overridden) (S\$) | | 4,650.00 | | |
| (S\$) | 10,495.52 | 4,650.00 | 5,845.52 | 55.70 |
| + GST 7.00/7.00% (S\$) | 734.69 | 325.50 | 409.19 | 55.70 |
| Nett Amount (S\$) | 11,230.21 | 4,975.50 | 6,254.71 | 55.70 |
| + Car Rental (7.0 x S\$100.00/day + 7.00% GST) (S\$) | | 749.00 | | |
| + Doc/Search Fee (S\$) | | 17.00 | | |
| + Other Costs (S\$) | | 60.00 | | |
| Nett Liability (S\$) | | 5,801.50 | | |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 11/02/2020 | |
| Date Inspected: | 11/02/2020 | Inspected At: 9A SERANGOON NORTH AVE 5 Repairer: Optima Werkz Pte Ltd (HQ) |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1 | 1 | | *REAR TAILGATE | Bent | 2,347.60 FL | *1,422.00 FL |
| 2 | 1 | | *REAR TAILGATE FOCUS EMBLEM | Necessary | 112.00 FL | *86.00 FL |
| 3 | 1 | | *REAR WINDSCREEN RUBBER | Serviceable | 112.00 FL | *- FL |
| 4 | 8 | | *REAR TAILGATE INNER TRIM CLIPS | Not Necessary | 52.00 FL | *- FL |
| 5 | 1 | | *REAR BUMPER | Cracked | 1,972.60 FL | *1,320.00 FL |
| 6 | 10 | | *REAR BUMPER CLIPS | Necessary | 58.00 FL | *58.00 FL |
| 7 | 1 | | *REAR BUMPER LOWER LID COVER | Bent | 762.00 FL | *685.00 FL |
| 8 | 1 | | *REAR BUMPER SIDE BRACKET LH | Distorted | 149.00 FL | *149.00 FL |
| 9 | 1 | | *REAR BUMPER SIDE BRACKET RH | Repair | 149.00 FL | *- FL |
| 10 | 1 | | *REAR BUMPER UPPER BRACKET LH | Repair | 126.00 FL | *- FL |
| 11 | 1 | | *REAR BUMPER UPPER BRACKET RH | Repair | 126.00 FL | *- FL |
| 12 | 1 | | *REAR BUMPER REFLECTOR LH | Cracked | 192.80 FL | *192.80 FL |
| 13 | 1 | | *REAR BUMPER FIXING COVER | Missing | 60.00 FL | *60.00 FL |
| 14 | 1 | | *REAR BUMPER INNER CENTER RETAINER GUIDE | Serviceable | 246.00 FL | *- FL |
| 15 | 1 | | *REAR TAIL LAMP LH | Cracked | 1,216.00 FL | *850.00 FL |
| 16 | 1 | | *REAR QUARTER PANEL LINER LH | Torn | 610.50 FL | *610.50 FL |
| 17 | 1 | | *REAR QUARTER PANEL LINER RH | Serviceable | 610.50 FL | *- FL |
| 18 | 1 | | *REAR END PANEL (NPA) | Repair | 0.00 FL | *- FL |
| 19 | 1 | | *REAR BUMPER REINFORCEMENT (NPA) | Repair | 0.00 FL | *- FL |
| 20 | 1 | | *REAR QUARTER PANEL LH (NPA) | Repair | 0.00 FL | *- FL |
| 21 | 1 | | *REAR WINDSCREEN SEALANT | Necessary | 60.00 FS | *40.00 FS |
| 22 | 2 | | *REAR WINDSCREEN STOPPER | Serviceable | 30.00 FS | *- FS |
| 23 | 1 | | *REAR BUMPER REVERSE SENSOR | Dented | 350.00 FS | *200.00 FS |
| 24 | 1 | | *REAR BUMPER REINFORCEMENT | Bent | 967.40 FL | *460.00 FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|------------------|-----------------|
| Sub Total (\$\$) | 10,309.40 | 6,133.30 |
| - List Item Discount on L Items 20.00/20.00% (\$\$) | 1,973.88 | 1,178.66 |
| Total Parts (\$\$) | 8,335.52 | 4,954.64 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | LABOUR CHARGES TO REMOVE,REPLACE ,REPAIR ,READJUST ,REAR ACCIDENT AREA & ETC | New | 600.00 | 500.00 |
| 2 | LABOUR CHARGES TO REMOVE,REPLACE ,REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT & ETC ,TO EFFECT REPLACE OF REAR TAILGATE | New | 150.00 | 120.00 |
| 3 | LABOUR CHARGES TO REMOVE,REPLACE ,REFIX REAR BUMPER SENSOR & ETC | New | 80.00 | 60.00 |
| 4 | LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC BACK TO ORIGINAL OPERATION | New | 120.00 | 60.00 |
| 5 | LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER ,REAR TAILGATE ,REAR END PANEL ,REAR QUARTER PANEL LH & ETC | New | 800.00 | 720.00 |
| 6 | TO CHECK WIRING & ELECTRICAL WIRING SYSTEM | New | 60.00 | 20.00 |
| 7 | TO TUFF KOTE & UNDERSEAL MATERIALS | New | 200.00 | 30.00 |
| 8 | TO DIAGNOSE FAULTY CODE & RESET MEMORY | New | 150.00 | 0.00 |
| Gross Labour Cost (\$) | | | 2,160.00 | 1,510.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >