

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Feb 2020		12 Feb 2020 11:49 Edit Adj Rpt	S\$5,650.00 Edit Estimates	S\$5,650.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	-, Co. Reg. No.: -		
Main Claimant:	PAN PACIFIC VAN & TRUCK LEASING PTE LTD, Co. Reg. No.: 201511635R		
Vehicle Reg. No.:	GBJ5890M	Date of Loss:	05/02/2020 08:00 - :59 [7 Months and 25 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D200661/SKK6075G/CECILIA	Policy/Cover Note No.:	DMPCSN3005981904 (Comprehensive)
Vehicle Reg. No. (Insured):	SKK6075G	Policy No. (Claimant):	D19MFL0005549
		Excess:	S\$0.00
Repairer:	Efficient Motor & Engineering Works Pte Ltd (HQ) 56 Loyang Way #06-07, Loyang Enterprise Building, 508775 Loyang - Tel: 63416758 / 62840827		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]		
Claimant's Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 21/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBJ5890M (SNM20D200661/SKK6075G/CECILIA)**
[SKK6075G]

TP

PAN PACIFIC VAN & TRUCK LEASING PTE LTD

Feb 5 2020 8:00AM

[-]

Efficient Motor & Engineering Works Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/03/20 15:44	Odometer Reading	 Load JPG	☒
2	13/03/20 15:44	General View	 Load JPG	☒
3	13/03/20 15:44	General View	 Load JPG	☒
4	13/03/20 15:44	General View	 Load JPG	☒
5	13/03/20 15:44	General View	 Load JPG	☒
6	13/03/20 15:44	General View	 Load JPG	☒
7	13/03/20 15:44	General View	 Load JPG	☒
8	13/03/20 15:44	General View	 Load JPG	☒
9	13/03/20 15:44	General View	 Load JPG	☒
10	13/03/20 15:44	General View	 Load JPG	☒
11	13/03/20 15:44	General View	 Load JPG	☒
12	13/03/20 15:44	General View	 Load JPG	☒
13	13/03/20 15:44	General View	 Load JPG	☒
14	13/03/20 15:44	General View	 Load JPG	☒
15	13/03/20 15:44	General View	 Load JPG	☒
16	13/03/20 15:44	General View	 Load JPG	☒
17	13/03/20 15:44	General View	 Load JPG	☒
18	13/03/20 15:44	General View	 Load JPG	☒
19	13/03/20 15:44	General View	 Load JPG	☒
20	13/03/20 15:44	General View	 Load JPG	☒
21	13/03/20 15:44	General View	 Load JPG	☒
22	13/03/20 15:44	General View	 Load JPG	☒
23	13/03/20 15:44	General View	 Load JPG	☒
24	13/03/20 15:44	General View	 Load JPG	☒
25	13/03/20 15:44	General View	 Load JPG	☒
26	13/03/20 15:44	General View	 Load JPG	☒
27	13/03/20 15:44	General View	 Load JPG	☒
28	13/03/20 15:44	General View	 Load JPG	☒
29	13/03/20 15:44	General View	 Load JPG	☒
30	13/03/20 15:44	General View	 Load JPG	☒
31	13/03/20 15:44	General View	 Load JPG	☒
32	13/03/20 15:44	General View	 Load JPG	☒
33	13/03/20 15:44	General View	 Load JPG	☒
34	13/03/20 15:44	General View	 Load JPG	☒
35	13/03/20 15:44	General View	 Load JPG	☒
36	13/03/20 15:44	General View	 Load JPG	☒
37	13/03/20 15:44	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	13/03/20 15:44	General View	 Load JPG	☒
39	13/03/20 15:44	General View	 Load JPG	☒
40	13/03/20 15:44	General View	 Load JPG	☒
41	13/03/20 15:44	General View	 Load JPG	☒
42	13/03/20 15:44	General View	 Load JPG	☒
43	13/03/20 15:44	General View	 Load JPG	☒
44	13/03/20 15:44	General View	 Load JPG	☒
45	13/03/20 15:44	General View	 Load JPG	☒
46	13/03/20 15:44	General View	 Load JPG	☒
47	13/03/20 15:44	General View	 Load JPG	☒
48	13/03/20 15:44	General View	 Load JPG	☒
49	13/03/20 15:44	General View	 Load JPG	☒
50	13/03/20 15:44	General View	 Load JPG	☒
51	13/03/20 15:44	General View	 Load JPG	☒
52	13/03/20 15:44	General View	 Load JPG	☒
53	13/03/20 15:44	General View	 Load JPG	☒
54	13/03/20 15:44	General View	 Load JPG	☒
55	13/03/20 15:44	General View	 Load JPG	☒
56	13/03/20 15:44	General View	 Load JPG	☒
57	13/03/20 15:44	General View	 Load JPG	☒
58	13/03/20 15:44	General View	 Load JPG	☒
59	13/03/20 15:44	General View	 Load JPG	☒
60	13/03/20 15:44	General View	 Load JPG	☒
61	13/03/20 15:44	General View	 Load JPG	☒
62	13/03/20 15:44	General View	 Load JPG	☒
63	13/03/20 15:44	General View	 Load JPG	☒
64	13/03/20 15:44	General View	 Load JPG	☒
65	13/03/20 15:44	General View	 Load JPG	☒
66	13/03/20 15:44	General View	 Load JPG	☒
67	13/03/20 15:44	General View	 Load JPG	☒
68	13/03/20 15:44	General View	 Load JPG	☒
69	13/03/20 15:44	General View	 Load JPG	☒
70	13/03/20 15:44	General View	 Load JPG	☒
71	13/03/20 15:44	General View	 Load JPG	☒
72	13/03/20 15:44	General View	 Load JPG	☒
73	13/03/20 15:44	General View	 Load JPG	☒
74	13/03/20 15:44	General View	 Load JPG	☒
75	13/03/20 15:44	General View	 Load JPG	☒
76	13/03/20 15:44	General View	 Load JPG	☒
77	13/03/20 15:44	General View	 Load JPG	☒
78	13/03/20 15:45	Reinspection Photo	 Load JPG	☒
79	13/03/20 15:45	Reinspection Photo	 Load JPG	☒
80	13/03/20 15:45	Reinspection Photo	 Load JPG	☒
81	13/03/20 15:45	Reinspection Photo	 Load JPG	☒
82	13/03/20 15:45	Reinspection Photo	 Load JPG	☒
83	13/03/20 15:45	After Repair Photo	 Load JPG	☒
84	13/03/20 15:45	After Repair Photo	 Load JPG	☒
85	13/03/20 15:45	After Repair Photo	 Load JPG	☒
86	13/03/20 15:45	After Repair Photo	 Load JPG	☒
87	13/03/20 15:45	After Repair Photo	 Load JPG	☒

Linked Accident Report Documents

			View	View in Browser
Assessment Reports			1 per page	☒
No	Finalized On	JP Knights Pte Ltd (HQ)	Thumbnail	Print
1	06/02/20 18:26	Accident Statement	 Load HTM	☐
Photos/Images			3 per page	☒
No	Finalized On	JP Knights Pte Ltd (HQ)	Thumbnail	Print
1	06/02/20 18:17	Police Report	 Load JPG	☒
2	06/02/20 18:17	Police Report	 Load JPG	☒
3	06/02/20 18:17	Police Report	 Load JPG	☒
4	06/02/20 18:17	Police Report	 Load JPG	☒
5	06/02/20 18:17	Police Report	 Load JPG	☒
6	06/02/20 18:17	Accident Photo	 Load JPG	☒
7	06/02/20 18:17	Accident Photo	 Load JPG	☒
8	06/02/20 18:17	Accident Photo	 Load JPG	☒
9	06/02/20 18:17	Accident Photo	 Load JPG	☒
10	06/02/20 18:17	Accident Photo	 Load JPG	☒
11	06/02/20 18:17	Accident Photo	 Load JPG	☒
12	06/02/20 18:17	Accident Photo	 Load JPG	☒
13	06/02/20 18:17	Accident Photo	 Load JPG	☒
14	06/02/20 18:17	Accident Photo	 Load JPG	☒
15	06/02/20 18:17	Accident Photo	 Load JPG	☒
16	06/02/20 18:17	Accident Photo	 Load JPG	☒
17	06/02/20 18:17	Accident Photo	 Load JPG	☒
18	06/02/20 18:17	Accident Photo	 Load JPG	☒
19	06/02/20 18:17	Accident Photo	 Load JPG	☒
20	06/02/20 18:17	Accident Photo	 Load JPG	☒
21	06/02/20 18:17	Accident Photo	 Load JPG	☒
22	06/02/20 18:17	Accident Photo	 Load JPG	☒
23	06/02/20 18:17	Accident Photo	 Load JPG	☒
24	06/02/20 18:17	Accident Photo	 Load JPG	☒
25	06/02/20 18:17	Accident Photo	 Load JPG	☒
26	06/02/20 18:17	Accident Photo	 Load JPG	☒
27	06/02/20 18:18	Accident Photo	 Load JPG	☒
28	06/02/20 18:18	Accident Photo	 Load JPG	☒
29	06/02/20 18:18	Accident Photo	 Load JPG	☒
30	06/02/20 18:18	Accident Photo	 Load JPG	☒
31	06/02/20 18:18	Accident Photo	 Load JPG	☒
32	06/02/20 18:18	Accident Photo	 Load JPG	☒
33	06/02/20 18:18	Accident Photo	 Load JPG	☒
34	06/02/20 18:18	Accident Photo	 Load JPG	☒
35	06/02/20 18:18	Accident Photo	 Load JPG	☒
36	06/02/20 18:18	Accident Photo	 Load JPG	☒
37	06/02/20 18:18	Accident Photo	 Load JPG	☒
38	06/02/20 18:18	Accident Photo	 Load JPG	☒
39	06/02/20 18:18	Accident Photo	 Load JPG	☒
40	06/02/20 18:18	Accident Photo	 Load JPG	☒
41	06/02/20 18:18	Accident Photo	 Load JPG	☒
42	06/02/20 18:18	Accident Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	JP Knights Pte Ltd (HQ)	Thumbnail	Print
43	06/02/20 18:18	Accident Photo	 Load JPG	☒
44	06/02/20 18:18	Accident Photo	 Load JPG	☒
45	06/02/20 18:18	Accident Photo	 Load JPG	☒
46	06/02/20 18:18	Accident Photo	 Load JPG	☒
47	06/02/20 18:18	Accident Photo	 Load JPG	☒
48	06/02/20 18:18	Accident Photo	 Load JPG	☒
49	06/02/20 18:18	Identification Card	 Load JPG	☒
50	06/02/20 18:18	Identification Card	 Load JPG	☒
51	06/02/20 18:18	Driving License	 Load JPG	☒
52	06/02/20 18:18	Driving License	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	JP Knights Pte Ltd (HQ)	Thumbnail	Print
1	06/02/20 17:57	Sketch Plan	 Load JPG	☒
2	06/02/20 17:57	Sketch Plan #2	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002423/T1TF3E2

Date: 31/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSN3005981904

Claimant Vehicle No: GBJ5890M Insured Vehicle No: SKK6075G

Date of Loss: 05/02/2020 Nature of Claim: TP Claim No: SNM20D200661/SKK6075G/CECILIA

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ5890M Engine No: 1GD8361384

Make & Model: TOYOTA HIACE, 2.8 D (A) Chassis No: GDH2012004147

Reg. Date: 11/06/2019 (Man. Year: 2018) Odometer: 16754 km

Colour: Silver

Engine Capacity: 2754 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/80 R15 Rear Tyre Size: 195/80 R15

Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,188.50	4,821.00	9,367.50	66.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,580.00	2,270.00	1,310.00	36.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,768.50	7,091.00	10,677.50	60.09
Approved Total (Overridden) (S\$)		5,650.00		
(S\$)	17,768.50	5,650.00	12,118.50	68.20
+ GST 7.00/7.00% (S\$)	1,243.80	395.50	848.30	68.20
Nett Amount (S\$)	19,012.30	6,045.50	12,966.80	68.20

INSPECTION

Date of Assignment: 12/02/2020

Date Inspected: 12/02/2020 Inspected At:

Efficient Motor & Engineering Works Pte Ltd (HQ)
56 Loyang Way #06-07, Loyang Enterprise Building
Singapore 508775

Estimated Period of Repair: 9.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 31 Mar 2020)	
Parts:	N/A	TOYOTA HIACE 2.8 D (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ5890M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Deformed	496.00 FL	*496.00 FL
2	1	*FRONT BUMPER REINFORCEMENT	Not Necessary	320.00 FL	*- FL
3	1	*FRONT HEADLAMP LH	Not Necessary	2,600.00 FL	*- FL
4	1	*FRONT HEADLAMP RH	Not Necessary	2,600.00 FL	*- FL
5	1	*FRONT GRILLE	Cut	530.00 FL	*530.00 FL
6	1	*FRONT BUMPER SIDE RETAINER LH	Deformed	193.00 FL	*193.00 FL
7	1	*FRONT BUMPER SIDE RETAINER RH	Not Necessary	193.00 FL	*- FL
8	1	*FRONT BUMPER LOWER GRILLE	Cracked	160.00 FL	*160.00 FL
9	1	*REAR TAILGATE	Bent	2,100.00 FL	*2,100.00 FL
10	1	*REAR TAILGATE LOCK	Not Necessary	240.00 FL	*- FL
11	1	*REAR TAILGATE LOCK CATCH	Not Necessary	85.00 FL	*- FL
12	1	*REAR TAILGATE HING LH	Repair	59.00 FL	*- FL
13	1	*REAR TAILGATE HING RH	Repair	59.00 FL	*- FL
14	1	*REAR TAILGATE SHOCK ABSORBER LH	Not Necessary	280.00 FL	*- FL
15	1	*REAR TAILGATE SHOCK ABSORBER RH	Not Necessary	280.00 FL	*- FL
16	1	*REAR TAILGATE EMBLEM LOGO	Necessary	68.00 FL	*68.00 FL
17	1	*REAR TAILGATE STICKER	Necessary	42.00 FL	*42.00 FL
18	1	*REAR TAILLAMP LH	Not Necessary	260.00 FL	*- FL
19	1	*REAR TAILLAMP RH	Not Necessary	260.00 FL	*- FL
20	1	*REAR TAILGATE INNER TRIM BOARD	Not Necessary	180.00 FL	*- FL
21	10	*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	80.00 FL	*- FL
22	1	*REAR TAILLAMP INNER PANEL LH	Repair	496.00 FL	*- FL
23	1	*REAR TAILLAMP INNER PANEL RH	Repair	496.00 FL	*- FL
24	1	*REAR TAILLAMP LOWER APRON PANEL LH	Bent	85.00 FL	*85.00 FL
25	1	*REAR TAILLAMP LOWER APRON PANEL RH	Not Necessary	85.00 FL	*- FL
26	1	*REAR TAILLAMP LOWER APRON PANEL BRACKET LH	Bent	38.00 FL	*38.00 FL
27	1	*REAR TAILLAMP LOWER APRON PANEL BRACKET RH	Not Necessary	38.00 FL	*- FL
28	1	*REAR BUMPER	Deformed	350.00 FL	*350.00 FL
29	1	*REAR BUMPER SIDE RETAINER LH	Necessary	38.00 FL	*38.00 FL
30	1	*REAR BUMPER SIDE RETAINER RH	Necessary	38.00 FL	*38.00 FL
31	10	*REAR BUMPER CLIPS	Necessary	80.00 FL	*30.00 FL
32	1	*REAR END PANEL OUTER	Bent	350.00 FL	*350.00 FL
33	1	*REAR END PANEL INNER	Not Necessary	1,043.00 FL	*- FL
34	1	*REAR END PANEL TOP METAL PLATE	Not Necessary	89.00 FL	*- FL
35	1	*REAR FLOOR PANEL	Repair	1,900.00 FL	*- FL
36	4	*REAR BUMPER BRACKET	Not Necessary	152.00 FL	*- FL
37	1	*REAR SPARE TYRE BRACKET	Not Necessary	350.00 FL	*- FL
38	1	*REAR SPARE TYRE LOCK	Not Necessary	35.00 FL	*- FL
39	1	*REAR BUMPER STEP PANEL	Bent	260.00 FL	*260.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
40	1		*BONNET	Bent	850.00 FL	*850.00 FL
41	1		*REAR PLY WOOD	Cracked	350.00 FS	*250.00 FS
42	1		*REAR REVERSE SENSOR	Not Working	250.00 FS	*200.00 FS
43	1		*SEALANT	Necessary	60.00 FS	*60.00 FS
44	1		*FRONT NUMBER PLATE	Cracked	45.00 FS	*45.00 FS
45	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
46	1		*REAR TAILGATE TEMPLATE	Necessary	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

	Sub Total (S\$)	18,653.00	6,228.00
- List Item Discount on L Items 25.00/25.00% (S\$)		4,464.50	1,407.00
	Total Parts (S\$)	14,188.50	4,821.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING	New	1,800.00	1,200.00
2	LABOUR FOR SPRAYPAINTING	New	1,000.00	800.00
3	WIRING	New	80.00	50.00
4	LABOUR FOR REMOVE & REFIX REAR WINDSCREEN GLASS	New	150.00	120.00
5	LABOUR FOR REMOVE & TRANSFER ALL REAR TAILGATE FITTING	New	250.00	60.00
6	TO APPLY ANTI RUST PROOF ON REAR ACCIDENT AREAS	New	300.00	40.00
Gross Labour Cost (\$\$)			3,580.00	2,270.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >