

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20002435/ABS3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900008959

**Claimant Vehicle No :** SLU8531D **Insured Vehicle No :** SJC3303Y

Date of Loss: 11/02/2020 Nature of Claim: TP Claim No: 2494982818SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |              |
|-----------------------------|-----------------------------------|-------------|--------------|
| Reg No:                     | <b>SLU8531D</b>                   |             |              |
| Make & Model:               | TOYOTA HARRIER, 2.0 (A)           | Engine No:  | 3ZRB968050   |
| Reg. Date:                  | 15/12/2017 (Man. Year: 2017)      | Chassis No: | ZSU600099257 |
| Colour:                     | Blue                              | Odometer:   | 63430 km     |
| Engine Capacity:            | 1986 cc                           |             |              |
| Market Value/New Car Price: | N/A                               |             |              |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |              |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 235/55 R18       | Rear Tyre Size:  | 235/55 R18       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 11,070.10         | 7,591.05          | 3,479.05          | 31.43         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 3,150.00          | 2,280.00          | 870.00            | 27.62         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>14,220.10</b>  | <b>9,871.05</b>   | <b>4,349.05</b>   | <b>30.58</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>7,900.00</b>   |                   |               |
| <b>(S\$)</b>                                    | 14,220.10         | 7,900.00          | 6,320.10          | 44.44         |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | 995.41            | 553.00            | 442.41            | 44.45         |
| <b>Nett Amount (S\$)</b>                        | <b>15,215.51</b>  | <b>8,453.00</b>   | <b>6,762.51</b>   | <b>44.44</b>  |
| <b>+ Car Rental (7.0 x S\$120.00/day) (S\$)</b> |                   | 840.00            |                   |               |
| <b>+ Doc/Search Fee (S\$)</b>                   |                   | 2.00              |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>9,295.00</b>   |                   |               |
| <b>Global Sum Settlement (S\$)</b>              |                   | <b>9,200.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 14/02/2020

Date Inspected: 14/02/2020 Inspected At:

Kang Car Repairers Pte Ltd (HQ)  
No 1 Kaki Bukit Ave 6, #02-06  
AutoBay@Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 7.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                          | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *BOOT LID                            | Dented        | 1,469.50 FL | *1,469.50 FL |
| 2   | 1   |          | *BOOT LID HARRIER EMBLEM             | Necessary     | 72.10 FL    | *72.10 FL    |
| 3   | 1   |          | *BOOT LID LAMP RH                    | Cracked       | 412.20 FL   | *412.20 FL   |
| 4   | 1   |          | *BOOT LID LAMP LH                    | Cracked       | 412.20 FL   | *412.20 FL   |
| 5   | 1   |          | *BOOT LID LOCK                       | Damaged       | 763.70 FL   | *418.00 FL   |
| 6   | 1   |          | *BOOT LID LOCK CHECKER               | Not Necessary | 54.40 FL    | *- FL        |
| 7   | 1   |          | *BOOT LID RUBBER                     | Cut           | 410.40 FL   | *410.40 FL   |
| 8   | 1   |          | *BOOT LID TRIM                       | Cracked       | 479.50 FL   | *479.50 FL   |
| 9   | 1   |          | *BOOT LID AUTO LOCKING SENSOR        | Damaged       | 468.70 FL   | *230.50 FL   |
| 10  | 1   |          | *REAR WINDSCREEN RUBBER              | Necessary     | 82.20 FL    | *82.20 FL    |
| 11  | 2   |          | *BOOTLID SIDE AUTO CLOSE SENSOR      | Not Necessary | 2,074.40 FL | *- FL        |
| 12  | 1   |          | *REAR PANEL                          | Dented        | 715.30 FL   | *715.30 FL   |
| 13  | 1   |          | *REAR PANEL TRIM                     | Deformed      | 562.90 FL   | *361.00 FL   |
| 14  | 2   |          | *REAR PANEL TRIM CHROM               | Not Necessary | 205.40 FL   | *- FL        |
| 15  | 1   |          | *BOOT COMPARTMENT COVER              | Deformed      | 669.70 FL   | *669.70 FL   |
| 16  | 1   |          | *BOOT CENTRE TRAY                    | Deformed      | 647.90 FL   | *647.90 FL   |
| 17  | 1   |          | *REAR FENDER INNER TRIM RH           | Deformed      | 799.50 FL   | *799.50 FL   |
| 18  | 1   |          | *TAIL LAMP LH                        | Not Necessary | 517.30 FL   | *- FL        |
| 19  | 1   |          | *TAIL LAMP RH                        | Not Necessary | 517.30 FL   | *- FL        |
| 20  | 1   |          | *REAR BUMPER                         | Deformed      | 1,395.30 FL | *1,395.30 FL |
| 21  | 1   |          | *REAR BUMPER SPONGE                  | Cracked       | 137.80 FL   | *137.80 FL   |
| 22  | 2   |          | *REAR BUMPER BRACKET                 | Not Necessary | 158.80 FL   | *- FL        |
| 23  | 2   |          | *REAR BUMPER SIDE RETAINER           | Necessary     | 189.60 FL   | *189.60 FL   |
| 24  | 1   |          | *REAR LOWER BUMPER                   | Deformed      | 486.30 FL   | *486.30 FL   |
| 25  | 1   |          | *REAR BUMPER REFLECTOR LH            | Cut           | 54.10 FL    | *54.10 FL    |
| 26  | 1   |          | *REAR BUMPER REFLECTOR RH            | Cut           | 54.10 FL    | *54.10 FL    |
| 27  | 1   |          | *REAR ANTENNA SENSOR                 | Chipped       | 144.20 FL   | *144.20 FL   |
| 28  | 1   |          | *SET BOOTLID TRIM CLIPS              | Necessary     | 50.00 FS    | *30.00 FS    |
| 29  | 1   |          | *REAR WINDSCREEN SEAL                | Necessary     | 60.00 FS    | *40.00 FS    |
| 30  | 1   |          | *REAR WINDSCREEN SEALANT             | Necessary     | 60.00 FS    | *40.00 FS    |
| 31  | 1   |          | *SET REAR PANEL TRIM CLIPS           | Necessary     | 48.00 FS    | *20.00 FS    |
| 32  | 1   |          | *SET REAR FENDER INNER TRIM CLIPS RH | Not Necessary | 48.00 FS    | *- FS        |
| 33  | 1   |          | *SET REAR LOWER BUMPER CLIPS         | Not Necessary | 40.00 FS    | *- FS        |
| 34  | 1   |          | *SET REVERSE SENSORS                 | Damaged       | 250.00 FS   | *200.00 FS   |
| 35  | 1   |          | *SET REAR BUMPER CLIPS               | Necessary     | 48.00 FS    | *30.00 FS    |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                  |
|------------------------------------------------------------|------------------|------------------|
| <b>Sub Total (\$\$)</b>                                    | <b>14,558.80</b> | <b>10,001.40</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b> | <b>3,488.70</b>  | <b>2,410.35</b>  |
| <b>Total Parts (\$\$)</b>                                  | <b>11,070.10</b> | <b>7,591.05</b>  |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                               | Lab.Type | Repairer's      | Amount          |
|---------------------------------|-----------------------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                                           |          |                 |                 |
| 1                               | TO CHECK WIRING                                                                                           | New      | 50.00           | 30.00           |
| 2                               | TO REMOVE AND REFIT REVERSE CAMERA                                                                        | New      | 100.00          | 60.00           |
| 3                               | TO REMOVE AND REFIT REAR WINDSCREEN                                                                       | New      | 120.00          | 120.00          |
| 4                               | TO REMOVE AND REFIT INNER TRIM                                                                            | New      | 200.00          | 80.00           |
| 5                               | TO REMOVE AND REFIT REVERSE SENSOR                                                                        | New      | 100.00          | 60.00           |
| 6                               | TO SPRAY UNDERSEAL                                                                                        | New      | 180.00          | 80.00           |
| 7                               | (REAR) TO SPRAY PAINTING                                                                                  | New      | 1,200.00        | 950.00          |
| 8                               | TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS | New      | 1,200.00        | 900.00          |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                                           |          | <b>3,150.00</b> | <b>2,280.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >