

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20002442/UVF3E2

Date: 12/05/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 0100563086
Claimant Vehicle No : FBQ8988J	Insured Vehicle No : SGE4085U
Date of Loss: 15/01/2020	Nature of Claim: TP Claim No: 1090655033SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ8988J		
Make & Model:	KTM 200 DUKE, 200cc	Engine No:	990625732
Reg. Date:	30/12/2019 (Man. Year: 2019)	Chassis No:	VBKJUC404KC053112
Colour:	Orange/Black	Odometer:	153 km
Engine Capacity:	200 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	110/70 R17	Rear Tyre Size:	150/60 R17
Front Left Side:	Metzeler 7 mm	Rear Left Side:	Metzeler 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,196.00	1,841.40	354.60	16.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	320.00	280.00	40.00	12.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	2,516.00	2,121.40	394.60	15.68

INSPECTION

Date of Assignment:	12/02/2020	
Date Inspected:	13/02/2020	Inspected At: Dirt Wheel Motor Trading (HQ) Blk 9004 Tampines Street 93, #01-100 Singapore 528838
Estimated Period of Repair:	2.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Bent	157.00 F	*157.00 FL
2	1		*THROTTLE GRIP	Torn	19.00 F	*19.00 FL
3	1		*THROTTLE TUBE	Cracked	19.00 F	*19.00 FL
4	1		*BRAKE LEVER	Cut	33.00 F	*33.00 FL
5	1		*SIGNAL LIGHT / FRONT / (R)	Cut	62.00 F	*62.00 FL
6	1		*TANK COVER / ORANGE / TOP	Cut	163.00 F	*163.00 FL
7	1		*TANK COVER / (R) / MATT BLACK	Cut	115.00 F	*115.00 FL
8	1		*CRASH BAR	Cut	433.00 F	*433.00 FL
9	1		*BRAKE PEDAL	Cut	73.00 F	*73.00 FL
10	1		*FOOTREST / FRONT / (R)	Cut	34.00 F	*34.00 FL
11	1		*FOOTREST BRACKET / FRONT / (R)	Serviceable	90.00 F	*- FL
12	1		*MIRROR (R)	Broken	39.00 F	*39.00 FL
13	1		*HANDLE BAR TOP CLAMP	Damaged	45.00 F	*45.00 FL
14	1		*HANDLE BAR BOTTOM CLAMP	Damaged	45.00 F	*45.00 FL
15	1		*DECAL KIT	Necessary	189.00 F	*189.00 FL
16	1		*REAR BOX	Cut	680.00 F	*620.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	2,196.00	2,046.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	204.60
Total Parts (\$\$)	2,196.00	1,841.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	2WAY - IDAC - DW	New	70.00	60.00
2	LABOUR	New	250.00	220.00
Gross Labour Cost (\$\$)			320.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >