

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	06 Feb 2020		12 Feb 2020 13:22 Edit Adj Rpt	S\$2,343.72 Edit Estimates	S\$2,343.72 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured: -, Co. Reg. No.: -									
Main Claimant: OFIRA , Co. Reg. No.: 53203627A									
Vehicle Reg. No.: GBF3460E		Date of Loss: 04/02/2020 11:00 - :59 [102 Months and 2 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM20D200658C02		Policy/Cover Note No.: DMCVSN17460119022							
Vehicle Reg. No. (Insured): GBG2598T		Policy No. (Claimant): Z20VC05004448							
		Excess: S\$0.00							
Repairer: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel: 6844 2475									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Adeline Chng Pei Wen]									
Claimant's Insurer: Lonpac Insurance Bhd (HQ) - Tel: +65 62507388									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 21/02/2020]									
Adj Asg. Remarks: survey revert									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBF3460E (SNM20D200658C02)**
[GBG2598T]

TP

OFIRA

Feb 4 2020 11:00AM

[-]

Teamwork Garage Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	05/02/20 17:10	Accident Statement		Load HTM	
Photos/Images				3 per page	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
2	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
3	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
4	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
5	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
6	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
7	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
8	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
9	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
10	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
11	05/02/20 17:09	Accident Photo [Linked Accident Report Documents]		Load JPG	
Documentation				1 per page	
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	12/02/20 13:23	Pre-Repair Survey		Load PDF	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	05/02/20 17:09	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	
2	05/02/20 17:09	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	

Linked Accident Report Documents

Assessment Reports				1 per page	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	05/02/20 17:10	Accident Statement		Load HTM	
Photos/Images				3 per page	
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	05/02/20 17:09	Accident Photo		Load JPG	
2	05/02/20 17:09	Accident Photo		Load JPG	
3	05/02/20 17:09	Accident Photo		Load JPG	
4	05/02/20 17:09	Accident Photo		Load JPG	
5	05/02/20 17:09	Accident Photo		Load JPG	
6	05/02/20 17:09	Accident Photo		Load JPG	

Assessment Reports					1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print	
7	05/02/20 17:09	Accident Photo		Load JPG	☒	
8	05/02/20 17:09	Accident Photo		Load JPG	☒	
9	05/02/20 17:09	Accident Photo		Load JPG	☒	
10	05/02/20 17:09	Accident Photo		Load JPG	☒	
11	05/02/20 17:09	Accident Photo		Load JPG	☒	
Documentation					1 per page	☒
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print	
1	05/02/20 17:09	Accident Sketch Plan		Load JPG	☒	
2	05/02/20 17:09	Accident Sketch Plan		Load JPG	☒	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI20002448/ETF3S2**Date:** 04/06/2020**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN17460119022
Claimant Vehicle No :	GBF3460E	Insured Vehicle No :	GBG2598T
Date of Loss:	04/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200658C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBF3460E	Engine No:	K9KF276D088886
Make & Model:	NISSAN NV200, 1.5 (A)	Chassis No:	JN1YBAM20U0003111
Reg. Date:	02/08/2011 (Man. Year: 2010)	Odometer:	173996 km
Colour:	Grey		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,844.59	623.72	8,220.87	92.95
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,360.00	1,720.00	1,640.00	48.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	12,204.59	2,343.72	9,860.87	80.80
+ GST 7.00/7.00% (\$\$)	854.32	164.06	690.26	80.80
Nett Amount (\$\$)	13,058.91	2,507.78	10,551.13	80.80

INSPECTION

Date of Assignment:	12/02/2020	
Date Inspected:	17/02/2020	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	6.0 days	

Adjuster: CHEN TSUE YEE**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

6/4/2020

Adjuster Report

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$812.00 NETT)

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jun 2020)	
Parts:	N/A	NISSAN NV200 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF3460E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	*Check	805.92 FL	*- FL
2	1		*REAR BUMPER RETAINER	*Check	96.30 FL	*- FL
3	1		*REAR RH FENDER	Repair	1,979.67 FL	*- FL
4	1		*REAR RH FENDER MOULDING	Not Necessary	159.30 FL	*- FL
5	1		*REAR RH FENDER INNER SHIELD	Not Necessary	127.40 FL	*- FL
6	1		*TAILLAMP RH	Cut	659.69 FL	*659.69 FL
7	1		*RH SLIDING DOOR	Repair	1,711.43 FL	*- FL
8	1		*RH SLIDING DOOR HINGE	Not Necessary	86.00 FL	*- FL
9	1		*RH SLIDING DOOR CHECKER	Not Necessary	121.10 FL	*- FL
10	1		*REAR AXLE BEAM	Not Necessary	2,417.03 FL	*- FL
11	1		*REAR RH WHEEL HUB WITH BEARING	Not Necessary	293.50 FL	*- FL
12	1		*REAR RH SHOCK ABSORBER	Not Necessary	592.20 FL	*- FL
13	1		*RIM	Not Necessary	600.00 FS	*- FS
14	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
15	1		*SET REAR FENDER INNER SHIELD CLIP	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,749.54	689.69
- List Item Discount on L Items 10.00/10.00% (\$\$)	904.95	65.97
Total Parts (\$\$)	8,844.59	623.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING AND LIGHTING SYSTEM.	New	60.00	30.00
2	COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT.	New	200.00	60.00
3	REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS.	New	150.00	0.00
4	TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW.	New	200.00	0.00
5	REMOVE AND REFIT REAR QUARTER GLASS.	New	200.00	100.00
6	PANEL BEATING ON AFFECTED AREAS.	New	1,200.00	800.00
7	SPRAY PAINTING ON AFFECTED AREAS.	New	1,200.00	700.00
8	APPLY ANTI RUST ON AFFECTED AREAS.	New	150.00	30.00
Gross Labour Cost (\$\$)			3,360.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >