

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWER

SINGAPORE 048623

INV No. AC2003803

INV Date 12/05/2020

Reference CS/SMO20002449/Fyf3n2

Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. GBH 767E

Insured Veh. SKP 2872Y

Claim No. CMTD2000374/THE

Policy No.

Accident Date 21/01/2020

Inspection Date 23/04/2020

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	250.00
GST (7%)	17.50
Grand Total	267.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Affiliated to Federation Internationale Des Experts En Automobile							
SOMPO INSURANCE SINGAPORE PL Ref :				CS/SMO20002449/Fyf3n2			
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date :	12-05-2020				
			Code :	SMO			
1.		Policy Particulars	:- THIRE	PARTY CLAIM			
	Insured Veh.	SKP 2872Y	Veh. In	nspected	GBH 767E		
	Policy No.		Covera	age (\$)	0.00		
	Claim No.	CMTD2000374/THE	Excess	s (\$)	0.00		
	Assign From	GRACE TEO	Assigr	n Date	12/02/2020		
2.		Vehicle Partic	culars &	Condition			
	Make & Model	NISSAN NV200	c.c		1461		
	Engine No.	HIDDEN	Year of Reg.		2017		
Chassis No.		VSKYBAM20Z0150268	Colour		WHITE		
	Odometer	73514	Steerir	ng	IN ORDER		
	Brakes	IN ORDER	Modifie	cation	STANDARD ALLOY RIM		
	General	FAIR					
3.		Conditie	ons of 1	Tyres			
		Size	Make		Balance		
	R/H Front Tyre	175/70 R14	DURAT	URN	6 mm		
	L/H Front Tyre	175/70 R14	DURAT		6 mm		
	R/H Rear Tyre	175/70 R14	DURAT	URN	6 mm		
	L/H Rear Tyre	175/70 R14	DURAT	URN	6 mm		
4.		Description					
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	FRONT	AND FRONT PORT	TION.		
	DAMAGES SEE D	ETAILS.					
5.		General	Inform	ation			
	Accident Date	21/01/2020	Inspec	tion Date	23/04/2020		
	Survey held at	EFFICIENT MOTOR & ENGINEE	ERING W	ORKS PTE LTD			
	56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775						
5a.		Re	emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				REPAIRS.		
5b.	b. Estimate Days of Repair						
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:		3 Working Days			



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBH 767E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	SCRATCHED / BROKEN	655.20	655.20
1	FRONT BUMPER RETAINER L/H	NOT NECESSARY	26.00	-
1	HEADLAMP L/H	SCRATCHED	615.90	615.90
1	HEADLAMP LOWER GARNISH L/H	TO REPAIR SEE LABOUR	368.50	-
1	FRONT FENDER L/H	BUCKLED	555.20	555.20
1	FRONT FENDER INNER SEAL L/H	NOT NECESSARY	188.40	-
	LESS 10% DISCOUNT		-240.92	-182.63
			2,168.28	1,643.67
	SPECIAL NETT ITEMS			
5	BUMPER CLIPS @\$8.00 (SN)	NECESSARY	40.00	35.00
4	FRONT FENDER INNER SEAL CLIPS @\$5.00 (SN)	NECESSARY	20.00	20.00
			60.00	55.00
	<u>LABOUR</u>			
	TO DISMANTLE AND RE-FIX DAMAGED FRONT PORTIONS;AFFECTED DAMAGED PORTION.	NOT NECESSARY	1,000.00	-
	TO APPLY ANTI RUST COAT AND TUFF KOTE AFFECTED AREAS.		70.00	30.00
	TO PANEL BEAT AFFECTED AREA.INCLUSIVE OF THE REPAIR OF HEADLAMP LOWER GARNISH L/H.		800.00	550.00
	TO SPRAY PAINTING FOR FRONT AND SIDE PORTIONS AFFECTED PARTS.		1,000.00	500.00
	TO DO FRONT WHEEL ALIGNMENT.		150.00	80.00
	TO APPLY WATERPROOFING SEALER ON END PANELS.		80.00	50.00
	-		-	-
	-		-	-
	-		-	-
			3,100.00	1,210.00
	GRAND TOTAL		5,328.28	2,908.67

RECOMMENDED COST OF REPAIRS		2,908,67
REGOINMENDED GOOT OF RELATING		2,000.07

Report Ref No. CS/SMO20002449/Fyf3n2





Report Ref No. CS/SMO20002449/Fyf3n2

PARASURAM S/O SHANMUGAM

Asst. Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 767E

INSPECTION
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBH 767E

RE-INSPECTION





