Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20002456/ABA3Q2

**Date:** 11/12/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800123302

Claimant
Vehicle No: SLL4382R

Insured Vehicle No: SMF4315E

Date of Loss: 08/02/2020 Nature of Claim: TP Claim No: 2264676077SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLL4382R

Make & Model: MITSUBISHI LANCER, 1.6 EX AT LED TAIL Engine No: 4A92CL8861

LAMP (A)

Reg. Date: 27/02/2017 (Man. Year: 2016) Chassis No: JMYSRCY1AGU006185

 Reg. Date:
 27/02/2017 (Man. Year: 2016)
 Chassis No:
 JMYSRCY1.

 Colour:
 Blue
 Odometer:
 103681 km

Engine Capacity: 1590 cc
Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
Front Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,861.56	1,797.32	1,064.24	37.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,290.00	1,030.00	260.00	20.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,151.56	2,827.32	1,324.24	31.90
Approved Total (Overridden) (S\$)		2,250.00		
Nett Amount (S\$)	4,151.56	2,250.00	1,901.56	45.80
+ Car Rental (4.0 x S\$10	00.00/day) (S\$)	400.00		
+ Doc/S	earch Fee (S\$)	7.45		
Ne	tt Liability (S\$)	2,657.45		
Global Sum S	Settlement (S\$)	2,600.00		

**INSPECTION** 

Date of Assignment: 11/02/2020

Date Inspected: 11/02/2020 Inspected At: Chin Meng Motors (HQ)

1 Kaki Bukit Ave 6 #01-40/63, Autobay

@ Kaki Bukit Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount			
1	1		*REAR BOOT EMBLEM -LOGO	Necessary	55.60 FN	*55.60 FN			
2	1		*REAR BOOT EMBLEM -LANCER	Necessary	65.80 FN	*65.80 FN			
3	1		*REAR BOOT EMBLEM -SPORT	Necessary	55.20 FN	*55.20 FN			
4	1		*REAR BOOT EMBLEM -C&C	Necessary	62.50 FN	*62.50 FN			
5	1		*REAR BOOT EMBLEM -MIVEC	Necessary	54.50 FN	*54.50 FN			
6	1		*REAR BOOT INNER LOCK	Not Necessary	233.50 FN	*- FN			
7	1		*REAR BUMPER	Deformed	815.50 FN	*815.50 FN			
8	1		*REAR BUMPER REINFORCEMENT	Bent	266.30 FN	*266.30 FN			
9	2		*REAR BUMPER RETAINER	Necessary	91.60 FN	*91.60 FN			
10	2		*REAR BUMPER BRACKETS	Not Necessary	179.00 FN	*- FN			
11	1		*REAR BUMPER TOW COVER	Deformed	28.50 FN	*28.50 FN			
12	2		*REAR BUMPER REFLECTORS	Not Necessary	91.60 FN	*- FN			
13	1		*REAR BUMPER PAD (TOP)	Cut	113.50 FN	*113.50 FN			
14	1		*REAR END PANEL	Repair	489.50 FN	*- FN			
15	1		*REAR END PANEL GARNISH	Deformed	115.80 FN	*115.80 FN			
16	1		*REAR NO PLATE WITH COVER	Bent	45.00 FS	*45.00 FS			
17	1		*SET REAR REVERSE SENSOR	Damaged	250.00 FS	*200.00 FS			
18	1		*REAR EXHAUST PIPE COVER	Not Necessary	120.00 FS	*-FS			
F=Fra	F=Franchise part. S=SpcNett. N=NettItemDisc.								
				Sub Total (S\$)	3,133.40	1,969.80			
- Nett Item Discount on N Items 10.00/10.00% (S\$) 271.8				271.84	172.48				
				Total Parts (S\$)_	2,861.56	1,797.32			
	Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO PANEL BEATING ,WELDING ,REMOVING DAMAGED PARTS AND REPLACEMENT OF THE NEW PARTS AS MENTIONED ABOVE ETC	New	400.00	300.00					
2	TO APPLY UNDERSEAL	New	50.00	50.00					
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	60.00	50.00					
4	TO RESPRAY AFFECTED PART	New	750.00	600.00					
5	TO CHECK WIRINGS	New	30.00	30.00					
	Gross Labour Cost (S\$)		1,290.00	1,030.00					
		,							

< END OF ESTIMATES >

Report was unsubmitted during this print-out.