

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20002461/UGS3Q2
Date: 25/05/2021REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994303
Claimant Vehicle No :	SMK7021G	Insured Vehicle No :	GBH3119G
Date of Loss:	11/02/2020	Nature of Claim:	TP
		Claim No:	5893600150SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMK7021G	Engine No:	K9KF649D059563
Make & Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Chassis No:	VF1RFA00662476759
Reg. Date:	22/04/2019 (Man. Year: 2019)	Odometer:	65061 km
Colour:	Blue		
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Goodyear 7 mm	Rear Left Side:	Goodyear 7 mm
Front Right Side:	Goodyear 7 mm	Rear Right Side:	Goodyear 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,750.22	7,691.81	6,058.41	44.06
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,520.00	1,880.00	1,640.00	46.59
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,270.22	9,571.81	7,698.41	44.58
Approved Total (Overridden) (S\$)		7,650.00		

Adjuster Report

	(S\$)	17,270.22	7,650.00	9,620.22	55.70
Nett Amount (S\$)		18,479.14	8,185.50	10,293.64	55.70
	+ Car Rental (7.0 x S\$92.00/day) (S\$)		644.00		
	+ Doc/Search Fee (S\$)		7.45		
	Nett Liability (S\$)		8,836.95		

INSPECTION

Date of Assignment: 12/02/2020

Date Inspected: 12/02/2020

Estimated Period of Repair: 5.0 days

Inspected At:

Tan Lim Motor Pte Ltd (Defu)
1 Defu Lane 6
Singapore 539365**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,081.32 FL	*1,081.32 FL
2	1		*REAR BUMPER CENTRE PAD	Cracked	480.00 FL	*480.00 FL
3	1		*REAR BUMPER LOWER	Distorted	684.50 FL	*684.50 FL
4	1		*REAR BUMPER REFLECTOR	O/S Cracked	868.40 FL	*205.00 FL
5	2		*REAR BUMPER SIDE RETAINER	Not Necessary	674.60 FL	*- FL
6	1		*REAR BUMPER LOWER BRACKET	O/S Cracked	207.20 FL	*103.60 FL
7	2		*REAR BUMPER CENTRE PAD LOWER BRACKET	Not Necessary	650.20 FL	*- FL
8	2		*REAR BUMPER CENTRE PAD SPLASH GUIDE	Not Necessary	745.40 FL	*- FL
9	4		*REAR BUMPER PARKING SENSOR	Shorted (2 PCS ONLY)	978.40 FL	*489.20 FL
10	1		*REAR BUMPER PARKING SENSOR WIRE HARNESS	Not Necessary	446.50 FL	*- FL
11	1		*REAR BUMPER BEAM	Bent	625.60 FL	*625.60 FL
12	1		*REAR END PANEL	Dented	797.60 FL	*797.60 FL
13	1		*REAR END PANEL INNER TRIM	Not Necessary	595.00 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Not Necessary	245.60 FL	*- FL
15	1		*REAR END PANEL UNDER PLASTIC	Cracked	1,169.90 FL	*525.00 FL
16	1		*TAILGATE LID	Dented / Cracked	2,292.70 FL	*2,292.70 FL
17	1		*TAILGATE LID CENTRE EMBLEM	Necessary	151.20 FL	*151.20 FL
18	1		*TAILGATE LID SCENIC EMBLEM	Necessary	119.60 FL	*119.60 FL
19	1		*TAILGATE LID RENAULT EMBLEM	Necessary	138.10 FL	*138.10 FL
20	1		*TAILGATE LID LAMP	Not Necessary	516.50 FL	*- FL
21	2		*REAR NUMBER PLATE LAMP	Not Necessary	71.60 FL	*- FL
22	1		*REAR KEYLESS SWITCH	Not Necessary	124.80 FL	*- FL
23	1		*REAR KEYLESS SWITCH ANTENA (NPA)	Not Necessary	0.00 FL	*- FL
24	1		*REAR REVERSE CAMERA	Not Necessary	458.50 FL	*- FL
25	1		*REAR EXHAUST HEAT SHIELD -OUTER	Bent	160.30 FL	*160.30 FL
26	1		*REAR EXHAUST HEAT SHIELD -END	Not Necessary	235.10 FL	*- FL
27	1		*REAR NUMBER PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
28	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
29	1		*REAR WINDSCREEN INNER SEAL	Necessary	50.00 FS	*40.00 FS
30	1		*O/S TAILLAMP	Cracked	443.40 FL	*443.40 FL
31	1		*O/S REAR BUMPER BEAM TOP BRACKET	Cracked	116.00 FL	*116.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	15,258.02	8,533.12
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,507.80	841.31

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
					Total Parts (\$)	13,750.22	7,691.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RUST-PROOFING OF THE AFFECTED AREAS	New	300.00	30.00
2	TO REINSTALL OF REAR BUMPER PARKING SENSOR	New	80.00	50.00
3	TO REINSTALL OF REAR REVERSE CAMERA	New	80.00	0.00
4	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	60.00	20.00
5	TO REPAIR AND REALIGN REAR EXHAUST BOX	New	100.00	0.00
6	TO PERFORM WATER SEEPAGE TEST ,WINDNOLSE AND TEST-DRIVE	New	80.00	0.00
7	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	200.00	100.00
8	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
9	TO REMOVE AND REFIT INTERIOR FITTINGS TRIMMINGS,GARNISH AND OTHER ,TO ENABLE REPAIR	New	100.00	80.00
10	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	1,200.00	680.00
11	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,200.00	800.00
			Gross Labour Cost (S\$)	3,520.00
				1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >