

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20002467/ABA3Q2

**Date:** 28/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100503443

**Claimant**  
**Vehicle No :** SGV8422P **Insured Vehicle No :** SKK7667S

Date of Loss: 10/02/2020 Nature of Claim: TP Claim No: 3260703525SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | <b>SGV8422P</b>                   |             |                   |
| Make & Model:               | TOYOTA COROLLA ALTIS, 1.6 (A)     | Engine No:  | 3ZZ4671716        |
| Reg. Date:                  | 27/06/2007 (Man. Year: 2007)      | Chassis No: | MR053ZEC107150343 |
| Colour:                     | Silver                            | Odometer:   | 141874 km         |
| Engine Capacity:            | 1598 cc                           |             |                   |
| Market Value/New Car Price: | N/A                               |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b> |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 185/70 R14    | Rear Tyre Size:  | 185/70 R14    |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                            | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                            | 7,624.05          | 3,158.95          | 4,465.10          | 58.57         |
| Miscellaneous Items                              | 0.00              | 0.00              | 0.00              |               |
| Labour                                           | 6,310.00          | 2,100.00          | 4,210.00          | 66.72         |
| Paintwork Labour                                 | 0.00              | 0.00              | 0.00              |               |
| Towing                                           | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>             | <b>13,934.05</b>  | <b>5,258.95</b>   | <b>8,675.10</b>   | <b>62.26</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>        |                   | <b>4,200.00</b>   |                   |               |
| <b>(\$\$)</b>                                    | 13,934.05         | 4,200.00          | 9,734.05          | 69.86         |
| <b>+ GST 7.00/7.00% (\$\$)</b>                   | 975.38            | 294.00            | 681.38            | 69.86         |
| <b>Nett Amount (\$\$)</b>                        | <b>14,909.43</b>  | <b>4,494.00</b>   | <b>10,415.43</b>  | <b>69.86</b>  |
| <b>+ Loss of Use (8.0 x S\$60.00/day) (\$\$)</b> |                   | 480.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                   |                   | 7.45              |                   |               |
| <b>Nett Liability (\$\$)</b>                     |                   | <b>4,981.45</b>   |                   |               |

### INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 11/02/2020 Inspected At:

MG Solution Pte Ltd (HQ)  
23 Kaki Bukit Avenue 4 #02-03B,  
VICOM Inspection Centre  
Singapore 415933

Estimated Period of Repair: 7.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                           | Condition     | Repairer's | Amount     |
|-----|-----|----------|---------------------------------------|---------------|------------|------------|
| 1   | 1   |          | *BOOTLID                              | Buckled       | 668.90 FL  | *668.90 FL |
| 2   | 1   |          | *BOOTLID LOGO                         | Necessary     | 68.60 FL   | *68.60 FL  |
| 3   | 1   |          | *BOOTLID EMBLEM COROLLA               | Necessary     | 55.10 FL   | *55.10 FL  |
| 4   | 1   |          | *BOOTLID EMBLEM ALTIS                 | Necessary     | 55.40 FL   | *55.40 FL  |
| 5   | 1   |          | *BOOTLID E EMBLEM                     | Necessary     | 45.50 FL   | *45.50 FL  |
| 6   | 1   |          | *BOOTLID VVT-I EMBLEM                 | Necessary     | 65.40 FL   | *65.40 FL  |
| 7   | 1   |          | *BOOTLID TOP LOCK                     | Damaged       | 184.00 FL  | *184.00 FL |
| 8   | 1   |          | *BOOTLID LOWER CATCH                  | Not Necessary | 87.00 FL   | *- FL      |
| 9   | 2   |          | *BOOTLID HINGE                        | Not Necessary | 202.00 FL  | *- FL      |
| 10  | 1   |          | *BOOTLID NUMBER PLATE GARNISH         | Not Necessary | 114.00 FL  | *- FL      |
| 11  | 1   |          | *BOOTLID NUMBER PLATE GARNISH CHROME  | Not Necessary | 89.50 FL   | *- FL      |
| 12  | 2   |          | *BOOTLID REFLECTOR                    | Not Necessary | 690.00 FL  | *- FL      |
| 13  | 1   |          | *BOOTLID WEATHERSTRIP                 | Cut           | 175.10 FL  | *175.10 FL |
| 14  | 1   |          | *REAR BUMPER                          | Distorted     | 398.20 FL  | *398.20 FL |
| 15  | 2   |          | *REAR BUMPER SIDE RETAINER            | Necessary     | 202.00 FL  | *70.00 FL  |
| 16  | 2   |          | *REAR BUMPER BRACKET                  | Dented        | 202.00 FL  | *86.40 FL  |
| 17  | 1   |          | *REAR BUMPER REINFORCEMENT            | Not Necessary | 460.00 FL  | *- FL      |
| 18  | 2   |          | *TAILLAMP                             | Cut           | 670.00 FL  | *670.00 FL |
| 19  | 2   |          | *TAILLAMP PANEL                       | Buckled       | 380.00 FL  | *380.00 FL |
| 20  | 2   |          | *TAILLAMP LOWER BRACKET               | Not Necessary | 116.00 FL  | *- FL      |
| 21  | 1   |          | *SET REAR NUMBER PLATE LAMP           | Not Necessary | 98.60 FL   | *- FL      |
| 22  | 1   |          | *REAR END PANEL                       | Dented        | 790.00 FL  | *790.00 FL |
| 23  | 1   |          | *REAR END PANEL TOP GARNISH           | Deformed      | 350.00 FL  | *86.00 FL  |
| 24  | 1   |          | *SPARE TYRE BOLT                      | Not Necessary | 980.00 FL  | *- FL      |
| 25  | 1   |          | *SPARE FLOOR PANEL                    | Repair        | 980.00 FL  | *- FL      |
| 26  | 1   |          | *SPARE FLOOR PANEL TOP COVER          | Not Necessary | 298.10 FL  | *- FL      |
| 27  | 1   |          | *REAR EXHAUST PIPE                    | Not Necessary | 980.00 FL  | *- FL      |
| 28  | 1   |          | *REAR NUMBER PLATE                    | Not Necessary | 50.00 FS   | *- FS      |
| 29  | 1   |          | *SET REAR BUMPER CLIPS                | Necessary     | 20.00 FS   | *20.00 FS  |
| 30  | 1   |          | *SET REAR TAILLAMP CLIPS              | Necessary     | 20.00 FS   | *20.00 FS  |
| 31  | 1   |          | *BOOTLID SEALANT                      | Not Necessary | 80.00 FS   | *- FS      |
| 32  | 1   |          | *REAR END PANEL SEALANT               | Necessary     | 80.00 FS   | *60.00 FS  |
| 33  | 1   |          | *SET REAR END PANEL TOP GARNISH CLIPS | Necessary     | 20.00 FS   | *10.00 FS  |
| 34  | 1   |          | *REAR FLOOR PANEL SEALANT             | Not Necessary | 80.00 FS   | *- FS      |
| 35  | 1   |          | *REVERSE SENSOR                       | Damaged       | 220.00 FS  | *200.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                           |                 |                 |
|-----------------------------------------------------------|-----------------|-----------------|
| <b>Sub Total (S\$)</b>                                    | <b>9,975.40</b> | <b>4,108.60</b> |
| <b>- List Item Discount on L Items 25.00/25.00% (S\$)</b> | <b>2,351.35</b> | <b>949.65</b>   |
| <b>Total Parts (S\$)</b>                                  | <b>7,624.05</b> | <b>3,158.95</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                      | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                  |          |                 |                 |
| 1                               | PANEL BEATING ,INCLUDING OF THE REPAIR OF<br>TAILLAMP PANEL AND SPARE TYRE PANEL | New      | 2,500.00        | 900.00          |
| 2                               | SPRAY PAINTING TO AFFECTED AREA                                                  | New      | 2,500.00        | 1,000.00        |
| 3                               | WIRING                                                                           | New      | 150.00          | 30.00           |
| 4                               | TUFF COAT                                                                        | New      | 180.00          | 60.00           |
| 5                               | TO CONDUCT WATER LEAKAGE TEST                                                    | New      | 250.00          | 0.00            |
| 6                               | TO REMOVE AND REFIX REAR EXHAUST PIPE                                            | New      | 250.00          | 0.00            |
| 7                               | TO REMOVE AND REFIX REAR WINDSCREEN                                              | New      | 150.00          | 0.00            |
| 8                               | TO TRANSFER BOOTLID MECHANISM                                                    | New      | 180.00          | 60.00           |
| 9                               | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE<br>SETTING                          | New      | 150.00          | 50.00           |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                  |          | <b>6,310.00</b> | <b>2,100.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >