

TP QBE
Khanhna

SMG 7575X

Mazda 3

JMGBN22A8K0250960.

Rees Bumper Deformed 1074.80 ✓

Rees Bumper Clips. ^{new} 30 ✓

Rees Bumper Side Holder x 02 ^{HP} ^{new} 55 x 2 = 110. x

Rees Bumper Reinforcement. Dated 538 ✓

Rees Bumper Tow Cover. Missing 18.50 ✓

Reverse Sensor ^{Damaged} 280. 200(SN)
1661.30 S.N: 200.
1329.04

Panel Beating. 400 ~~200~~

Spray Painting 400 ~~200~~

Wiring 50 ~~30~~

To remove reverse sensor. 100 ~~50~~.

480.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 2009.04

L/s: 1.6K.

03 Pays.