



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKX 7318G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	DUCT ,RR VENTILATOR (SN)	NOT NECESSARY	30.00	-
1	COVER ,RR VENTILATOR (SN)	NOT NECESSARY	40.00	-
4	CLIP,GEARSHIFT CONTROL LIN(SN)	NOT NECESSARY	12.00	-
1	BRACKET ,RR BUMPER ,LH (SN)	BROKEN	28.00	28.00
1	BRACKET ,RR BUMPER ,RH (SN)	BROKEN	28.00	28.00
6	CLIP,RR BUMPER (SN)	NECESSARY	24.00	24.00
1	FACE ,RR BUMPER (SN)	DENTED	748.00	748.00
			960.00	848.00
<u>LABOUR</u>				
	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE ,REPAIR REAR END PANEL,REPAIR LH REAR FENDER.		2,200.00	825.00
	REMOVE AND INSTALL PARKING ASSIST.		100.00	100.00
	REMOVE AND INSTALL REAR BOOT CABIN ,SIDE TRIM TO FACILITATE REPAIR WORK.		250.00	180.00
	PAINT WORK SPRAY REAR END PANEL,REAR BUMPER,LH REAR FENDER AND AFFECTED PORTION.		1,680.00	840.00
	PERFORM RUST PREVENTION.	NOT NECESSARY	80.00	-
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	30.00
	SUPPLY PARKING SENSOR .	NOT NECESSARY	220.00	-
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		200.00	200.00
			4,780.00	2,175.00
GRAND TOTAL			5,740.00	3,023.00
RECOMMENDED COST OF REPAIRS				3,023.00

Report Ref No. CC4/FCI20002474/Eda3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.